Downriver Community Conference Brownfield Consortium Southgate, Michigan

Phase I Environmental Site Assessment Washtenaw County Juvenile Center 2260 and 2270 Platt Road Ann Arbor, Michigan

May 2010







May 20, 2010

TTL Project No. 6358.01

Ms. Paula Boase Downriver Community Conference Brownfield Consortium 15100 Northline Road Southgate, Michigan 48195

> Phase I Environmental Site Assessment Washtenaw County Juvenile Center 2260 and 2270 Platt Road Ann Arbor, Michigan

Dear Ms. Boase:

The final report for the Phase I Environmental Site Assessment (ESA) conducted for the Downriver Community Conference Brownfield Consortium (DCCBC) and Washtenaw County by TTL Associates, Inc. (TTL) for the above-referenced site is enclosed.

This project was performed in conformance with the requirements specified in the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," E 1527-05. The purpose of this Phase I ESA was to identify, to the extent feasible pursuant to the processes described in ASTM E 1527-05, Recognized Environmental Conditions in connection with the site.

TTL appreciates the opportunity to provide the DCCBC with our engineering, consulting, and testing services. Should you have any questions or require additional information, please contact Rob Clark at (734) 455-8600 ext. 1235.

Sincerely,

TTL Associates, Inc.

Steven J. Gach, P.E. Senior Engineer

CC: Mr. Brett Lenart, Washtenaw County

Robin J. Clark Senior Scientist

V:\Plymouth\DCC Brownfield Consortium\2270 Platt Ann Arbor\report\6358.01 Phase I ESA Report.doc

PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUNVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

FOR

DOWNRIVER COMMUNITY CONFERENCE BROWNFIELD CONSORTIUM 15100 NORTHLINE ROAD SOUTHGATE, MICHIGAN 48195

MAY 11, 2010 TTL PROJECT NO. 6358.01

TTL ASSOCIATES, INC.
44265 PLYMOUTH OAKS BOULEVARD
PLYMOUTH, MICHIGAN 48170
(734) 455-8600
FAX: (734) 455-8608



TABLE OF CONTENTS

		Page No.
EX	ECUTIVE SUMMARY	E-1
1.0	INTRODUCTION	1
1.0	1.1 Purpose and Scope of Work	
	1.2 Limitations and Exceptions of Assessment	
	1.3 User Provided Information	
	1.3.1 Reason for Performing the Phase I ESA	
	1.3.2 Environmental Liens and Activity and Use Limitations	
	1.3.3 Specialized Knowledge	
	1.3.4 Commonly Known or Reasonably Ascertainable Information	
	1.3.5 Valuation Reduction for Environmental Issues	
	1.4 Additional Services	
2.0	SITE DESCRIPTION	5
	2.1 Site Location and Legal Description	
	2.2 Site Utilities	
	2.3 Physical Setting	
	2.3.1 Topography	
	2.3.2 Soils/Geology	6
	2.3.3 Hydrology	6
3.0	SITE HISTORICAL/RECORDS REVIEW	8
	3.1 Summary of Historical/Records Review	8
	3.2 Ownership Information	
	3.3 Prior Use Interviews with Owner(s) and Occupant(s)	8
	3.4 Local Government Agency Record Review	
	3.5 Historical Maps and Other Information	
	3.6 Historical City Directories	
	3.7 Aerial Photographs	
	3.8 Previous Environmental Reports	11
4.0	SITE RECONNAISSANCE	
	4.1 Methodology and Limiting Conditions	
	4.2 Site Description and Current Uses	
	4.3 Site Observations	12
5.0	REGULATORY FILE SEARCH	14
6.0	CURRENT AND HISTORICAL USES OF ADJOINING PROPERTIES	17



TABLE OF CONTENTS (CONTINUED)

		Page No.
7.0	DATA GAPS	18
8.0	OPINION	19
9.0	DECLARATIO	N20
10.0	REFERENCES	AND RECORDS OF COMMUNICATION21
TA.	BLES	
	Table 1.0	Summary of Historical Site Use8
	Table 2.0	Summary of Site Observations
	Table 3.0	Facilities Identified on the ASTM-Specified Databases15
FIG	URES	
	Figure 1.0	Site Location Map (USGS Topographic Map)
	Figure 2.0	Site Sketch
API	PENDICES	
	Appendix A:	Phase I ESA Questionnaires
	Appendix B:	Local Government Agency Records
	Appendix C:	City Directories
	Appendix D:	Aerial Photographs
	Appendix E:	Site Photographs
	Appendix F:	Environmental Database Report
	Appendix G:	TTL Team Resumes



EXECUTIVE SUMMARY

This report presents the methodology and findings of a Phase I Environmental Site Assessment (ESA) conducted for the Downriver Community Conference Brownfield Consortium (DCCBC) and Washtenaw County by TTL Associates, Inc. (TTL) in April and May 2010 for the property located at 2260 and 2270 Platt Road in Ann Arbor, Washtenaw County, Michigan (site). This Phase I ESA was performed in conformance with the scope and limitations of the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," E 1527-05. The purpose of this Phase I ESA was to identify, to the extent feasible pursuant to the processes prescribed in ASTM E 1527-05, Recognized Environmental Conditions (RECs) in connection with the site.

Findings and Opinions

The site is approximately 10 acres in area and consists of a portion of one approximately 140-acre parcel. The site was undeveloped and/or agricultural land from at least 1937 to 1954. The site is occupied with one juvenile court and detention building, one office building, and asphalt and concrete paved and landscaped areas on the northern portion of the site. The remaining areas of the site are occupied by unimproved land. The northeastern building (the O'Brien Center, 2260 Platt Road) was constructed in approximately 1954. The current juvenile court and detention building (Washtenaw County Juvenile Center, 2270 Platt Road) was constructed in approximately 1969. The 2260 Platt Road building was operated as the juvenile detention center until the newer building was constructed.

Based on the information obtained and evaluated as part of this Phase I ESA, the following suspect environmental conditions were identified in association with the site:

- Ann Arbor Fire Department records indicate that the 2260 Platt Road building was heated via heating oil in 1956 through at least the early 1970s, before natural gas was used. No documentation was identified whether the heating oil was stored in an aboveground storage tank (AST) or underground storage tank (UST). The possible former use of a heating oil UST at the site is considered to be a REC.
- Environmental Database Resources (EDR) identified the site on the Facility Index System (FINDS) database under the name "Washtenaw County Juvenile Detention". The FINDS database lists the site as identified on the National Compliance Database (NCDB), which supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act Tracking System (TSCA) databases. No additional information regarding the site's NCDB listing was provided by EDR or identified through a search of U.S. EPA's on-line databases. Based on the lack of other database listings for the site and the nature of the NCDB listing (not indicative of a release or spill of hazardous substances or petroleum), the NCDB listing is not considered to be a REC in connection with the site.



• EDR identified the easterly adjoining former Ann Arbor Civic Theater property at 2275 Platt Road (across Platt Road from the site) on the Baseline Environmental Assessment (BEA) and State Hazardous Waste Site (SHWS) databases. This property is currently occupied by a church. Inclusion in the BEA database indicates that hazardous substances were detected at the property in excess of the Michigan residential cleanup criteria. Information in the SHWS database indicates that evaluation has been conducted. Based on its inferred downgradient location and current use as a church, the former Ann Arbor Civic Theater is not considered to be a REC in connection with the site.

Conclusions

TTL has performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM E 1527-05. Any exceptions to, or deletions from, this practice are described in Sections 1.2 and 7.0 of this report. This Phase I ESA has revealed no evidence of RECs in connection with the site, except for the following:

• The possible former use of a heating oil UST at the site associated with the 2260 Platt Road building from the 1950s until at least the early 1970s.

Recommendations

TTL recommends completing a Phase II ESA to assess the site for impacts from the possible historic heating oil UST.



1.0 INTRODUCTION

This report presents the methodology and findings of a Phase I Environmental Site Assessment (ESA) conducted for the Downriver Community Conference Brownfield Consortium (DCCBC) and the Washtenaw County by TTL Associates, Inc. (TTL) in April and May 2010 for the property located at 2260 and 2270 Platt Road in Ann Arbor, Washtenaw County, Michigan (site). This project was conducted under TTL's contract with the DCCBC and was funded by the DCCBC's 2009 U.S. EPA Brownfield Assessment Grant.

The Phase I ESA has been performed in conformance with the scope and limitations of the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," E 1527-05.

1.1 Purpose and Scope of Work

The purpose of this Phase I ESA was to identify, to the extent feasible pursuant to ASTM E 1527-05, Recognized Environmental Conditions (RECs) in connection with the site. RECs are defined as:

"The presence or likely presence of any hazardous substances or petroleum products on the property (site) under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on property (site) or into the ground, groundwater, or surface water of the property (site). The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include *de minimis* conditions that generally do not present a material risk of harm to public health or the environment and that would generally not be the subject of an enforcement action if brought to the attention of the appropriate governmental agencies."

The ASTM E 1527-05 Phase I ESA scope of work consists of four components: records review, site reconnaissance, interviews, and a report. All conclusions made in this report are based upon the assessment performed and are subject to the Limitations and Exceptions presented in Section 1.2 and the Data Gaps as presented in Section 7.0 of this report.

1.2 Limitations and Exceptions of Assessment

The information contained in this report was prepared for the DCCBC and Washtenaw County, and is intended for their sole use. Only the parties noted above may rely on the information contained within this Phase I ESA report unless otherwise authorized by TTL in writing. Written consent from the DCCBC is required to release any or all information contained in this report to other users. The scope of the services performed in this Phase I ESA might not be appropriate to satisfy the needs of other users; any use or reuse of this document without prior written consent is at the sole risk of said user.



The conclusions and recommendations presented in this report are professional opinions based solely upon the information described in this report and TTL's interpretation of this information. The information presented in this report was compiled and evaluated using generally accepted environmental assessment practices. The information, conclusions, and recommendations are intended exclusively for the purpose outlined herein.

TTL has reviewed the available information for this site and will not be responsible for conditions arising from concealed, withheld, or incorrect information. In addition, areas that were not accessible or that would have required demolition in order to investigate, such as pavement, walls, and floors were not inspected. No air quality monitoring or chemical analyses of building materials, soil, surface water, drinking water, or groundwater were performed as part of this assessment, except as noted within this report. TTL's services were limited to the scope of work as described in the aforementioned proposal.

No Phase I ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with the site. Performance of a Phase I ESA within the scope and limitations of the ASTM E 1527-05 standard is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs in connection with the site, subject to reasonable limits of time and cost.

The limitations of, and exceptions to, this Phase I ESA include:

- Pavement, site buildings, and grassy areas limited TTL's observations of the ground surface
 of the site.
- TTL was prohibited from taking photographs in the court and detention building.
- The information contained in this report is accurate only to the degree implied by the methods used in conducting this Phase I ESA.
- The information obtained from publicly available sources is presumed to be reliable.
- Information revealed by person(s) interviewed is presumed to be accurate and truthful.
- The following considerations, not intended to be an all-inclusive list, are outside the scope of the ASTM E 1527-05 standard and are not included within the performance of this Phase I ESA:
 - Asbestos-containing materials survey.
 - Radon testing.
 - Lead-based paint testing.
 - Lead in drinking water.
 - Wetlands determination or delineation.
 - Regulatory compliance.
 - Cultural and historical resources.
 - Industrial hygiene.



- Health and safety.
- Ecological resources.
- Endangered species.
- Indoor air quality testing.
- Biological agents.
- Mold.
- High voltage power lines.
- Soil and/or groundwater testing.

This report does not represent a legal opinion, a guarantee or warranty. The current conclusions do not result in any warranty that the site does not contain unidentified regulated materials. Should additional surface, subsurface, or chemical data become available, the findings and conclusions contained in this report shall not be considered valid unless these data are reviewed and the conclusions of the report are modified or approved in writing by TTL.

1.3 User Provided Information

The following information was provided by the DCCBC and Washtenaw County representatives, regarding the purpose of performing this Phase I ESA and any existing environmental information that they may have regarding the site.

1.3.1 Reason for Performing the Phase I ESA

Washtenaw County plans to vacate the site buildings in the near future. Washtenaw County plans to demolish the site buildings and market the site for sale/re-use.

1.3.2 Environmental Liens and Activity and Use Limitations

Washtenaw County representatives indicated that they were unaware of environmental cleanup liens or activity and use limitations (AULs), institutional or engineering control restrictions, for the site.

1.3.3 Specialized Knowledge

Washtenaw County representatives indicated that they had no specialized knowledge of environmental concerns at the site.

1.3.4 Commonly Known or Reasonably Ascertainable Information

Washtenaw County representatives indicated that the site is occupied by one court and detention building and one office building, built in 1969 and 1954, respectively.



1.3.5 Valuation Reduction for Environmental Issues

Not applicable. Neither the DCCBC nor Washtenaw County intends to purchase the site; this assessment was conducted in association with plans for marketing and redevelopment of the site.

Information provided by Washtenaw County regarding the site is contained in Appendix A.

1.4 Additional Services

TTL did not perform additional services beyond the ASTM E 1527-05 scope of work for this Phase I ESA.



2.0 SITE DESCRIPTION

This section discusses the site location and legal description, site utilities, and the site's physical setting characteristics.

2.1 Site Location and Legal Description

Site Address(es):

2260 and 2270 Platt Road, Ann Arbor, Washtenaw County,

Michigan.

Side of the Street:

West side of Platt Road.

Nearest Intersection:

The site is located northwest of the intersection of Platt Road

and South Huron Parkway.

Parcel Number(s):

Southeast portion of 09-12-03-100-001.

Zoning:

Public Land (PL).

The site is approximately 10 acres in size and consists of a portion of one approximately 140-acre parcel, as designated above. The site is currently occupied by one court and detention building (Washtenaw County Juvenile Center, 2270 Platt Road), one office building (O'Brien Center, 2260 Platt Road), and associated asphalt and concrete paved parking and landscaped areas. Refer to Figure 1.0, which is a map indicating the approximate location of the site and Figure 2.0, which is a site sketch. A parcel map, which illustrates the approximate boundaries of the site parcel and an abbreviated legal description of the site parcel were obtained from the Ann Arbor Assessor's Office (AAAO), and are included in Appendix B. The parcel description is provided for convenience only and should not be relied upon as a definitive site description.

2.2 Site Utilities

Current/Former Water Supply:

The site is connected to the municipal water system. According to information provided by the Washtenaw County Health Department (WCHD), the site has been connected to the municipal water since the late 1960s.

Current/Former Sewage

Connection:

The site is connected to the municipal sewer system. According to information provided by the WCHD, the site has been connected to the municipal sewer system since the late

1960s.

Current/Former Heating

Supply:

The site is connected to natural gas. According to Mr. Jason Fee, WCJC Facilities Manager, the site has been connected to

natural gas since the late 1960s.



Historical resources indicate that the site was occupied by the current office building (former juvenile detention home) since 1954. Based on its date of construction, it is possible that the office building utilized a private water well and/ or septic system; however, based on the identified use (unlikely to have used significant quantities of petroleum or hazardous substances), the possible former use/presence of a well or septic system is not considered to be a REC in connection with the site.

Ann Arbor Fire Department (AAFD) records indicate that the office building (former juvenile detention home) was heated via a heating oil-fired boiler in 1956 through the early 1970s, before natural gas was used. No documentation was identified during this Phase I ESA whether the heating oil was stored in an aboveground storage tank (AST) or an underground storage tank (UST) at the site. The possible former use of a heating oil UST on the site is considered a REC.

2.3 Physical Setting

This section discusses the topography, geology, and hydrology in the vicinity of the site. An understanding of the site's physical setting is necessary to evaluate the potential for impact to the site from possible RECs at and in the vicinity of the site.

2.3.1 Topography

A review of the Ann Arbor East, Michigan United States Geological Survey (USGS) Topographic Quadrangle (dated 1965; photorevised 1983) indicated that surficial topography in the site vicinity [elevation 815 feet above mean sea level (msl)] is relatively level with a slight downward slope to the southeast. An unnamed creek, located approximately 500 feet southeast of the site, is the closest body of water and drains northeast towards the Huron River.

2.3.2 Soils/Geology

According to the Quarternary Geology of Southern Michigan Map (1982), Ann Arbor, Michigan lies within an area where surficial materials are characterized as hummocky material. This material chiefly underlies extensive, flat, low-lying areas, formerly inundated by glacial Great Lakes. The bedrock, in general, is part of the Coldwater Shale unit.

According to the U.S. Department of Agriculture (USDA) Natural Resources Conservation Service (NRCS) Web Soil Survey, the site soils consist of Boyer loamy sand and Matherton sandy loam. Boyer soils consist of well drained loamy sand, with moderate permeability. Matheron soils consist of somewhat poorly drained sandy loam, with moderately slow permeability.

2.3.3 Hydrology

Stormwater in paved areas of the site would typically be directed from the paved surface to the municipal stormwater system via inlets. In unpaved areas, stormwater would infiltrate the surface soil. Site-specific information pertaining to the depth to groundwater and the



groundwater flow direction was not identified during this assessment. Based on the review of the Ann Arbor East, Michigan USGS Topographic Quadrangle, the ground surface topography in the site vicinity is relatively level with a slight downward slope toward the southeast. The groundwater table often mimics the ground surface topography, suggesting that shallow groundwater may flow to the southeast in the site vicinity.



3.0 SITE HISTORICAL/RECORDS REVIEW

The review of historical sources is utilized to develop a history of the previous uses of the site, in order to help identify the likelihood of past uses having led to RECs in connection with the site.

3.1 **Summary of Historical/Records Review**

A review of historical resources identified during the performance of this Phase I ESA has identified the following current/historical uses of the site:

	Table 1.0 Summary of Historical Site Uses						
Year	Identified Use(s)						
1937 - 1954	Occupied by unimproved agricultural land.						
1954 – 1969	Occupied by the current office building (2260 Platt Road), which was operated as a county juvenile detention home.						
1969 - Present	Occupied by the current court and juvenile detention building (2270 Platt Road) and office building.						

None of the identified current or historical uses of the site are considered to be RECs with respect to the site.

3.2 Ownership Information

According to information provided by the AAAO, the site has been owned by Washtenaw County since at least 1989. No additional ownership information was readily available for the site through the AAAO.

3.3 Prior Use Interviews with Owner(s) and Occupant(s)

TTL interviewed Mr. Jason Fee, Facilities Manager for the site, to obtain information to assist in the identification of RECs in connection with the site. Mr. Fee was unaware of any USTs, ASTs, groundwater wells, and/or septic systems associated with the site. Mr. Fee indicated that no fuel was stored in the portable emergency generator stored west of the court and detention building.

Questionnaires regarding the availability of "helpful documents" (as defined by ASTM E 1527-05) pertaining to liens, recorded activity and use limitations, environmental violations, permits, previous environmental reports, and/or other environmental documents and a Key Site Manager Questionnaire for the site were completed by Mr. Fee. The completed questionnaires are included in Appendix A.



3.4 Local Government Agency Record Review

The following agencies were contacted to obtain information regarding potential environmental concerns associated with the site:

- Ann Arbor Fire Department (AAFD).
- Washtenaw County Health Department (WCHD).
- Ann Arbor Assessor's Office (AAAO).

TTL contacted the AAFD to obtain information regarding any USTs, ASTs, or environmental incidents for the site. As previously noted, AAFD files indicate that the office building was heated via heating oil from at least 1956 until the early 1970s. However, AAFD records do not indicate whether the heating oil was stored in an UST or an AST. The possible former use of a heating oil UST at the site is a REC. The AAFD records did not identify any other significant environmental concerns associated with the site.

TTL contacted the WCHD to obtain information regarding health violations, water wells, sanitary/septic systems, environmental issues, USTs, and/or ASTs at the site. According the information provided by WCHD, the site was connected to the municipal sewer and water systems by the time of a 1977 inspection. No other environmental information was identified from the WCHD.

Information obtained from the AAAO indicated that the site parent parcel has been owned by Washtenaw County since at least 1989.

Copies of records obtained from local governmental agencies are provided in Appendix B.

3.5 Historical Maps and Other Information

Sanborn Fire Insurance (Sanborn) maps were requested from Environmental Data Resources, Inc. (EDR), but were not available for the site. A review of the Ann Arbor, Michigan USGS Topographic Quadrangle (dated 1965; photorevised 1983) indicated that the site is occupied by two buildings, which are approximately the same size and shape as the current site buildings. The larger building (2270 Platt Road) is shaded magenta, indicating that it was constructed after 1965. The smaller building (2260 Platt Road) is shaded black, indicating that it was constructed prior to 1965.

3.6 Historical City Directories

Historical city directories dated 1940, 1945, 1950, 1955, 1960, 1965, 1970, 1975, 1980, 1984, 1989, 1994, 1998, 2003, and 2008 were reviewed at the Ann Arbor Public Library (AAPL). Information obtained from the city directories is summarized below.



Address	Listing	1960, 1965, 1970				
	No listing	1940, 1945, 1950, 1955				
	County Juvenile Detention Home	1960, 1965, 1970				
	Washtenaw County Vocational Residential Center, Center for Occupational & Personalized Education	1975				
2260 Platt Road	Francis L. O'Brien Center for Youth Development-Cope, Center for Occupational & Personalized Education, alternative education, and/or O'Brien Youth Developing Center	1980, 1984, 1989, 1994				
	COPE schools educations services	1998				
	O'Brien Center, government offices	2003				
	Washtenaw County Prosecuting Attorney, Washtenaw County Public Defender	2008				
	No listing	1940, 1945, 1950, 1955, 1960, 1965				
	County Juvenile Court Center	1970				
	County Juvenile Detention Home, County Juvenile Court Center	1975, 1980, 1984, 1989, 1994				
2270 Platt Road	Education Training Residential Services, Washtenaw County of Washtenaw Juvenile Court	1998				
8	Washtenaw County Juvenile Defender, Washtenaw County Juvenile Detention	2003				
	Washtenaw County Juvenile Center, Washtenaw County Juvenile Division	2008				

Copies of the city directories reviewed are provided in Appendix C.

3.7 Aerial Photographs

Copies of aerial photographs dated 1937, 1940, 1949, 1955, 1963, 1969, 1978, 1985, 1993, 1998, 2000, and 2007 were obtained from EDR. The aerial photographs indicated the following:

Date	Information	
1937, 1940, 1949 Aerial Photographs	Occupied by unimproved agricultural land.	
	Occupied by one building on the northeastern portion of the site.	
Photographs	The remaining areas of the site were unimproved agricultural land.	



Date	Information
1969 Aerial Photograph	Occupied by two buildings on the northern portion of the site. Disturbed soils were visible in the area of the larger building. The remaining areas of the site were undeveloped and/or agricultural land.
1978, 1985, 1993, 1998, 2000, 2007 Aerial Photographs	Occupied by two buildings on the northern portion of the site in the current site configuration. The remaining areas of the site were undeveloped land.

Due to the scale of the aerial photographs reviewed, the level of ascertainable detail was limited. Copies of available aerial photographs reviewed are included in Appendix D.

3.8 Previous Environmental Reports

Previous environmental reports were not provided to TTL by DCCBC or Washtenaw County.



4.0 SITE RECONNAISSANCE

This section discusses the observations of the site during field activities.

4.1 Methodology and Limiting Conditions

Field activities were conducted by Ms. Danielle Green of TTL on April 8, 2010. These activities included a grounds reconnaissance to observe site conditions to identify RECs, if any, at the site and adjoining properties. TTL's systematic approach for performing the site reconnaissance was to obtain overlapping views of the site. Refer to Figure 2.0 for the approximate locations of pertinent site features. Photographs of the site, pertinent site features, and surrounding properties are included in Appendix E.

Grassy vegetation, the site buildings, and asphalt and concrete paved areas limited TTL's observations of the ground surface of the site. On the day of the site visit, the weather was cloudy, with temperatures in the mid 50s.

4.2 Site Description and Current Uses

Access to the site is via Platt Road (eastern boundary). The site is currently occupied by one court and juvenile detention building (2270 Platt Road), one office building (2260 Platt Road), and associated asphalt and concrete paved parking areas on the northern portion of the site. The remaining areas of the site are occupied by grassy vegetation.

4.3 Site Observations

TTL's site observations that were performed to identify potential RECs in connection with the site are summarized below in Table 2.0.

Table 2.0								
Summary of Site Observations								
	Obs	erved	On-site?	Comments				
	Yes	Yes No Possible		Comments				
Hazardous Material Storage and/or Handling	X			Retail sized containers of janitorial materials.				
Petroleum Products Storage and/or Handling		X						
Electrical Transformers	X			One pad-mounted transformer.				
Hydraulic Lifts		X						
Floor Drains and/or Sumps		X						
USTs		X						
ASTs		X						
Noxious Odors		X						
Pools of Liquid		X						



Table 2.0 Summary of Site Observations								
	Obs	served	On-site?	Comments				
	Yes	No	Possible					
Staining (Interior or Exterior)		X						
Stressed Vegetation		X						
Pits, Ponds, or Lagoons		X						
Filled Areas		X						
Wells (drinking, monitoring, dry)		X						
Septic System		X						
Controlled Substances		X						
Other Observations	X			One portable emergency generator.				

Retail-sized containers of janitorial supplies were stored in the janitorial closet of the 2270 Platt Road site building. The janitorial supplies are utilized for the routine maintenance of the site. The materials were not stored near any floor drains. Additionally, no staining was observed in the vicinity of the storage area. Based on the observed conditions, these materials are not considered to be a REC in connection with the site.

One pad-mounted electrical transformer is located outside of the western side of the 2270 Platt Road site building. The electrical transformer, a potential source of polychlorinated biphenyls (PCBs), did not appear to be leaking or damaged. In accordance with federal regulations, transformers that have not been tested are assumed to be "PCB contaminated" (between 50 and 500 parts per million). There is no requirement to replace or to test a transformer unless there is a malfunction or evidence of leakage. In the event of either occurrence, DTE Energy, the owner of the transformer, would be responsible in accordance with all applicable federal, state, and local regulations. The electrical transformer is not considered to be a REC in connection with the site.

One portable emergency generator was observed near the western portion of the 2270 Platt Road building. According to Mr. Fee, no fuel was stored in the generator. No staining was observed in the vicinity of the generator. Based on the lack of fuel in the generator and the lack of staining in the storage area, the emergency generator is not considered to be a REC in connection with the site.



5.0 REGULATORY FILE SEARCH

EDR was contracted to perform a search of ASTM-specified federal, state and tribal databases to obtain information that will assist in the identification of potential RECs in connection with the site. This database report identifies known facilities of environmental concern within their respective minimum search distance radii as specified by ASTM E 1527-05. A copy of the EDR report is presented in Appendix F. The federal, state and tribal databases researched and their respective minimum search distances are summarized below.

Federal Records

- National Priority List (NPL) 1.0 mile radius
- Delisted NPL 0.5 mile radius
- Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) 0.5 mile radius
- CERCLIS No Further Remedial Action Planned (NFRAP) 0.5 mile radius
- Resource Conservation and Recovery Act (RCRA)
 - Treatment, Storage, and Disposal (TSD) facilities 0.5 mile radius
 - Corrective Action Facilities (CORRACTS) 1.0 mile radius
 - Small Quantity Generators (SQG) Site and Adjoining
 - Large Quantity Generators (LQG) Site and Adjoining
- Emergency Response Notification System (ERNS) Site
- Institutional Control/Engineering Control Registries Site
- U.S. Clandestine Drug Lab (USCDL) Site
- Clandestine Drug Lab Listings (CDL) Site
- National Clandestine Laboratory Register (US HIST CDL) Site

State and Tribal Records

- State and Tribal Hazardous Waste Sites (SHWS) 1.0 mile radius
- Solid Waste Landfills and Solid Waste Disposal Sites 0.5 mile radius
- Underground Storage Tanks (USTs) Site and Adjoining
- Leaking Underground Storage Tanks (LUST) 0.5 mile radius
- Institutional Control/Engineering Control Registries 0.5 mile radius
- Voluntary Cleanup Sites 0.5 mile radius
- Brownfield Sites 0.5 mile radius

Table 3.0 summarizes the properties identified by EDR as located within 0.25 mile of the site on the ASTM-specified federal, tribal, and state databases. Properties farther than 0.25 mile from the site are not considered to be potential RECs based on their distance from the site. Table 3.0 also provides an evaluation of each of the properties as a potential REC based on its regulatory status, distance, and direction from the site. Based on area topography, groundwater in the site area is inferred to flow towards the southeast.



Facilities Identified on t	Table 3.0 Facilities Identified on the ASTM-Specified Federal, State and Tribal Databases								
Facility Name and Address	Database Listing	Approximate Distance and Direction from Site	REC (Yes/No)						
Washtenaw County Juvenile Detention 2270 Platt Road	FINDS	Site	No						
Ann Arbor Civic Theater 2275 Platt Road	BEA, SHWS	Easterly adjoining	No						
Ann Arbor Fire Department 2415 South Huron Parkway	LUST, UST	Approximately 400 h							
FISCA Oil Company Inc. #83 3060 Washtenaw Avenue	LUST	Approximately 1,100 feet north-northeast	No						
Buddy's Mini-Mart Inc. #39 Arbor Wash 3031 Washtenaw Avenue	LUST/UST SHWS/Brownfields/BEA	Approximately 1,150 feet north	No						
Gordon Cadillac LLC John Lee Oldsmobile 3120 Washtenaw Avenue	RCRA-CESQ/FINDS LUST/UST	Approximately 1,150 feet north-northeast	No						
Arbor Buick Co. 3165 Washtenaw Avenue	RCRA-NonGen FINDS LUST/UST	Approximately 1,200 feet northeast	No						
Steven Murillo 3000 Washtenaw Avenue	LUST/UST	Approximately 1,200 feet north	No						
RCRA-NonGen		Approximately 1,250 feet northeast	No						

EDR identified the site on the Facility Index System (FINDS) database. The FINDS database lists the site as identified on the National Compliance Database (NCDB), which supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act Tracking System (TSCA) databases. No additional information regarding the site's NCDB listing was provided by EDR or identified through a search of U.S. EPA's on-line databases. Based on the lack of other database listings for the site and the nature of the NCDB listing (not indicative of a release or spill of hazardous substances or petroleum), the NCDB listing is not considered to be a REC in connection with the site.

EDR identified the easterly adjoining former Ann Arbor Civic Theater property at 2275 Platt Road (across Platt Road from the site) on the Baseline Environmental Assessment (BEA) and SHWS databases. This property is currently occupied by Vineyard Church. Inclusion in the BEA database indicates that hazardous substances were detected at the property in excess of the Michigan residential cleanup criteria. Information in the SHWS database indicates that evaluation has been conducted. Based on its inferred downgradient location and current use as a



church, the former Ann Arbor Civic Theater property is not considered to be a REC in connection with the site.

EDR identified the Ann Arbor Fire Department property located approximately 400 feet east of the site at 2415 South Huron Parkway, on the UST and LUST databases. Information in the UST database indicates that one 550-gallon gasoline UST was removed from this property in 1991. Information in the LUST database indicates that the facility had one LUST incident that was closed in August 1992. Based on its distance from the site, inferred downgradient location, and current regulatory status (closed LUST), the Ann Arbor Fire Department property is not considered to be a REC in connection with the site.

Based on the distances from the site, facility status, and/or inferred crossgradient or downgradient location, none of the remaining facilities identified on the above-referenced ASTM-specified state and federal databases are considered to be RECs in connection with the site.

Fifteen facilities were identified on EDR's "Orphan" list. Facilities may be identified as "Orphan" due to an incomplete address, an inaccurate address, or a street address that could not be accurately "geocoded". Nevertheless, these facilities have been determined to be in the general area by city, ZIP code, or county boundaries. None of the facilities identified by EDR on the "Orphan" list were identified within the immediate site area during the Phase I ESA site reconnaissance or research; therefore, none of these facilities are considered to be RECs in connection with the site. For detailed "Orphan" facilities information, refer to Appendix F.



6.0 CURRENT AND HISTORICAL USES OF ADJOINING PROPERTIES

This section discusses the current and historical uses of the properties adjoining and surrounding the site to evaluate potential or identified RECs in the vicinity of the site. The information below describes the extent that indications of current and past uses of adjoining properties were identified through site reconnaissance, interviews, record reviews, or client-provided information obtained during this Phase I ESA for the site as specified in Section 3.0 of this report. The historical and current uses of the adjoining properties are as follows:

North:

The area adjoining to the north of the site was undeveloped and/or agricultural land from at least 1937 to approximately 1985. Since at least 1985, Washtenaw County Park has occupied the property.

East:

The area adjoining to east of the site, beyond Platt Road, has been occupied by various commercial businesses since the 1940s. The businesses included a filter supplier, an electronic equipment supplier, marketing, a house cleaner, a waste water treatment equipment supplier, offices, a theater, and a skating park. Currently, United Way (2305 Platt Road), Vineyard Church (2275 Platt Road), and a bank (2400 Platt Road) occupy the properties. The area northeast of the site across Platt Road at 2231 Platt Road has been occupied by an automotive repair facility since 1984. This property was not identified on any of the environmental databases searched by EDR. In addition, it is located downgradient of the site. Therefore, this facility is not considered to be a REC in connection with the site.

South:

The area adjoining to south of the site was undeveloped and/or agricultural land from at least 1937 to the late 1950s/early 1960s. A development of single-family residential homes has occupied this area since at least 1963.

West:

The area adjoining to the west of the site was undeveloped and/or agricultural land from at least 1937 until approximately 1985. Since at least 1985, Washtenaw County Park has occupied the property.

None of the identified current and historical uses of adjoining and surrounding properties are considered to be RECs in connection with the site.



7.0 DATA GAPS

Data failure occurs when standard historical resources that are reasonably ascertainable and likely to be useful have been reviewed and yet the objective of identifying the use of the site to the first use or 1940, whichever is earlier, has not been met. As indicated in ASTM E1527-05, data failure is not uncommon when performing Phase I ESAs. TTL was able to identify the site use back to 1937 (unimproved agricultural land).

The term "significant data gap," in the context of this report, is defined as a lack of information, which, in TTL's professional judgment, might materially impact TTL's ability to identify RECs at the site. Examples of significant data gaps might include inaccessibility to a portion of the property during site reconnaissance or the inability to interview a site owner or occupant. There were no significant data gaps for this Phase I ESA.



8.0 OPINION

TTL has performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM E 1527-05. Any exceptions to, or deletions from, this practice are described in Section 1.2 of this report. This Phase I ESA has revealed no evidence of RECs in connection with the site, expect for the following:

• The possible former use of a heating oil UST at the site associated with the 2260 Platt Road building from the 1950s until at least the early 1970s.



9.0 DECLARATION

This assessment was performed utilizing methods and procedures consistent with customary practice designed to conform to acceptable industry standards. The TTL team that performed this Phase I ESA consisted of environmental staff and professionals that have training and expertise in performing Phase I ESAs. Resumes for the TTL team that performed this assessment are provided in Appendix G. An Environmental Scientist performed the site reconnaissance, research, interviews, and prepared the report. A Senior Engineer reviewed the draft report. A Senior Scientist coordinated with the client, provided technical guidance and Quality Assurance/Quality Control and technical reviews.

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property (site). We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

PREPARED BY:

DANIELLÉ J. GREEN ENVIRONMENTAL SCIENTIST

REVIEWED BY:

STEVEN J. GACH, P.E. SENIOR ENGINEER

APPROVED BY:

ROBIŇ J. CLARK SENIOR SCIENTIST



10.0 REFERENCES AND RECORDS OF COMMUNICATION

Resources utilized and persons contacted to obtain information to complete this Phase I ESA included, but were not limited to:

Ann Arbor Assessor's Office, contacted for parcel information, April 7, 2010.

Ann Arbor Fire Department, contacted for environmental information, April 7, 2010.

Ann Arbor Public Library, provided city directories dated 1940, 1945, 1950, 1955, 1960, 1965, 1970, 1975, 1980, 1984, 1989, 1994, 1998, 2003, and 2008, April 8, 2010.

EDR search of state, federal, and tribal databases which included, but were not limited to, the following resources: NPL; CERCLIS; CERCLIS NFRAP; ERNS; RCRIS SQG/LQG; TSD; CORRACTS; SHWS; USTs; LUSTs; and SWL; Sanborn map information; Aerial photographs, April 7, 2010.

Mr. Jason Fee, Facilities Manager and site representative, provided site information and completed the key site manager and owner questionnaires, April 5, 2010.

Mr. Brett Lenart, Washtenaw County, provided site information, March 10, 2010.

USGS, Ann Arbor, Michigan Topographic Quadrangle (dated 1965, photorevised 1983).


USGS Web Soil Survey, http://websoilsurvey.nrcs.usda.gov/app/HomePage.htm, provided site/area soil information, April 2010.


Washtenaw County Health Department, contacted for environmental information, April 7, 2010.



FIGURES







APPENDIX A PHASE I ESA QUESTIONNAIRES



PHASE I ENVIRONMENTAL SITE ASSESSMENT KEY SITE MANAGER QUESTIONNAIRE

Property:	2260 and 2270 Platt Road	TTL Project No.:	6358.01
	Ann Arbor, MI		
		Date:	4/5/2010

The following is a list of questions regarding the environmental status of the above-referenced property (Site). Please answer all questions to the best of your knowledge and in good faith. Mark the column corresponding to the appropriate response. Additional details necessary to explain any yes or unknown responses should be provided in the "Comments" column. Please return the completed questionnaire to TTL Associates, Inc. Thank you for your time.

QUESTION		R	ESP	ONSE	COMMENTS
			N	Unk	
1A.	Is the Site used for an industrial use?		X		
1B.	Are any adjoining properties used for an industrial use?		X		
2A.	To the best of your knowledge, has the Site been used for an industrial use in the past?		X		
2B.	To the best of your knowledge, has any adjoining properties been used for an industrial use in the past?		X		
3A.	Is the Site used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		X		
3B.	Is any adjoining property used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		X		
4A.	To the best of your knowledge, has the Site been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		X		
4B.	To the best of your knowledge, has any adjoining property been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		X		
5A.	Are there currently any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of greater than five gallons in volume or fifty gallons in the aggregate, stored on or used at the Site?		λ		
5B.	To the best of your knowledge, have there been previously any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of greater than five gallons in volume or fifty gallons in the aggregate, stored on or used at the Site?		χ		
6A.	Are there currently any industrial drums (typically 55 gallon) or sacks of chemicals located on the Site?		X		
6B.	To the best of your knowledge, have there been previously any industrial drums (typically 55 gallon) or sacks of chemicals located on the Site?		X		

QUESTION		R	ESP	ONSE	COMMENTS
		Y	N	Unk	
7A.	Has fill dirt been brought onto the Site which originated from a contaminated site?		X		<u>.</u>
7B.	Has fill dirt been brought onto the Site which is of an unknown origin?		χ		
8A.	Are there currently any pits, ponds or lagoons located on the Site in connection with waste treatment or waste disposal?		X		
8B.	To the best of your knowledge, have there been previously any pits, ponds or lagoons located on the Site in connection with waste treatment or waste disposal?		χ		
9A.	Is there currently, any stained soil on the Site?		×		
9B.	To the best of your knowledge, has there been previously any stained soil on the Site?		Х		
10A.	Are there currently any registered or unregistered storage tanks (above or underground) located on the Site?		X		
10B.	To the best of your knowledge, have there been previously any registered or unregistered storage tanks (above or underground) located on the Site?		X		
11A.	Are there currently any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Site or adjacent to any structure located on the Site?		X		
11B.	To the best of your knowledge, have there been previously any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Site or adjacent to any structure located on the Site?		X		
12A.	Are there currently any flooring, drains, or walls located at the Site that are stained by substances other than water or are emitting foul odors?		X		
12B.	To the best of your knowledge, have there been previously any flooring, drains, or walls located at the Site that are stained by substances other than water or are emitting foul odors?		X		
13A.	If the Site is served by a private well or non-public water system, have contaminants been identified in the well or system that exceed guidelines applicable to the water system?		X		
13B.	If the Site is served by a private well or non-public water system, has the well been designated as contaminated by any government environmental/health agency?		X		
14.	Are there any environmental liens or governmental notification relating to past or current violations of environmental laws with respect to the Site?		X		
15A.	Have you been informed of the current existence of hazardous substances or petroleum products with respect to the Site?		X		
15B.	Have you been informed of the past existence of hazardous substances or petroleum products with respect to the Site?		X		
15C.	Have you been informed of the past existence of environmental violations with respect to the Site?		X.		
15D.	Have you been informed of the current existence of environmental violations with respect to the Site?		X		

QUESTION			ESP	ONSE	COMMENTS				
		Y	N	Unk					
16.	Have there been any environmental site assessments of the Site that indicated the presence of hazardous substances or petroleum products on, or contamination of, the Site or recommended further assessment of the Site?		X						
17.	Are you aware of any pending, threatened, or past lawsuits or administrative proceedings concerning a release or threatened release of hazardous substances or petroleum products at the Site?		X						
18A.	Does the Site discharge waste water onto or adjacent to the Site, other than storm water into a storm water sewer system?		X						
18B.	Does the Site discharge waste water onto or adjacent to the Site, other than storm water or sanitary waste into a sanitary system?		X						
19.	Have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the Site?		Χ						
20.	Is there a transformer, capacitor or any hydraulic equipment for which there are any records indicating the presence of PCBs on the Site?		X						
21A.	Are there currently any groundwater monitoring wells located on the Site?		X						
21B.	To the best of your knowledge, have there been previously any groundwater monitoring wells located on the Site?		X						
22.	Are there any oil/water separators on the Site?		X						
23.	Is there a drinking water well on the Site?		X						
24.	Is there a septic system/leach field on the Site?		X						
25.	Are the current Site buildings heated via heating oil?		X						
26.	Have the current and/or historic Site buildings ever been heated via heating oil?		X						
27.	To the best of your knowledge, has there ever been any petrolcum product/hazardous substance spills or releases at the Site?		X						
summa was the current modific	best of your knowledge, rize historical Site use (when Site developed with the improvements, what cations have taken place, what Site used for prior to its use).								
Name:	Jason Fee si	ignat	ure:		John				
				ngth of association 7 years					
Date:	4-8-10				t				

V:\Toledo\Controlled Documents\Phase I\Phase I ESA Forms\Phase I ESA Key Site Manager Questionnaire.doc

PHASE I ENVIRONMENTAL SITE ASSESSMENT QUESTIONNAIRE

Property:	2260 and 2270 Platt Road	TTL I	6358.01	
	Ann Arbor, MI	Data		4/5/2010
	***************************************	Date:	4/5/2010	
referenced pr If you could indicating yo document ex attach a copy	g is a list of potential documents to coperty which are recommended to please take the time to review this our knowledge of the existence of ists, could you indicate the availar of the available documents to this you for your time.	be obtained by s list and check the documents bility of a copy	y the ASTM E k the appropriat listed below. y, and wheneve	1527-05 standard e box (yes or no In addition, if the r possible, pleas
		AVAILABLE		
	DOCUMENT	YES	NO	COPY
Environment	al Assessment Reports Interior	X		·
Environment	al Audit Reports	X		
	al Permits (e.g., solid waste ardous waste disposal, tewater)			
	for Aboveground (AST) or I (UST) Storage Tanks		×	
Material Safe	ety Data Sheets (MSD)	X		
Community l	Right-to-Know Plan		×	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Spill Prevention, Prevention lness Plans, etc.		×	
Hydrogeolog	cic Conditions Reports			
Violations Agencies	Notices from Regulatory			
Environment	al Liens		\times	
Hazardous W	Vaste Generator Notices		\times	
Geotechnical	Studies		\longrightarrow	
Administrativ	reatened, Past Litigation or ve Proceedings Relevant to ad Hazardous Substances		X	

NAME: Juson Fee SIGNATURE: Juson Fee



DOWNRIVER COMMUNITY CONFERENCE BROWNFIELD CONSORTIUM USEPA ASSESSMENT GRANTS NOMINATION FORM

Please return the completed form and attachments to: Paula Boase Program Director Downriver Community Conference 15100 Northline Road Southgate, MI 48195 2408 (734) 362-3477 Fax (734) 281-6661 Paula.Boase@dccwf.org **Application Information** Developer: TBD Address: 110 N. Fauth Alc. P.O Box 9645. Ann Arbor Type of Ownership: Private Public Owner (Entity) Name: Washlehah) Property Access Agreement In-place: X Yes No Proof of access required before project can be approved **Property Information** Project Name: Washand Camby Property Acreage: ~ 6 Address/Location: 2270 Plat Rd. 48104 No. Buildings: Square Footage of Buildings: 43,320 09-12-03-100-00 Parcel Identification No(s).: - Public Land Zoning: PL Surrounding Land Use: Residential, Office, Public Current Owner: Walash Previous Owners: Unknown Historic Property Uses: Agriculture, Juvenile **Assessment Grant Request** Phase I Phase II BEA/Due Care Hazardous Materials Survey Other Anticipated Cost: TBD Previous Environmental Activities Completed Unknown Phase I Phase II □BEA Remediation None

Please provide copies of any available environmental reports.



Personal knowledge/common knowledge of environmental iss	ues on the site: Some as loes tos
Potential Environmental Concerns	
Former Gasoline Station Asbestos/Lead	☐ Industrial Property
Tanks (Above/Below Ground) Drums Pi	(2)
Other Potential Environmental Hazards:	
Potential for Redevelopment	^
Planned Reuse: Potential for demolition, W	narketing for sale (re-use
Existing Development Agreement	eveloper actively pursuing the property
☐ Interest has been expressed in property ☐ Ci	ty/Township is actively pursuing redevelopment
High potential for redevelopment once it is cleared and/or re	esponse activities taken
Comments: Centrally located in Ann Avi	our adjacent to public
secreation tacilities	
Please provide site plans for redevelopment, if available.	
Community Impact	
Please describe the impact you feel your proposal will have	re on the community.
This will provide information to facili	tale potential re-use of
This will provide information to facility the property, which will soon be	Vacant.
	*
Capital Investment and Economic Impact	
Total Project Investment: \$ 400,000 (est demolified)	Anticipated Project Development Date: TBD
Total Estimated New Taxes Generated: \$_TBD	Anticipated Project Completion Date: 18D
Estimated Permanent Jobs Created: 18D	Estimated Temporary Jobs Created: 780
Has funding been secured? Yes Yoo Please list type	es and amounts.
Source of Funds: Polential County fund allocation	
Source of Funds:	Amount: \$
Source of Funds:	Amount: \$
Brownfield TIF: Yes No	Amount: \$
`	Amount: \$
Brownfield SBT: Yes No No Pokuhally after	Amount: \$
sale	

SOUTHERN CAMPUS

Family Court - Juvenile Division

2270 Platt Road Ann Arbor, MI 48104

Year Constructed: 1969

Insured Value:

\$7,365,060

Building Size:

42,320 sq ft

Property Size:

10 Acres (for both 2260 and 2270 Platt)

of FTE:

Condition:

Major improvements required in immediate future





Building Usage Notes

The south half of this building was previously used for juvenile detention and has cells, dayrooms, a kitchen, recreation rooms, and support areas on the south portion of the building. In 2003, after the new Youth Center was built, portions of this area were converted for office and storage space; however, much of this area remains unused. The north half of the building houses courtrooms and court support functions.

Building Condition Notes

This building is 37 years old and over half of the building is empty. Most of the detention portion of the building could not be converted to usable office space even with major renovation. Fixtures, partitions, plumbing and electrical equipment in all restrooms require major renovation to meet current standards. The heating and distribution system is original equipment and due for immediate replacement and upgrades. The addition of a new entrance for security purposes will be completed in 2006.








Chevron Project

This building was not included in the Chevron project.



SOUTHERN CAMPUS

O'Brien Center

2260 Platt Road Ann Arbor, MI 48104

Year Constructed: 1954

Insured Value:

\$599,020

Building Size:

6,680 sq ft

Property Size:

10 Acres (for both 2260 and 2270 Platt)

of FTE: Condition:

Major improvements required in immediate future







Building Usage Notes

The O'Brien Center is used by the Public Defender and Prosecuting Attorney as support to the Family Court – Juvenile Division, which is located directly next to the building at 2270 Platt Road.

Building Condition Notes


This building is approximately 52 years old and requires major improvements in the immediate future. Most of the buildings mechanical systems are beyond their useful life and major improvements are also needed on the building's interior finishes, roof, doors, entrances and restrooms.






Chevron Project

This building was not included in the Chevron project.



APPENDIX B LOCAL GOVERNMENT AGENCY RECORDS





TAX MAP 2008

PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN

TTL PROJECT NO. 6358.01



[Back to Non-Printer Friendly Version] [Send To Printer]

Parcel: 09-12-03-100-001 **Data Current As Of:** 0:32 AM 3/04/2010

Property Address

[collapse]

2960 WASHTENAW AV Ann Arbor, MI 48104

Owner Information

[collapse]

WASHTENAW COUNTY 220 NORTH MAIN STREET Ann Arbor, MI 48104

Unit:

09

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2010

[collapse]

Property Class:

092

Assessed Value:

\$0

School District:

81010 - Ann Arbor

Taxable Value:

\$0

State Equalized Value: User Number Indx:

\$0

Map # Date of Last Name Chg:

N/A 12/19/2008

Date Filed:

Principal Residence Exemption

(2009 May 1):

0.0000 %

Principal Residence Exemption

(2009 Final):

0.0000 %

Principal Residence Exemption

(2010 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2009	\$0	\$0	\$0
2008	\$0	\$0	\$0

Land Information			[collapse]
Acreage:	0.00	Frontage:	0.00 Ft.
Zoning Code:	R1A	Depth:	0.00 Ft.
Land Value:	\$0	Mortgage Code:	N/A
Land Improvements:	N/A	Lot Dimensions/Commer	nts:
Renaissance Zone:	NO		
ECF Neighborhood Code:	099		

Legal Information for 09-12-03-100-001

[collapse]

BEG E 1/4 POST SEC 3 TH N 0 DEG 37 MIN E 2180.05 FT TH S 89 DEG 35 MIN 30 SEC W 191.05 FT TH N 89 DEG 50 MIN 30 SEC W 620 FT TH W 425 FT ALG ARC CURVE TO LT RAD 8617.9 FT CEN ANG 2 DEG 49 MIN 30 SEC CHORD N 76 DEG 45 MIN 30 SEC W 425 FT TH N 78 DEG 10 MIN 10 SEC W 1449.1 FT TH S 1 DEG 20 MIN W 390.12 FT TH N 89 DEG 24 MIN W 12 FT TH S 0 DEG 54 MIN 30 SEC W 100 FT TH S 89 DEG 05 MIN 30 SEC E 140 FT TH S 0 DEG 54 MIN 30 SEC W 250 FT TH N 89 DEG 05 MIN 30 SEC W 140 FT TH S 0 DEG 54 MIN 30 SEC W 150 FT TH S 0 DEG 54 MIN 30 SEC W 170 FT TH N 89 DEG 56 MIN 30 SEC W 170 FT TH

Sales Information

2 sale r	ecord(s) fo	ound.			
Sale Date	Sale Price	Instrument Grantor	Grantee	Terms Of Sale	Liber/Page

11/21/2008 \$0.0	00	U	WASHTENAW COUNTY BUILDING AUTHORITY	WASHTENAW COUNTY	Warranty Deed	4708/205
12/26/1989 \$1.0	00	U	WASHTENAW COUNTY	WASHT COUNTY BLDG AUTHORITY	Warranty Deed	2376:0467

Building Information

0 building(s) found.		
Description	Floor Area	Yr Built

^{**}Disclaimer: BS&A Software provides this Web Site as a way for municipalities to display information online and is not responsible for the content or accuracy of the data herein. This data is provided for reference only and WITHOUT WARRANTY of any kind, expressed or inferred. Please contact your local municipality if you believe there are errors in the data.

Privacy Policy



WILLIAM G. MILLIKEN, GOVERNOR

GENERAL OFFICE BUILDING 7150 HARRIS DRIVE LANSING, MICHIGAN 48913

PHONE: (517) 322-1924

FIRE MARSHAL DIVISION

DEPARTMENT OF STATE POLICE

COL. GERALD L. HOUGH, DIRECTOR

December 19, 1980

RECEIVED

Mr. Todd Woolery, Director Washtenaw County Detention Home 2270 Platt Road 48104 Ann Arbor, MI

JAN 1 5 1981

FIRE DEPARTMENT

Fire Safety Inspection Report, Child Caring Institution (27)

Washtenaw County Detention Home Ann Arbor - Washtenaw County

DSS-I-43-81, CA 81167

From: Captain William R. Rucinski, Chief, Fire Marshal Division D/Lt. William B. Rando, Adult & Children's Inspection Unit

By: D/Sgt. William Zimmerman, Ypsilanti State Police Fire Marshal Division on December 16, 1980

Encl: Fire Safety Certification (FM-50)

An inspection has been made of the above captioned facility at the request of the Department of Social Services. This report describes conditions which are not in accordance with the applicable rules or guidelines for your type of facility. Therefore, we are asking you to comply with the following:

- Re-install 1/4 inch wired glass in steel frames in all of the below listed areas to maintain required room to corridor separation. For this project only, Lexan Polycarbonate up to 1/4 inch thick or any similar material that has been tested by ASTM-D-2843-73 may be installed to the room side of the wired glass to prevent breakage by residents. (Rule 3)
 - a. Boys Sleeping Rooms
 - b. Staff Office Room #14
 - c. Entry Hall area
 - d. Homemaking Room
 - e. Kitchen
 - f. Classroom 31
 - g. Classroom 72
 - h. ANY similar areas throughout facility
- 2. Rule 18(a)(b) Air handling equipment recirculating air in more than one room or single area shall have fire dampers installed on the discharge side of each recirculating fan unit.

Where practicable, an approved thermostatic device shall be installed in the return air duct ahead of the fresh air intake, actuation of which shall open the electrical circuit shutting down the fan. If this cannot be



Mr. Todd Woolery Page Two December 19, 1980

- (cont.) accomplished, thermostatic device or smoke detection may be located on the discharge side of the fan performing the same required function.
- 3. Rule 16 Remove the combustible storage from the following rooms or separate the rooms by one (1) hour construction with automatic sprinkler protection.
 - a. Room 16
 - b. Room 29
 - c. Room 20
 - d. Room 30
- 4. Replace the fire extinguishers in the following areas:
 - a. Homemaking Room
 - b. Day Room
- 5. NFPA #13 Relocate the sprinkler head in north end of the wood shop storage room. Sprinkler head is obstructed by an air duct.
- 6. Rule 5 Remove the cabinet in front of exit door in Room 27.
- 7. Rule 14 The fire alarm system shall be tested at least one time per month. Test sprinkler system at least quarterly. Maintain a log of all tests.
- 8. Rule 12 Repair the exit light at west end of Girls Dorm area.

If you have any questions regarding these requirements, you may contact Detective Sergeant Zimmerman at (313) 482-1413.

WRR:WBR:cmh

cc: Dept. of Social Services, Virgil Carrier (Iansing)
Dept. of Social Services, Michael Miller (Ann Arbor)
Arbor Fire Department
Inspecting Officer

DEPARTMENT OF STATE POLICE FIRE MARSHAL DIVISION GENERAL OFFICE BUILDING 7150 HARRIS DRIVE LANSING, MICHIGAN 48913

FIRE SAFETY CERTIFICATION

DSS-I-43-81 CA 81167 4-26-0457-80 Closed

FACILIT	Υ _	Washtenaw County Detention Home			
ADDRESS		2270 Platt Road, Ann Arbor, MI	48104		
COUNTY		Washtenaw			
()	Hospital	()	ICF/MR
()	Nursing Home	()	School
()	Home for Aged	(')	L.P. Gas
()	Psychiatric Hospital	()	Public Assembly
(X)	Child Care Organization	()	Flammable Liquid
()	Adult Foster Care Facility	()	Explosive Storage
()	Freestanding Surgical Clinic			
()	OTHER		· · · · · · · · · · · · · · · · · · ·	
Below c	one	clusion drawn from an inspection rep tted by: Detective Sergeant William	port dat Zimmern	ed nan	December 16, 1980
1. ()	This facility is in acceptable compules and therefore is approved for			
2. (X)	This facility is not in complete corules, but the items of noncompliant temporary approval is recommended pending compliance with corrective	nce are untilTH	of E N	such a nature that EXT REQUIRED INSPECTION
3. ()	This facility is not in acceptable rules. Until substantial complian is attained, approval for use and	ce with	th	e corrective directives
To:	`	William Brown and of Bullia Had	+h n		of Modical
()	Michigan Department of Public Heal Care Administration			
(X) ()	Michigan Department of Mental Heal Department of Social Services, Bur Fire Safety Division			
()	X)	Other Mr. Michael Miller, DSS, An	n Arbor,	/Anı	n Arbor Fire Department
cc: Fa	aci nsp	lity ecting Department Department of St	ate Pol	ice	- Ypsilanti

SIGNATURE William B. Rando

TITLE Det/Lieutenant

DATE JAN 581

FIRE SAFETY INSPECTION REQUEST

Michigan Department of Social Services

Michigan Department of State Police Fire Marshal Division

DS	S-	Numb C→	er 4	3	-8	Į
2. Date	Forwar	ded/	//	81	· · ·	

see instructions on pack.				-T	
3. License Number CA 81167	4. Expiration Da 01/31		5. Status of License REGULAR - APPROVAL	6. Capacity	27
7. Type of Facility			8. Reason for Inspection		
Foster Family Home (for 1 - 4 chi Foster Family Group Home (for 5 Family Day Care Home (for 1 - 6 Group Day Care Home (for 7 - 12 Adult Foster Care Family Home (to 6 children) children) children)		New Application Reinspection (Specify below) Renewal Inspection Complaint (Specify below)	Proposed f	Plan Review New Construction/
Adult Foster Care Small Group H Adult Foster Care Large Group H	ome (for 7 - 12)		9. Name of Facility WASHTENAW COUNTY DETEN		, 55.000
Adult Foster Care Carge Group 11 Adult Foster Care Congregate Face Child Caring Institution		1	10. Name of Administrator/Contact Person Todd Woolery, Director		
	Open		11. Location of Facility (Number, Street) 2270 Platt Road		
Child Care Center County Infirmary	en e		12. City Ann Arbor	13. Tow	vnship
14. Is the facility (Check proper box)			15. County	16. Zip	
AIS/MR Yes	No No		WASHTENAW 17. Facility Telephone Number 971-7100		104 ernate Telephone Number
19. Directions to the Facility			37.7100	l	
			·	······································	
				1. STATE	POLICE LUCION
				DEC 3 0 1	1980
20. Comments:				re water	
				the second of th	**************************************
			MI lin	CH. STA	TE POLICE
			L	11	02 1980
MAIL CORRESPONDENCE TO:			21. Date of Last Fire Safety Inspection 08/10/77	FIRE MAI	RSHAL DIV. , MICHIGAN
above address			TO BE COMPLETED BY FIRE MA	RSHAL DIVIS	SION
23. Address (Number, Street)			Post, District, Division or Bureau		
24. City	25. State	26. Zip Code	Pg/son Contacted/Title		
27. Signature of Licensing Worker/Cons Michael Miller, Licen	sing Consu	ltant		28. Telephone (313) 9	994-1862
29. Address of Worker/Consultant (Nun 2350 West Stadium Blv			30. city Ann Arbor	31. Zlp Code 48103	32. Date of Request 11/20/80
DSS-1712 (Rev. 4-78) Previous edition	obsolete.				

MICHIGAN DEPARTMENT OF STATE POLICE POST COMPLAINT #4-260457-80
ADULT & CHILDRENS UNIT INSPECTION CHECKLIST

		DATE /	16-80)		
	OF FACILITY WASHENING Co. DETENTION HOME	DAY CARE CENTER CHILD CARING IN	ST			
ADDRE	ss 2270 PLATT Rd.	RESIDENTIAL FAC SECURE CUS			8L	
	ANN ARBIE /CAPACITY: 27	OPEN CUSTO CHILDREN'S CAMP			····· 🗍	
	Y WASHTENAND ZIP CODE 48104	ADULT FOSTER CA SUBSTANCE ABUSE	FACILIT	Y		
The f	ollowing areas of fire safety were considere cting the above captioned facility:	d by the undersi	gned off	icer while	e	
1.	Plans required and submitted:		YES	NO	W/AD	
2.	Building construction classification approve of occupancy and location of occupancy: (Che	ed for type eck type of cons	(ES ruction)	NO	N/A	
	▼ FIRE RESISTANT □ NON-COMBU	STORIES	WOOD FRA	R PROTECTE ME	D-ORDINA	RY
3.	Required means of egress and/or corridors ac	dequate, & appro	ved: 🏵	Э ио		N/A
4.	Adequate Exits (exterior exit doors):		YE.	₹ NO)	N/A
5.	Approved hardware installed (Non-locking ag	ainst egress):	(YE	S NO)	N/A
6.	Required exit stairways enclosed:		Æ	g NC)	N/A
7.	Required floor separation provided at basemelevels above main floor:	ent and/or	VE	s) no)	N/A
8.	Interior finish use areas including basemen	t, if occupied	: YE	s no)	N/A
9.	Interior finish/means of egress/ Approve ("B" interior finish for most basement occu	d ("B" in most f pancies):	ac.) Æ	s no)	N/A
10.	Combustible and flammable liquid storage ro separated when required:	oms properly	Œ	§ NO)	N/A
11.	Fire alarm or system provided, where requir	ed:	Œ	NO €)	N/A
12.	Fire detection system provided:		YE	S NO	3	d/D
13.	Automatic sprinkler system provided:		X	S N	0	N/A
14.	Adequate number and type of fire extinguish	ers provided:	YE	:s 🚳	0	N/A
15.	Heat plant room and/or ventilation system ewhen required:	enclosed where a	nd, YE	:S 🐠	Ø	N/A
16.	Gas or oil water heater enclosed:		¥Ι	S N	О	N/A
17.	Change of occupancy or location of licer	nsed area:	YI	es n	0	STA-
18.	Fire separation provided where and when recoccupancy - D.C.C. Basement use area, etc.)	quired (Mixed	YI	es n	10	¥/A
19.	Door direct to outside from occupied baseme	ent use area:	ď	S N	Ю	N/A
20.	Door swing approved (More than 12 must be	in direction of	egress) 8	ES N	10	N/A
21.	Door width approved:		χ	(S) N	10	N/A
22.	Required exit doors and doors in egress all hinged \underline{e} hung at floor level:	l side	Ý	ES N	10	N/A

THIS FORM WILL BE SUPPLIED WITH EACH INSPECTION PACKET
AND MUST BE COMPLETED & RETURNED TO STATE POLICE FIRE MARSHAL DIVISION AT ADDRESS BELOW.

MICHIGAN DEPARTMENT OF STATE POLICE FIRE MARSHAL DIVISION GENERAL OFFICE BUILDING 7150 HARRIS DRIVE LANSING, MICHIGAN 48913 Willin Jamm(SIGNATURE) MSP Ypsilant,
(DISTRICT & POST)



CITY OF ANN ARBOR MICHIGAN

219 East Huron Street, Ann Arbor, Michigan 48108

Phone (313) - 994-2772

Ann Arbor Fire Department

July 16, 1976

Mr. Robert E. Bee Division of Child Welfare Licensing Suite 1180-84 Executive Plaza 1200 Sixth Street Detroit, Michigan 48226

Re: Washtenaw County Juvenile Detention Center

2270 Platt Road, Ann Arbor 48104

Dear Mr. Bee:

This Department and Mr. Todd Woolery of the above facility have been working to implement improvements in the fire protection of the Detention Center.

One of the major items in the process is the installation of a Dry Chemical Hood Extinguishing System in the Kitchen.

I would like to bring to your attention that the present alarm system is deficient and I feel a meeting with you, Mr. Woolery and me is in order.

I feel that this department could grant a tentative approval for relicensing with the understanding that the three of us meet and initiate steps to provide adequate fire detection and annunciation for this detention facility.

Please respond.

Cordially,

Charles J. Osborn Fire Inspector

CJO:ap

cc: Mr. Todd Woolery

2270 Platt Road, Ann Arbor 48104



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

	JOHN T.	. DEMPSEY	, Director				
				Date:	6-10-76		
				Provider No.:			
Fire Inspection Bureau 219 E. Huron Ann Arbor, Michigan 481		FROM:	Division to F of Suite 1180-11 1200 Sixth S Detroit, MI. 48 (313) 256-371	3226	censing Plaza		
This is a request that a member of your 1973, it is the responsibility of this De thereafter. This evaluation requires the tance in this essential service on behal	partment to regulate e assurance of the he	all child	he child care facil care facilities pri	ity listed. Accord or to initial operat	ion and periodically		
We appreciate your help and thank you f	or your cooperation.						
NAME OF ORGANIZATION							
Wash <mark>tenaw County Juvenile Det</mark> e	ention Center		TYPE OF FACILITY				
ADDRESS (Number and Street) 2270 Platt Road		1	. Child Care Center	☐ Full - Time ☐ Part - Time	Proposed 27		
Ann Arbor	ZIP CODE 48104	2	Child-Caring		Secure Custody Open		
COUNTY W a sh ten aw			. ☐ Foster Family	•			
CONTACT Mr. Todd Woolery, Sup	perintendent		Group Day Cai				
TELEPHONE (Area) 313	(Number) 971-7100	5.	. Camps	Residential	☐ Day		
SPECIAL INSTRUCTIONS		s	TATUS				
			Proposed		Addition		
		D/	Renewal Inspe	ection	Reinspection		
			As soon as p	ossible			
Please send your findings and recommend with your approval. Please mail a copy of your findings.					s if the facility meets		

Todd Woolery, Supe	erintendent	
ADDRESS 2270 Platt Road	Ann Arbor	ZIP CODE 48104





CITY OF ANN ARBOR MICHIGAN

FIRE DEPARTMENT
219 E. Huron Street Ann Arbor, Michigan 48108

April 13, 1976

Mr. Todd Woolery, Director Washtenaw County Juvenile Detention Center 2270 Platt Road Ann Arbor, Michigan

Re: Fire Inspection Conducted 3-31-76

Dear Mr. Woolery:

At your request a fire inspection was conducted 3-31-76. In order to meet current Code Requirements and Life Safety Standards the following conditions require attention:

1. Due to the use and area the chapel has been designated a place of public assembly. In order to comply with requirements for the above:

(last mular) que no persona

a) All Exit doors shall swing in the direction of egress.

b) Exits shall be designated with an illuminated Exit sign powered from an independent or secondary power source.

c) The maximum capacity shall be posted. This may be computed using the following formula: Length x Width _ Number of 15 sq. ft. Persons

A dry chemical, ABC, or CO₂ Hood Extinguishing System should be provided for the kitchen exhaust hood. Water is not an acceptable suppression system for this application.

Craft Room - Remove the clock and cover the exposed electrical wiring.

Repair the fire brick in the kiln.

The practice of melting paraffin for candle making should be discontinued until a proper heating unit designed for that purpose is provided.

The opening from the Day Room to the corridor has a 'B' labelled fire door with a plastic window installed. The plastic should be replaced with wired glass to maintain the fire integrity of the door.

7. Rem doo

7. Remove the dead bolt and repair the lockset on the east Exit door from the Community Room.

8. Repair the synchronizing hardware and magnetic hold-open device on the fire doors segregating the Girls Detention Wing.

Basement Area

Personal 11.

Provide a metal cabinet for the storage of oil base paints and thinners.

Wire in water conditioner in accordance with the National

Electrical Code.

The garage area is in need of a general house cleaning. It is apparent that your present alarm system is deficient in several areas. It is recommended that a meeting with your people, Social Services and this Department be set up to review the need for an approved supervised alarm system, automatic smoke detection, emergency lighting.

If there are any questions regarding the above, please contact this office.

Cordially,

Charles J. Osborn Fire Inspector

CJO:ap

of the



Ann Arbor Fire Department

CITY OF ANN ARBOR MICHIGAN

219 East Huron Street, Ann Arbor, Michigan 48108

Phone (313) - 994-2772

July 13, 1976

Mr. Robert E. Bee Division of Child Welfare Licensing Suite 1180-84 Executive Plaza 1200 - Sixth Street Detroit, Michigan 48226

Re: Washtenaw County Vocational Residential Center 2260 Platt Road, Ann Arbor 48104

Dear Mr. Bee:

A fire inspection conducted 7-2-16 revealed conditions to be satisfactory for the purpose of relicensing for the coming year.

Cordially,

Charles J. Osborn Fire Inspector

CJ0:ap

cc: Ms. Marlys Schutzer, Director 2260 Platt Rd, Ann Arbor 48104 JP DEPARTMENT OF

STATE OF MICHIGAN



WILLIAM G. MILLIKEN, Governor

SOCIAL SERVICES

JOHN T. DEMPSEY, Director

Date:	6-10-76	
Provider No.:		

TO:

City of Ann Arbor Fire Department

Fire Inspection Bureau

219 E. Huron

Ann Arbor, Michigan

FROM:

Robert E. Bee

Division of Child Welfare Licensing Suite 1180-1184 Executive Plaza

1200 Sixth St.

Detroit, Ml. 48226

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act No. 116, P.A. 1973, it is the responsibility of this Department to regulate all child care facilities prior to initial operation and periodically thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children.

We appreciate your help and thank you for your cooperation.

NAME OF ORGANIZATION				
Washtenaw County Vocat	tional Residential Center		TYPE OF FACILI	TY
ADDRESS (Number and Street) 2260 Platt Road		1. Child Care Center	☐ Full-Time ☐ Part-Time	Proposed Capacity: 12
Ann Arbor	ZIP CODE 48104	2. Child-Caring Institutions	Public D	Secure Custody Open
Washtenaw		3. 🗌 Foster Family	,	
Marlys Schutzer, Direc	ctor	4. Group Day Cai		
TELEPHONE (Area) 313	(Number) 97 ! - 7870	5. Camps	Residential	☐ Day
SPECIAL INSTRUCTIONS		Proposed Renewal Inspendent Due As soon as p		☐ Addition ☐ Reinspection

- 1. Please send your findings and recommendations to this office at the address given above and inform us if the facility meets with your approval.
- 2. Please mail a copy of your findings and recommendations to the child care facility as indicated:

Marlys Schutzer, D	irector	
ADDRESS 2260 Platt Road	Ann Arbor	ZIP CODE 48104
2200 1 1411 10dd	74111 74 501	40104





CITY OF ANN ARBOR MICHIGAN

219 East Huron Street, Ann Arbor, Michigan 48108
Phone (313) - 994-2772

Ann Arbor Fire Department

November 5, 1975

Mr. Robert Bee Div. of Child Care Licensing 1200 Sixth Street, Suite 1180 Detroit, Michigan 48226

Re: Washtenaw County Vocational Residential Center

2260 Platt Road

Ann Arbor, Michigan 48104

Dear Mr. Bee:

A reinspection of the above facility revealed the conditions noted in my letter of September 29, 1975 to be corrected.

Approval of this office is hereby granted.

Cordially,

Charles J. Osborn

CJO:ap

cc: Ms. Maryls Schutzer

Washtenaw County Vocational RDsidential Center

2260 Platt Road

Ann Arbor, Michigan 48104



CITY OF ANN ARBOR MICHIGAN

219 East Huron Street, Ann Arbor, Michigan 48108

Phone (313) - 994-2772

Ann Arbor Fire Department

September 29, 1975

Ms. Marlys Schutzer
Washtenaw County Vocational
Residential Center
2260 Platt Road
Ann Arbor, Michigan 48104

Re: Fire Inspection for Relicensing

Dear Ms. Schutzer:

A fire inspection conducted September 26, 1975 revealed the following conditions that require your attention before approval of this office may be granted:

1. Remove all storage from the corridors as discussed.

OK

2. The refrigerator in the supervisor's apartment should be plugged directly into the wall.

3. The general housekeeping is in need of attention, with particular attention to the combustibles lying around the refrigerator and clothes dryer.

4. The vent pipes from the hot water heater and furnace need sealing where it enters the chimney as was discussed with you.

 The installation of a smoke detector in the sleeping wing of the facility is highly recommended.

As soon as these conditions are corrected, please contact this office so a reinspection may be made and approval granted.

cc: Mr. Robert Bee
Division of Child Care Licensing
1200 Sixth Street, Suite 1180
Detroit, Michigan 48226

Cordially,

Charles J. Osborn Fire Inspector Mrs. Shirley Daly, Consultant Day Care Centers & Nursery Schools MichiganDDepartment of Social Welfare 120 Catherine St. Ann Arbor, Michigan 48108

Re: Jack & Jill 3-Day Care Center

1121 N. Maple Rd.

Dear Mrs. Daly:

A fire inspection made this date revealed that the conditions noted in the letter of March 14, 1973 have been corrected.

Approval for re-licensing for the coming year is hereby granted by this office.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

cc: Mrs. DoneldaClark (Proprietor of Day Care Center) 1445 Woodland Dr., AA, 48103 Mrs. Shirley Daly, Consultant Day Care Cenders & Nursery Schools Michigan Department of Social Welfare 120 Catherine St. Ann Arbor, Michigan 48108

Re: Jack & Jill 3-Day Care Center 1121 N. Maple Rd.

Dear Mrs. Daly:

A fire inspection made this date revealed the following conditions which have to be corrected before approval by this office make be granted:

- 1. Remove all combustible storage from furnace room.
- 2. Provide a ${\rm CO_2}$ or ABC extinguisher for the kitchenette.

A reinspection will be made when we are informed that these difficiencies have been corrected.

Charles J. Osborn

Fire Inspector

Fire Prevention Bureau

CJO/dw

cc - Mrs. Donelda Clark (Proprietor of Day Care Center) 1445 Woodland Dr., Ann Arbor 48103



WILLIAM G. MILLIKEN, Governor

DAY CARE CENTER AND NURSERY SCHOOL SERVICES 13730 W. EIGHT MILE ROAD OAK PARK, MICHIGAN 48237 548-2361

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

			DATE	·26 - 73
TO: City of Ann Arbor Fire De	ent. FF	ROM:	FILE #	
219 E. Huron Ann Arbor, MI 48108	5.00	Mrs. Shir Consultan		
				te.
			. + .	
This is a request that a member of your 1944, Act 280, P.A. 1939, and Act 288, facilities prior to initial operation and a of the children. Therefore, we are askin We appreciate your help and thank you for	P.A. 1939, it is the resporn nnually thereafter. This e ng your assistance in this	rsibility of this De valuation requires	epartment to evaluate all the assurance of the he	l child care
NAME	<u> </u>		TYPE OF FACILITY	
Jack & Jill 3 Day Care Center	r		ED F U TO L D	
ADDRESS (NUMBER AND STREET)		I I. — Ody Horsely. —		
1121 N. Maple Rd.			•	Capacity —
CITY	ZIP CODE	2. 🔲 Child-Carin	County County	Secure Custody
Ann Arbor	48103	z cirra-curiii	g man. Private	Open
Washtenaw				
CONTACT		3. 🔲 Group Home	: County	Private
Mrs. Donelda Clark	<u> </u>			
761-4118 (NUMBE	LI .	4. Camps:	Residential [Day
SPECIAL INSTRUCTIONS		STATUS		
45 children, 2½-6, full day		Proposed	Relocation	Addition
		X Annual Ins	pection	Reinspection
	<u> </u>	DATE REPORT DUE		-
		as soon a	s possible	
 Please send a copy of your finding facility meets with your approval. 	s and recommendations to	this office at the c	address given above and	inform us if the
2. Please mail a second copy of your	findings and recommendati	ons to:		
NAME Mrs. D	onelda Clark, Prop.	Jack & Jill 3	3 Day Care Center	
ADDRESS 1445 Wo	odland Dr.	CITY	Ann Arbor	21P CODE 48103



March 5, 1974

Mr. Robert Bee, Consultant State of Michigan Dept. of Social Services 32500 Dolly Madison Dr. #230 Madison Heights, Michigan 48071

Re: 2270 Platt Rd.

Dear Mr. Bee:

A fire inspection made this date revealed that conditions were satisfactory for the purpose of relicensing for the coming year.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

cc: Tom Woolery

Supt. - Washtenaw County Juvenile Ctr.

STATE OF MICHIGAN



DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

	DATE2-28-74	_
FROM:	Robert Bee FILE #	
	Div. of Child Welfare Lic.	
	13730 W. Eight Mile Road	
	Oak Park, MI 48237	

ZIP CODE

48104

Fire Prevention Bureau 219 E. Huron Ann Arbor, MI 48108

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

AME		TYPE OF FACILITY
Washtenaw County Juvenile Court Center ADDRESS (NUMBER AND STREET) 2270 Platt Road		1. Day Nursery: Full-Time Proposed Part-Time Capacity
Ann Arbor	ZIP CODE 48104	2. X Child-Caring Inst.: County Secure Custody
COUNTY Washtenaw CONTACT Mr. Todd Woolery, Superintendent		3. Group Home: County Private
FELEPHONE (AREA)	(NUMBER) -7100	4. Camps: Residential Day
Cap: 27 children		STATUS Proposed Relocation Addition Annual Inspection Reinspection
		As soon as possible

Ann Arbor



DSS-3627 (Rev. 11-71) (Previous editions may be used)

2270 Platt Road

2. Please mail a second copy of your findings and recommendations to:

ADDRESS

Mr. Todd Woolery, Superintendent

Mra Robert E. Bee Consultant to Children's Agencies Div. of Licensing and Consultation 13730 W. Eight Mile Road Oak Park, MI 48237

Re: Washtenaw Co. Juvenile Court Ctr. 2270 Platt Rd. Ann Arbor

Dear Mr. Bee:

A reinspection made this date of the above named facility reveals that conditions noted in our previous letter have been corrected.

Approval for relicensing for the coming year are hereby granted by this office.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

cc: Mr. Geo. E. Foltz
Dir of Juvenile Services
2270 Platt Rd., Ann Arbor



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

FROM:	Robert E. Bee FILE #
	Consultant to Children's Agencies
	Div. of Licensing and Consultation
	13730 W. Eight Mile Road
	Oak Park MI 48237

DATE __March 29. 1973

To: Nolan J. Lee, Fire Marshal Ann Arbor Fire Dept. 219 E. Huron St. Ann Arbor, MI 48108

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

NAME			TYF	PE OF FACILITY	/
Washtenaw Co. Juvenile C	ourt Center	1. [7]	Day Nursery:	Full-Time	Proposed
2270 Platt Road			5 by 110/00/y.	Part-Time	Capacity
Ann Arbor	ZIP CODE 48104	2. 🔯	Child-Caring In	St.: County	X Secure Custody
COUNTY		#	3	Private	Open
Washtenaw				_	
CONTACT		3.	Group Home:	County	Private
Mr. George Foltz, Dir. o		þ			
313 971-7		4.	Camps:	Residential	Day
SPECIAL INSTRUCTIONS		STATL			
		31710	Proposed [Relocation [Addition
				•	
		LX	Annual Inspect	ion	Reinspection
		DATER	EPORT DUE	I - 73	
 Please send a copy of your finding facility meets with your approval. 	s and recommendations t	o this of	fice at the addre	ess given above (and inform us if the
2. Please mail a second copy of your	indings and recommende	ations to	:		
NAME		 .			
Mr. Ge	orge E. Foltz, Dir	rector	of Juvenile	Services	
ADDRESS	<u> </u>	CITY	or varoni to	001 11000	ZIP CODE
2270 F	latt Rd.		Ann Arbor		48104



DSS-3627 (Rev. 11-71) (Previous editions may be used)

April 6, 1973

Ms. Marlys Schutjer
Acting Director
Wamhtenaw County Vocational
Residential Center
2260 Platt Road
Ann Arbor, Michigan

Dear Ms. Schutjer:

During the course of an inspection made on April 5, 1973, the following conditions were noted:

- 1. The number of electrical outlets for the apartment were inadequate.
- 2. There was no extinguisher provided for the kitchen.

It is the recommendation of this department that these conditions be corrected. No reinspection will be made.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

cc - Ms.

April 6, 1973

Mr. Robert E. Bee Consultant to Children's Agencies Div. of licensing and Consoltation 13730 W. Eight Mile Road Oak Park, MI 48237

Re: 2260 Platt Rd.

Washtenaw Co. Vocational Residential Center

Dear Mr. Bee:

A fire inspection made on April 5, 1973 of the above named facilities revealed that conditions are satisfactory.

Approval is hereby granted by this office for relicensing for the coming year.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

cc - Ms. Marlys Schutjer, Acting Dir. 2260 Platt Rd. Ann Arbor, Michigan 48104





WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

FROM: Robert E. Bee Consultant to Children's Agencies Div. of Licensing and Consultation	
13730 W. Eight Mile Rd. Oak Park, Ml 48237	
Oak Falk, MI 40257	

DATE March 29, 1973


To: Nolan J. Lee, Fire Marshal Ann Arbor Fire Dept. 219 E. Huron St. Ann Arbor, MI 48108

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

NAME		TYPE OF FACILITY
Washtenaw Co. Voca ADDRESS (NUMBER AND STREET) 2260 Platt Rd.	ational Residential Cer	1. Day Nursery: Full-Time Proposed Part-Time Capacity
CITY Ann Arbor	ZIP CODE 48104	2. \(\times \) Child-Caring Inst.: \(\times \) Private \(\times \) Open
Washtenaw CONTACT Marlys Schutjer, A	Acting Director	3. Group Home: County Private
TELEPHONE (AREA) 313	(NUMBER) 971-7870	4. Camps: Residential Day
SPECIAL INSTRUCTIONS		STATUS Proposed Relocation Addition Annual Inspection Reinspection
		DATE REPORT DUE 5-1-73

- Please send a copy of your findings and recommendations to this office at the address given above and inform us if the
 facility meets with your approval.
- 2. Please mail a second copy of your findings and recommendations to:





DSS-3627 (Rev. 11-71) (Previous editions may be used) James H. Kinkema, Licensing Consultant State Department of Social Services Kalamazoo Field Office 426-28 West South Street Kalamazoo, Michigan 49006

Re: Washtenaw County Vocational Residential Center 2260 Platt Road Ann Arbor, Michigan 48104

Dear Sir:

Inspection was made of the above captioned facility and as far as this department is concerned it meets current fire regulations. At this time we have no objection for renewal of license for the coming year.

Very truly yours,

N.J. Lee, Inspector Fire Prevention Bureau City of Ann Arbor

cc: Mr. Tim Walters

NJL/ks



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

N, Director	DATE February 8, 1972
FROM:	James H. Kinkema FILE # Licensing Consultant
	State Department of Social Services
	Kalamazoo Field Office
	426-28 West South Street
	Kalamazoo, Michigan 49006

TO:Mr. Arthur L. Stauch, Fire Chief Ann Arbor City Fire Dept. 219 E. Huron Ann Arbor, Mi. 48108

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

NAME Washtenaw County Vocational Residential Center		TYPE OF FACILITY		
ADDRESS (NUMBER AND STREET) 2260 Platt Road	esidential Center	1. Day Nursery: Full-Time Proposed Part-Time Capacity		
CITY Ann Arbor	ZIP CODE 48104	2. K Child-Caring Inst.: County Private Secure Custody		
COUNTY Washtenaw CONTACT Mr. Tim Walters		3. Group Home: County Private		
TELEPHONE - (AREA) (NUMB 313 971-78		4. Camps: Residential Day		
SPECIAL INSTRUCTIONS		STATUS Proposed Relocation Addition Annual Inspection Reinspection		
		DATE REPORT DUE April 1, 1972		

- 2. Please mail a second copy of your findings and recommendations to:

NAME James H. Kinkema, Licens State Department of Social Ser	sing Consultant Vices	
ADDRESSKalamazoo Field Office 426-28 West South Street	CITY	ZIP CODE
Kalamazoo, Michigan 49006		



March 5, 1974

Mr. Robert Bee, Consultant State of Michigan Dept. of Social Services 32500 Dolly Madison Dr. #230 Madison Heights, MI 48071

Re: 2260 Platt Rd.

Dear Sir:

An inspection made this date revealed conditions to be satisfactory for the purpose of relicensing for the coming year.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Burea

CJO/dw

cc - Ms. Marlys Schutjer, Director 2260 Platt Rd., Ann Arbor March 5, 1974

Ms. Martys Schutjer, Director Washtenaw County Vocational Residential Center 2260 Platt Rd. Ann Arbor, Michigan 48104

Re: Approval

Dear Ms. Schutjer:

Enclosed please find the letter of approval to social services.

Please be advised that this is with the understanding that the padlocks be removed from the doors and that smoking be restricted to designated areas.

If there are any questions please feel free to contact this office.

Cordially,

Charles J. Osborn Fire Inspector Fire Prevention Bureau

CJO/dw

STATE OF MICHIGAN





WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

FROM: Robert Bee

Oak Park, MI 48237

DATE 2-28-74
Robert Bee FILE#
Div. of Child Welfare Lic.
13730 W. Eight Mile Road


To: City of Ann Arbor Fire Dept. Fire Prevention Bureau 219 E. Huron Ann Arbor, MI 48108

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

NAME	TYPE OF FACILITY
Washtenaw Co. Vocational Residential Center ADDRESS (NUMBER AND STREET) 2260 Platt Road	1. Day Nursery: Full-Time Proposed Capacity
Ann Arbor 48104	2. X Child-Caring Inst.: X County Secure Custody Den
Washtenaw CONTACT	3. Group Home: County Private
Ms. Marlys Schutjer, Director TELEPHONE (AREA) (NUMBER) 313 971-7870	4. Camps: Residential Day
SPECIAL INSTRUCTIONS Cap: 12 children	STATUS Proposed Relocation Addition Annual Inspection Reinspection
Please send a copy of your findings and recommendations	As soon as possible to this office at the address given above and inform us if the

- facility meets with your approval.
- 2. Please mail a second copy of your findings and recommendations to:





WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

John T. Dempsey, Director

Provider No.:	
Bee of Child Welfare Licensing State Plaza-Suite 1180	

Date: <u>9-23-75</u>

219 E. Huron Street

Fire Inspection Bureau

Charles J. Osborn

TO:

Ann Arbor, Michigan 48108

City of Ann Arbor Fire Department

1200 Sixth Street Detroit, Michigan 48226 256-3714

Robert E.

Division

Michigan

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act No. 116, P.A. 1973, it is the responsibility of this Department to regulate all child care facilities prior to initial operation and periodically thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children.

FROM:

We appreciate your help and thank you for your cooperation.

NAME OF ORGANIZATION				
Washtenaw County Vocational Residential Center		TYPE OF FACILITY		
ADDRESS (Number and Street) 2260 Platt Road		1. Child Care Center	Part - Time	Proposed Capacity:
Ann Arbor	48104	2. Child-Caring Institutions	Public D	Secure Custody Open
COUNTY Wash tenaw		3. ☐ Foster Family	1-	•
CONTACT Marlys Schutzer		4. Group Day Ca		
	mber) -7870	−5. Camps	Residential	☐ Day
SPECIAL INSTRUCTIONS	<u> </u>	STATUS		· · · · · · · · · · · · · · · · · · ·
		Proposed	Relocation	Addition
		Renewal Insp	ection	Reinspection
		As soon as	possible	

- 1. Please send your findings and recommendations to this office at the address given above and inform us if the facility meets with your approval.
- 2. Please mail a copy of your findings and recommendations to the child care facility as indicated:

NAME		
Marlys Schutzer		
ADDRESS	CITY	ZIP CODE
Washtenaw County Vocational	2260 Platt Rd., Ann Arbor	48104



DSS-3627 (Rev. 10-74) Previous editions obsolete.

Address 2270 Platt Rd		*	7730 Th	Capacity
	AŅN A	ARBOR FIF	RE DEPARTMEN	iΤ
	Fire	Preventio	n Code Permit	
	Chapter III	Title IX	Ann Arbor	City Code
Date Issued10-28-93			Expiration Date	10-28-95
Issued To Washtenaw	County Juvenil	e Detenti	on	
Use and Activity1-3	(Institution)		
times kept on the premises are not transferable and an revoke a permit or approval	designated therein a y change in use, op l issued under the p have been violated,	and shall be eration or ter rovisions of t or if there ha	in all times subject nancy shall require a his code if upon ins is been any false st	led in this code. Permits shall be at all to inspection by the Fire Official. Permits a new permit. The Fire Official may pection any violation of the code exists, atement or misrepresentation as to the was based.
Issued By:	- Still freeze		Den	nis W. Hasley, Fire Marshal

ANN ARBC Type Inspection Fire 343	7
2660 Plat Ka.	Occupied by Detention Home
Stories Construction ABSOLICY Weshtenaw County	Executive official Additional Security
1 1	
BUILDING	Nights IZZ odera occupANCY
Has bidg. fire walls? Yes openings protected?	Houberteping Fair (If poor, give details) Fair M. C.
automatic self-closing manual manual Are all other	
Do all doors and gates operate properly?	Is elevator pit clean
Are all other floor openings,	Kinds and amounts of inflammable liquids handled?
Are all stairwell fire at time of inspection?	
Number of exits Main Leach floor?	How and where stored?
	Storage of Combustibles
Are exits properly Yes maintained?	
Ves H not,	Permit?
Are exits adequate?	Any special hazards (material detrimental to firemen)? Give details
Type	
Do floors appear overloaded?floors?	
What is means of access to roof?	Is smoking permitted? Yes When and where? Office only
Was roof opening unlocked?	And free in by by comment
7	
Condition of heating apparatus, including smoke pipes, heat ducts, etc. (if defective, describe) I BID	Location of welding and cutting operations
	Any acetylene apparatus?
Condition of electrical Wiring? (If defective, explain) Fair	Ventilating system? In the the tenditioning?
	Condition of plenum chambers?
General condition of building (structurally)? Pair	
To see a second	

FIRE PROTECTION	
Is there a No Wet Dry	Conditions referred to other Departments?
capacity of each?	
Were control	
Are control valves	B
reddily decessions:	found, interviewed Title
inkler distribution	Notice Noissued as follows:
obstructed at any point?	
Ability I in a	
Condition of Course Fire Dept. connection?	With Actontion swatem typolich out Building
Has bidg. a NO Wet Ory	
Source of supply	
36	Night Couple.
on standpipe?	Kaloh + Denny Kucher
Can Fire Dept. Use	(0 #,/0
inquishers 5# co2 in kitchen area	7.260 11411 1151
3	
1	
14pt 69	
the one	
vice	
other than on standpipe?	
Condition of hose?	
Outline procedure for notitying	
	Time required to make interaction: 15 min

FIRE OR EXPLOSION

The first obligation of detention staff is to <u>prevent the onset of fire</u> by careful supervision and safety precautions. However, if a fire does occur, the following procedures should be followed.

- I. A verbal alert should be given to other staff and the supervisor or designated person in charge. Do not attend to the fire before giving an alert. The alarm should be triggered.
- II. Immediately begin moving youngsters to a part of the building or grounds away from the fire and smoke area. At least one staff should remain at all times with youngsters. As you leave the endangered areas, make sure that all of the youngsters are out and close doors behind you to retard the spread of flames. Depending on the size and seriousness of the fire, the youngsters should be moved:
 - A. First, to another part of the secure detention area away from the fire.
 - B. Second, to a non-secure area of detention (chapel, front hall).
 - C. Third, outside in the recreation yard.
 - D. Forth, outside to the court parking lot, if inclement weather exists, to the vocational center.
- III. Call the fire department as soon as youngsters are safe.
 - IV. Call the Superintendent and the Assistant Superintendent.
 - V. After youngsters have been moved to safety, staff, if appropriate, should attempt to contain the fire by closing doors and using fire extinguishers. The fire extinguishers are located:
 - A. Control Station (1 class BC) (1 water)
 - B. Kitchen (1 class ABC) (1 class BC)
 - C. Shop (1 class BC) (1 water)
 - D. Incinerator Room (1 class BC)
 - E. Court side of building 1 each in East-West hall (water)
 - VI. All youngsters should be accounted for. $^{\wedge}$ If any youngsters have run away, initiate the Notification Policy for runaways.
- VII. Before re-occupying an area of detention where there has been a fire, the area should be fully clear of smoke. REQUIRE PERMISSION OF THE OFFICER IN CHARGE PERMISSION OF THE OFFICER
- VIII. After each fire, each staff member should submit a written Incident Report, describing their activity during the incident.
 - IX. EMERGENCY NUMBERS
 - A. Ann Arbor Fire Department911
 - B. Ann Arbor Police Department911

BOMB THREATS

When a bomb threat is received by telephone the following procedure should be executed:

Ask for as much information as possible. Such as, where the bomb is located, what time it is set to detonate, what kind of package it is wrapped in. Give an alert to a second staff member that a bomb threat call is being received. Continue the call and obtain as much information about the bomb and caller as possible (i.e. materials used in bomb construction, color of bomb, package or container, time mechanism, why the person placed the bomb, the person's identiy, etc.).

The second staff person immediately should begin to move youths away from area of the bomb. When the <u>location of the bomb is known</u>, youths should be moved to either girls or boys wing, the one furthest away from the bomb. The wings should be clear checked for any strange objects by staff first and then by youths again as they are being moved. If a bomb or strange object is found in the wing area, dayroom area or classroom area, youths should be moved to the pen. If a bomb or strange object is found in the gymnasium, mud room, or basement area, youths should be moved to the chapel. If a bomb or strange object is identified, staff or youths SHOULD NOT TOUCH THE OBJECT.

When the location of the bomb is not known, youths should be moved to the wing areas. The wings should be clear checked by staff and again by youths and the sleeping rooms should each be checked by staff and youths. When youths have been secured in their sleeping quarters, staff should begin an inspection of other areas of the building for strange objects.

As soon as youths have been moved to a wing area, the pen, the chapel, or outside the building, the Ann Arbor Police - 911 Emergency Number - should be notified.

Staff should remain in the wing area with the youths. The person in charge should check for objects in other areas of the building and greet the police and escort the police on a search of the building. When a search has been completed and neither staff nor police have found any strange object or bombs, the person in charge may direct the return to cleared areas.

If an object is found, the person in charge should arrange to have youths moved again as necessary to an area furthest away from the bomb.

A complete Incident Report should be prepared by each staff person working during the shift. The report should be prepared after the incident is over and all youths are accounted for by <u>each</u> staff member on duty.

All windows should be left open during a <u>bomb threat</u> procedure. Open windows permit the escape of pressure caused by an explosion. The opposite procedure should be utilized in the case of fire. All <u>windows</u> and doors should be <u>closed</u> to retard the spread of <u>fire</u>.

MEDICAL

When a detained youth reports or displays a physical ailment that includes pain, bleeding, or any impairment of physical functioning, (i.e. loss of muscle control, blurred vision, inhibited breathing, etc.) the person in charge should procede as follows:

- 1. Call the doctor designated as on call. The number is located in the Medical Office on the bulletin board.
- 2. If recommended by the doctor or if physical problem is severe and immediate call HORNE-VINSON AMBULANCE 769-6221. Have youth transported to the hospital.
- 3. If hospital visitation is recommended by doctor, but physical problem is not severe or immediate, the person in charge will designate a youth counselor to transport youth to the hospital. A counselor may utilize taxi service and will be reimbursed for taxi expenses or mileage in personal vehicle.
- 4. An Incident Report should be completed each time a youth is transported to the hospital. The report should contain information including time of original complaint, doctor called, doctor's recommendation, counselor designated to accompany youth to hospital, result of hospital visit, and all other information relevant to the circumstances.

TORNADO

When a tornado <u>watch</u> is indicated for this geographical area, the person in charge should dial a radio to the weather alert station _____ and monitor broadcasts regarding the possible tornado.

When a tornado <u>warning</u> is indicated for this geographical area, the person in charge should move youths and staff to the gymnasium. The southwest corner of the gym is the area most safe during a tornado. Youths should remain in the gymnasium until the warning has been retracted.

PHYSICAL PLANT MALFUNCTION

When an emergent malfunction in one of the building systems occurs (i.e. flooding, loss of heat, electricity or water) the twenty-four hour EMERGENCY MAINTENANCE NUMBER - 994-2498 - should be called and a superintendent should be notified.

726	77 1.0.	Occupied by COUNTY E.C. WITE
Stories Construction Bldg. owned by $14/45 H T \epsilon R$	1 8 3	Executive official TAME PERIOR TRA
	BUILDING	OCCUPANCY
Has bida. fire walls?	Are fire wall openings protected?	Housekeeping (If poor, give details)
Fire wall doors are: automatic		
Are all fire wall	Are all other fire doors operative?	
elevator shafts	ies 🗡	is elevator
		Kinds and amounts of NONE
Including stairways, protected Are all stairwell fire	Were they closed X 5	
T T	•	How and where stored?
eden noor		Storage of Combustibles 64846 5 COULD STATE
N .	Are exits properly	
	4 SCA	Ç::a
ALWAYS LOCKED		Any special hazards Any special hazards freemen)? Give details 130/L F.R ROOM
		- 3 STEPS DOWN FROM MAIN FLOOR
Revolving Doors? Do floors appear	Type Operative? What	
overloaded?	floors?	
access to roof?		When and where? Any
Was roof opening unlocked?	Hot Water	EXEPCT IN DORMS AND DISMING KOSMI
Condition of heating apparatus, including smoke pipes, heat ducts, etc. (if defective, describe).	a describe)	Location of welding and cutting operations
\		Any acetylene apparatus?
wiring? (If defective, explain)	7	Ventilating system? // KITC / Air conditioning?
		Condition of plenum chambers?
(Alautanta) act.	ON CK	

4		_
5	2	-
	•	
٩	н	•
e	ř	
ı	٠.	•
٦	7	_
1	L	3
3		
ı	и	
1		-
ı	F	
ı	-	
ı	г	7
3	٠	٠.
1	ø	•
ŧ	۰	
1		ட
1	-	•
ł		м
ľ	Ξ	- 2
1		ĸ
ĺ	Ξ	≃
	=	_
	ы	

FIRE PROJECTOR	
sprinkler system? // Wet Dry	Conditions referred to other Departments?
Sources of supply and capacity of each?	
Were control	
vives com:	
readily accessible?	Regarding violations Title
Is sprinkler distribution	Notice No issued as follows:
obstructed at any point?	, , , , , , , , , , , , , , , , , , ,
Condition of ourside PLATT + WISSHIEW	HAL BUILDING HAIS MARKED
	Syst m
Has bidg. a Wet Dry	
standpipe system: Source of supply	FXTINGOSPICO NETO TO TO TOTAL
and capacity?	C.7
on standings of hose?	ALC NEW
5-45 COD IN 10316 16 16 10 10 10 10 10 10 10 10 10 10 10 10 10	
2.0 COD 14 WILLIAM 15-13 COD IN CLOSE	
M LARTHURES APT. COS IN CLOSET	
100 S 100	
Lost service x / / / / Antimuisher?	
type of hose	
other than on standpipe?	
Condition of hose? Outline procedure for notifying	
fire Dept. in case of nre:	
	CARRATO
	CONDITION
	Time required to make inspection: / MQ
	W. Thory

Feb-22-00 12:52PM;



Sent By: State of Michigan;

State of Michigan John Engler, Governor

Department of Consumer & Industry Services Kathleen M. Wilbur, Director

Page 1 of 1 OFS-40 Office of Fire Safety General Office Building 7150 Harris Drive Lansing, MI 48909-7504

FACILITY NAME Washtenaw County Juvenile Detention	DATE 2/15/2000	COUNTY Washtenaw	PROJECT 1430-99
ADDRESS 2270 Platt Road	FACILITY TYPE School	RULES/CODES School Rules	JOB/LIC/FAC. NO.
CITY, STATE ZIP CODE Ann Arbor, MI 48104	FACILITY REPRESE Tony V. Savo		INSPECTION TYPE Re-Check Final

AREAS REQUIRING COMPLIANCE:

RE: Remodeling of relocatable classroom space

A final fire safety inspection of the above captioned project was completed this date. Deficiencies noted in our prior inspection reports have been satisfactorily corrected. This report may be considered as final approval of this project.

Metro Group Architects Fax 734-747-9111

Anthony V. Savoni Fax 734-971-5085

Judy Kramer Fax 734-994-2592

Ann Arbor FD

FIRE SAFETY CERTIFICATION		PROJECT STATUS	REVIEWED BY	
Approved	approved			
DISTRIBUTION Facility File CIS/HQ	Inspecting official Jon Curtis SIGNATURE OF OFFICIAL	ADDRESS TELEPHONE	24155 Drake Rd Farmington, MI 48335 248.888.8767 FAX 248-888-8760	

eu - 5/12/70	1. COUNTY	2. DATE OF REPORT	3. STATE POLICE FILE NO. FIL
O(Rev. 1-70) Department of State Police	Washteney	April 29, 1970	20-921-69 4
FIRE SAFETY	4. TOWNSHIP	5. DATE OF ORIGINAL REPORT	6. (a) FIRST INSPECTION
INSPECTION REPORT		September 25, 1969 9. PLAN REVIEW JOB NUMBER	(b) FINAL INSPECTION
OST, DISTRICT, DIVISION OR BUREAU	8. CITY OR VILLAGE	F-110-67 6608-12	(c) RECHECK
M District, 12 troit	Ann Arbor	11.FOR FM OFFICE USE ONLY	(d) ANNUAL INSPECTION
Juvenile Court Genter			
(a) NAME OF FACILITY	tenaw Jovenile Cour	t Genter	
(b) ADDRESS 2270	Platt, App Arbor		
(c) CONTACTED (d) NEW EXISTING	Folts. Administrate	TEMPORARY REMODELING	MOBILE UNIT
THE ABOVE NAMED FACILITY WAS INS			
(a) (PRELIMINARY) (FINAL)	APPROVAL IS GRANTED.	(b) S DISAPPROVED (see	
(c) IS APPROVED FOR TEMPORARY	USE UNTIL	. (d) PARTIAL OCCUPANCY	(see number 16 below).
(e) REQUIRES COMPLIANCE WITH	THE RECOMMENDATIONS LISTER	J IN SECTION NUMBER TO BELOW.	
ORIGIN: ADDRESS			
RECEIVED BY		NSPECTING OFFICER(S)	and Det. Johnson
DISTRIBUTION		2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	as Count tanks
Earl Ves Alleberg, Det	rerman Associatos,	Fandemberg Center, 200 Hours , Lewis Case Building, 4th	Tigor, Lengths
Vacablese County Probe	s of another country C	ourt Nouse. Ass Arbor	
Pire Mershel. Ass Arbo	or Pire Department.	219 E. Huron, Ann Arbor	
department by note	ed structural steel for a minimum of on erised effidevit fr	25, 1969. in Storage B-7 with an app e (1) hour. (Repeated) Al on the supplier and the ine t time for some steel prote	so supply this
3. Protect the expose vill resist fire department by note that the material resistance rating laboratories, or 6. Provide proof to	ed structural steel for a minimum of on erised effidewit fr used at the presen of at least one () an independent test	in Storage B-7 with an app e (1) hour. (Repeated) Al- on the supplier and the ins t time for some steel prote) hour as determined by Und ing laboratory.	so supply this staller streating setion has a fire servritors'
3. Protect the expose will resist fire a department by note that the material resistance rating Laboratories, or a 6. Provide proof to installed in Chap	ed structural steel for a minimum of on erised effidevit fr used at the presen of at least one (1 am independent test this Department by el 9 is no more has	in Storage 3-7 with an app e (1) hour. (Repeated) Al- on the supplier and the ins t time for some steel prote) hour as determined by Und- ing laboratory. notorized effidavit that the ardown than Class "A" as re-	so supply this staller attenting sction has a fire servritors' se wood paneling squired by Rule 20
3. Protect the expose will resist fire a department by note that the material resistance rating Laboratories, or a 6. Provide proof to installed in Chap	ed structural steel for a minimum of on erised effidevit fr used at the presen of at least one (1 am independent test this Department by el 9 is no more has	in Storage B-7 with an app e (1) hour. (Repeated) Al- on the supplier and the ins t time for some steel prote) hour as determined by Und ing laboratory.	so supply this staller attesting sction has a fire servritors'
3. Protect the expose viil resist fire a department by note that the material resistance rating Laboratories, or a 6. Provide proof to installed in Chap of the Hospital as with.	ed structural steel for a minimum of on erised effidevit fr used at the presen of at least one (1 an independent test this Department by el 9 is no more has nd institution legu	in Storage 3-7 with an app e (1) hour. (Repeated) Al- on the supplier and the ine t time for some steel prote) hour as determined by Und- ing laboratory. notorized effidavit that the ardown than Class "A" as re-	sc supply this staller streating setion has a fire servritors' se wood peneling squired by Rule 20 set been complied
3. Protect the expose vill resist fire of department by note that the material resistance rating Laboratories, or of 6. Provide proof to installed in Chap of the Hospital and with. 7. Provide this Department	for a minimum of one erised effidewit from used at the present of at least one () an independent test this Department by el 9 is no more has no institution Regularithm a notar	in Storage B-7 with an app e (1) hour. (Repeated) Al- ce the supplier and the ins t time for some steel prote) hour as determined by Und- ing laboratory. motorized efficient that the ardows than Class "A" as re- letions. (Repeated) Has a	sc supply this taller streating ection has a fire ervritors' e wood paneling equired by Rule 20 not been complied
3. Protect the expose will resist fire i department by note that the material resistance rating Laboratories, or i 6. Provide proof to installed in Chap of the Hospital as with. 7. Provide this Department applier attesting	for a minimum of one erised effidevit from used at the present of at least one () an independent test this Department by el 9 is no more has no limitation Regulation	in Storage 3-7 with an app e (1) hour. (Repeated) Al on the supplier and the ine t time for some steel prote) hour as determined by Und ing laboratory. motorized effidavit that th ardous than Class "A" as re lations. (Repeated) Has t	so supply this taller streeting ction has a fire envritors' e wood paneling quired by Rule 20 not been complied building is either
3. Protect the expose will resist fire a department by note that the material resistance rating Laboratories, or a 6. Provide proof to a installed in Chap of the Hospital ac with. 7. Provide this Department applies attesting applied under 8 m	ed structural steel for a minimum of on arised effidevit from used at the present of at least one (lan independent test this Department by al. 9 is no more has not institution Regulation Regulation that all the place dis thickness or is	in Storage 3-7 with an app e (1) hour. (Repeated) Al on the supplier and the ine t time for some steel prote) hour as determined by Und ing laboratory. notarized efficient that th ardown than Class "A" as re lations. (Repeated) Has a listions. (Repeated) Has a	so supply this staller attesting setion has a fire servritors' se wood paneling squired by Rule 20 not been couplied so supplier and shullding is either
3. Protect the exposes will resist fire is department by note that the material resistance rating Laboratories, or is 6. Previde proof to installed in Chap of the Hospital an with. 7. Provide this Department applies attenting applied under 8 an with Rule 20 of to been couplied with	ed structural steel for a minimum of on erised effidevit from used at the present of at least one (least one (least one this Department by el 9 is no more has not institution Regulation Regulation that all the place its thickness or is the Nospital and Institution of its thickness or is the Nospital and Institution Regulated	in Storage 3-7 with an app e (1) hour. (Repeated) Al on the supplier and the ine t time for some steel prote) hour as determined by Und ing laboratory. motorized effidavit that th ardous than Class "A" as re lations. (Repeated) Hes to the well finish used to this no more benerious than Cla	sc supply this taller streating ction has a fire critical crit
3. Protect the exposes will resist fire a department by note that the material resistance rating Laboratories, or a 6. Provide proof to installed in Chap of the Hospital as with. 7. Provide this Department applies ettesting applied under 8 as with fluie 20 of the stalled in the second contents of the secon	ed structural steel for a minimum of on erised effidevit from used at the present of at least one (least one (least one this Department by el 9 is no more has not institution Regulation Regulation that all the place its thickness or is the Nospital and Institution of its thickness or is the Nospital and Institution Regulated	in Storage 3-7 with an app e (1) hour. (Repeated) Al on the supplier and the ine t time for some steel prote) hour as determined by Und ing laboratory. motorized effidavit that th ardous than Class "A" as re lations. (Repeated) Hes to the well finish used to this no more benerious than Cla	so supply this staller attesting stice has a fire servritors' se wood paneling squired by Rule 20 not been couplied se supplier and shullding is either

20-921	_60	4.5		April 29, 1970
. Provide approv	ed fire dampers	in all ducts t	hat pierce the	wells and coiling
				sted Japuery 8, 1968.
•				
(Repeated) De	repers have been	installed exce	pt for the eath	oust fon which will
still require	a fire damper.			
	_			
			- ·- -	-

			3. STATE POLICE FILE NO. FIL
-40B(1-70)	1. COUNTY	2. DATE OF REPORT April 10, 1973	3. STATE POLICE FILE NO. FIL CLAS
Department of State Police FIRE SAFETY	Vest tensy 4. TOWNSHIP	5. DATE OF ORIGINAL REPORT	6.
INSPECTION REPORT	H. IOWINGEIF	September 25, 1969	(a) FIRST INSPECTION
POST, DISTRICT, DIVISION OR BUREAU	8. CITY OR VILLAGE	9. PLAN REVIEW JOB NUMBER	(b) FINAL INSPECTION
re Marahal Div. Bdqts.	Ann Arbor	11. FOR FM OFFICE USE ONLY	(c) RECHECK
TYPE OF FACILITY		111 011 111 111 111	(d) ANNUAL INSPECTION
ildrene Residential Car	b Facility	* Contain	
	onem Juvenile Cour		
(b) ADDRESS	Plate Rd., Am Arb	er, nices gan	
	O'Brien & Eras Be	TEMPORARY REMODELING	MOBILE UNIT
(d NEW EXISTING	ADDITION	TEMPORARY REMODELING	
FIRE SAFETY CERTIFICATION.			
(a) The above named facility is in s	atisfactory compliance with th	ne fire safety requirements, therefore, is certif	ied July 13, 19
(b The above named facility does n	ot fully meet the fire safety re	equirements, however, temporary certification i	s granted until
(c) The above named facility is not	in acceptable compliance with	n the fire safety requirements, therefore, is not	certified (See number 16 below)
ORIGIN:	A A A A A A A A A A A A A A A A A A A		
ADDRESS RECEIVED BY	IN	SPECTING OFFICER(S)	
DISTRIBUTION TO THE PARTY CO	enty Probata Judge	, County Court House, Ame A	rber, Mishigan
re Marchal, Ann Arber I	ire Dept., 219 E.	Muron, Ann Arber	
sek H. Tarnetra, Daverne	n Associates. Ven	lenberg Center, 200 Mearce,	Grand Repids 49302
est Terretra, Jureau of	Social Services,	Lewis Case Bldg., 4th Floor	, Landing, Mich.
. Rese. Fire Marchal Bi	vision, 24870 Gran	od River, Michigan State Pol	ice, Detroit
Certification cannot b	e extended beyond	July 13, 1973 unless Item #	1 as listed
en our report dated N	Bruary 26, 1973 h	es been complied with.	
en our report dated fo	Bruary 26, 1973 h	se been complied with.	
ea our report dated 70	Bruary 26, 1973 h	se been complied with.	
en our report dated Fe	Brusry 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	se been complied with.	
en our report dated 76	Brusry 26, 1973 h	se been complied with.	
en our report dated Fe	Brusry 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	ee been complied with.	
ea our report dated Fe	Bruary 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	es been complied with.	
en our report dated Fe	Bruary 26, 1973 h	es been complied with.	
on our report dated Fe	Bruary 26, 1973 h	es been complied with.	
on our report dated Fe	Bruary 26, 1973 h	ee been complied with.	
en our report dated N	bruary 26, 1973 h	ee been complied with.	
en our report dated N	Bruary 26, 1973 h	es been complied with.	
es our report dated N	Bruary 26, 1973 b	es been complied with.	
es our report dated N	Bruary 26, 1973 b	es been complied with.	
en our report dated N	Bruary 26, 1973 b	es been camplied with.	
en our report dated N	Bruary 26, 1973 h	es been complied with.	
es our report dated N	Bruery 26, 1973 h	ee been complied with.	
en our report dated N	Bruary 26, 1973 b	es been complied with.	
en our report dated N	Bruary 26, 1973 b	es been complied with.	
es our report dated N	Druary 26, 1973 b	es been complied with.	
es our report dated N	Drusry 26, 1973 b	es been complied with.	
en our report dated N	Bruary 26, 1973 b	es been complied with.	
en our report dated N	Brusry 36, 1973 b	es been complied with.	
en our report dated N	Devery 26, 2973 b	es been complied with.	
** REPORTING OFFICER'S SIGNATURE			19. REVIEWING OFFICER
		lyde A. Harquardt	19. REVIEWING OFFICER

3-7-73-p			2 STATE POLICE FILE NO FIL
-408(1-70)	1. COUNTY	2. DATE OF REPORT	CLA
Department of State Police	Washtenaw	February 26 & 27, 1973 5. DATE OF ORIGINAL REPORT	2 0-921-09 4.5
FIRE SAFETY INSPECTION REPORT	4. TOWNSHIP	September 25, 1969	(a) FIRST INSPECTION
POST, DISTRICT, DIVISION OR BUREAU	8, CITY OR VILLAGE	9. PLAN REVIEW JOB NUMBER	(b) FINAL INSPECTION
_		F-110-67 6608-12	(c) RECHECK
Div. Detroit, SP/20 TYPE OF FACILITY	Ann Arbor	11. FOR FM OFFICE USE ONLY	
			(d) ANNUAL INSPECTION
venile Court Center (a) NAME OF FACILITY Washto	enaw Juvenile Court	Center	
	Platt Rd., Ann Arbo		
	11 - Maintenance		
(d) NEW EXISTING		TEMPORÄRY REMODELING	MOBILE UNIT
FIRE SAFETY CERTIFICATION.			
(a) The above named facility is in	satisfactory compliance with the	fire safety requirements, therefore, is certified	1.
b) The above named facility does i	not fully meet the fire safety req	uirements, however, temporary certification is	granted until 4-13-73
c) The above named facility is not	in acceptable compliance with	the fire safety requirements, therefore, is not c	ertified.(See number 16 below)
ODIO!NI			
ORIGIN: ADDRESS			
RECEIVED BY	INS	SPECTING OFFICER(S) Det/Set. John	D. MacDougall
DISTRIBUTION			
shteney County Probate	Judge, County Cour	t House, Ann Arbor, Michigan	
re Mershel. Ann Arbor	Fire Diot. 219 E.	Huron, Ann Arbor, Michigan	
at M. Tarnetre, Dever	en Aceseistes. Vand	lanbarg Center. 200 Monroe. G	rand Rapids 49502
cob Ternatra. Bureau o	f Social Services.	Lewis Cass Building, 4th Flo	or, Lansing, Mich.
minimum of one December 3rd of		i from our letters dated Apri	il 29th and
Please advise i	in writing your into	ent to comply with the above	mentioned item
within ten (10)	days.		
S. 188	1 2 4 7	gradient gradient gewond de	the second second
REPORTING OFFICER'S SIGNATURE	John	Mac Dougall, Det/Sergeant	19. REVIEWING OFFICER
STATION AND ADDRESS	04070 01 74	Detroit, Michigan 48129	[] FILE CLOSED
	ZAKZU GTANG KIVAT.	DEFECT WISHINGH GOLAY	1

			3. STATE POLICE FILE NO. FIL
40(Rev. 1-70) Department of State Police	1. COUNTY Washtenaw	2. DATE OF REPORT December 3, 1970	3. STATE POLICE FILE NO. FIL CLA 20-921-69 4
FIRE SAFETY	4. TOWNSHIP	5. DATE OF ORIGINAL REPORT	6.
INSPECTION REPORT		September 25, 1969	(a) FIRST INSPECTION
OST, DISTRICT, DIVISION OR BUREAU	8. CITY OR VILLAGE	9. PLAN REVIEW JOB NUMBER	(b) FINAL INSPECTION
Div. Detroit SP/20	Ann Arbor	F-110-67 6608-12	(c) RECHECK
TYPE OF FACILITY		TILFOR FM OFFICE USE UNLY	(d) ANNUAL INSPECTION
venile Court Center	man Juvenile Court	Center	
V=1	Tatt Rd., Ann Arbor		
	itz - Adm.	, · · · · · · · · · · · · · · · · · · ·	
(d) NEW EXISTING		TEMPORARY REMODELING	MOBILE UNIT
THE ABOVE NAMED FACILITY WAS INS	PECTED, AND		
(a) (PRELIMINARY) (FINAL)	APPROVAL IS GRANTED.	(b) IS DISAPPROVED (see	
		. (d) PARTIAL OCCUPANC	(see number 16 below).
(e) REQUIRES COMPLIANCE WITH	THE RECOMMENDATIONS LISTED	IN SECTION NUMBER TO BELOW.	
ORIGIN: ADDRESS			
RECEIVED BY	IN	ISPECTING OFFICER(S) Det. Hinds	& Det. Mac Dougall
DISTRIBUTION			
rl Van Allsburg, Davers	manAssociates, Vande	nberg Center, 200 Monroe,	Grand Rapids
		Lewis Cass Bldg., 4th Floo	r, Lansing
ashtensw County Probate	Ann Amban Fine Dec	ertment, 219 E. Huron, Ann	Arhar
THE METSHET, AND AFDOY,	ABII AFOOT TITE DEP	er Chenc, 219 C. Heron, And	A WOT
structural steel beam	in storage room "B-	7", with an approved mater	tal, which will
structural steel beam resist fire for a mini			tal, which will
			dal, which will
			ial, which will
			tal, which will
			dal, which will
			tal, which will
			dal, which will
			ial, which will
			tal, which will
			dal, which will
<u> </u>			dal, which will
<u> </u>			tal, which will
			dal, which will
resist fire for a mini	Image of one (1) hour		19. REVIEWING OFFICER
	Image of one (1) hour		

DW -	10/15/69		2. TOWNSHIP	3. STATE POLICE FILE
M-40(11-68)		1. COUNTY	2. TOWNSHIP	20-921-69
MICHIGAN	STATE POLICE	4. CITY	5. VILLAGE	6. FILE CLASS
	E SAFETY	Ann Arbor		4.5
	TION REPORT	7. PLAN NUMBER	8. DATE PLANS REVIEWED	9. FIRST RECHECK FINAL FORMAL ORDERS
	DIVISION OR BUREAU	11. ORIGINAL DATE	12. DATE OF SUPP. RPT.	13. TYPE OF FACILITY
and District	Mdetrs Detroi	£ 9/25/69		Juy. Court Center
	For I Van Albahar	a. Davermen Associati	Opend Bonddo A9502	
Address	Vandenberg Cente	r, 200 Mosroe, N.W.,	cer(s) Det, Arnold &. Jo	hiseon
Received by	3/34t BUORIC IND			
Contacted	Robert Paul			
Name of Facility	Washtean J	uvenile Court Center		
		Road, Ama Arbor, Mic		
	ING ADDITION	MOBILE TEMPORARY	REMODELING	
				conditionally approved
. The above listed	facility was inspected, and	is approved and disappro	ved is approved for temporary usone recommendations listed in section n	o. 18 below
1.			licate of electrical appropriate and electrical electri	
2.	Provide approved	fire extinguishers	throughout this facility	y in accordance with
	Rule 19 of the H	ospital and Institut:	ion Regulatione, also c	herge and tag with
	the date of serv	ico.		
3.	Complete the ins	telletion of the rol	ling steel curtain in K	itehen 78 so that
		oke tight installation		
4.	Fill spaces arou	nd pipes in upper Te	s Room P-1 with a mater	iel that will remist
	fire for one (1)	hour.		
5.	Protect the expo	eed structural steel	in Storage 3-7 with an	approved meterial
	that will resist	fire for a minimum	of one (1)hour.	
6.	Provide proof to	this Department by	noterised affidevit the	t the wood peneling
- T			ardous then Class A as	
9. Reporting office	er sign	A A- A	Rank	20. Reviewing Officer Initial
Arno	old R. Johnson		Detective	21. FILE CLOSED
Station and address	t of State Police	e. 24870 Grand River	Detroit 48219	Service Rendered

4-40 A(11-68)	ADDITIONAL INSPECTION REPORT			
E NO.	FILE NO. 20-921-69	FILE CLASS	9/25/69	
	of the hospital and inc	etitution Resulations.		
**			s from both the supplier and	
7.				
			h used in this building is	
	either applied under 8	mils thickness or is so me	ere heserdous thee Class A"	
	in accordance with Rule	e 20 of the Mospital and la	etitution Regulations.	
8.	Install approved door	closers for Doors B-13, B-1	14 and B-15.	
9.	Adjust the door closer	for Door 11 to Chapel 9 so	that it will close	
	automatically.			
10.	Provide approved fire	dampers in all ducts that	pierce the wells and ceiling	
			our firm deted January 8, 1968.	
	Or Languagy / O dis Indian			
			- 2000 - 4000-0-	
	-			

CONTRACTOR'S MATERIAL AND TEST CERTIFICATE SPRINKLER SYSTEMS — WATER SPRAY SYSTEMS

Part "A" General

PROCEDURE

Upon completion of work, inspection and tests should be made by the contractor's representative and witnessed by an owner's representative. All defects should be corrected and system left in service before contractor's men finally leave the job.

A certificate should be filled out and signed by both representatives. Copies should be prepared for inspecting authorities, owner, and contractor. It is inderstood the owner's representative's signature in no way prejudices any claim against contractor for faulty material, poor workmanship, or failure to comply with inspecting authority's requirements or local ordinances.

Property name The Mark Court Date Court D

Property address		· · · · · · · · · · · · · · · · · · ·
PLANS Accepted by inspection authority(s) names	92 FIRE I	DEPT.
Address		
Installation conforms to accepted plans:	Yes 🔀	No 🗆
Equipment used is approved	Yes 🗌	No 🗆

If no. state deviations.....

INSTRUCTIONS

das person in charge of fire equipment been instructed as to location of control valves and care of this new equipment?	Yes	N)	No	
f no, explain		•••••		
Has a copy of instruction and maintenance chart seen left at plant?	Yes		No	
't an amulain				

TEST DESCRIPTION

Flushing: Flow the required rate until mains are clear as indicated by no collection of foreign material in burlap bags at outlets such as hydrants and blow-offs.

Flush at flows not less than 750 GPM for 6-inch pipe and smaller, 1,000 GPM for 8-inch pipe, 1,500 GPM for 10-inch pipe, and 2,000 GPM for 12-inch pipe. Where supply cannot produce stipulated flow rates, obtain maximum available by using properly sized discharge devices.

Hydrostatic: Hydrostatic test should be made at not less than 200 PSI for we hours or 50 PSI above static pressure in excess of 150 PSI. Differential try-pipe valve clappers should be left open during test to prevent damage. All above ground piping leakage should be stopped.

Leakage: New pipe laid with rubber gasketed joints should, if the worknamship is satisfactory, have no leakage at the joints. Unsatisfactory amounts if leakage usually result from twisted, pinched or cut gaskets. However, ome leakage might result from small amounts of grit or small imperfections. The amount of leakage at the joints should not exceed 2 quarts per hour ser 100 joints irrespectively of pipe diameter. The leakage should be disributed over all joints. If such leakage occurs at a few joints the installation hould be considered unsatisfactory and necessary repairs made.

New pipe laid with caulked lead or lead-substitute joints, should, if the vorkmanship is satisfactory, have little or no leakage at the joints. Any oint having leakage or more than a "slight drip" or "weeping" should be epaired. Leakage should not exceed 1 oz. (liquid measure) per hour per nch of pipe diameter per joint. The leakage should be distributed over all oints. If such leakage occurs almost entirely at a few joints, the installation hould be considered unsatisfactory and necessary repairs made.

Pneumatic: Establish 40 PSI air pressure and measure drop which should not exceed 1½ PSI in 24 hours. Test pressure tanks at normal water level and

Part "B" Underground Piping

LOCATION				
Feeds bldgs.				
UNDERGROUND PIPES A	ND JOINTS			
Pipe type and class	Type joir	ıt		
Conforms to				
If no, explain				
Joints needing anchorage clam in accordance with	ped, strapped, or backed	l		
If no, explain				
TESTS REQUIRED				
Flushing Tests				
New underground piping flus	shed according to	Sta	ndard Yes	
by (Company)				
How flushing flow was obtain Public water		F	ire pump	
Through what type opening:	Hydrant butt	Open pip	oe 🗆	
Lead-ins flushed according to		Standa	rd Yes 🗌	
By (Company)				
How flushing flow was obtain Public water □	ed: Tank or reservoir	F	ire pump	
Through what type opening:	Y conn. to flange & spir	got 🗌	Open pipe	
Hydrostatic Test				
All new underground piping	hydrostatically tested	ıtpsi.	For ho	urs
Leakage Test				
Total amount of leakage me	easured gals.		nours	
Allowable leakage	_			
HYDRANTS				
Number installed	Type and M	ake		
All operate satisfactorily		Yes 🗌	No 🗆	
CONTROL WALLES				
CONTROL VALVES Water control valves left wid	la open:	Von 🗀	No. Cit	
If no, state reason	•		No []	
Hose threads of fire departs		vdranta in		hle
with those of fire department	answering alarm?	Yes [No 🗌	•010
REMARKS				
Date left in service				
		••••		
PARTS A AND B SIGNA				
Name of sprinkler contractor	r			

For property owner (signed)

				BOONE AND	DARR, INC.
Part "C" S		d Water Spra		ound Piping	TESTS
	(I'm out sep	alaterant C i	or each riser)		All piping hydrostatically tested at 200 PSI for hours
LOCATION	D_{AN}	RIVA FO	i Arc do		Dry piping pneumatically tested: Yes \(\scale= \) No \(\scale= \)
Serves building	s: 1/4 Y	RUM EC	4 A 8 3 /5	U/13	Equipment operates properly: Yes \(\subseteq \text{No} \subseteq \text{No} \subseteq \text{.}
TESTS REQU	IRED				If no, state reason
Hydrostatic: all	Control of the last of the las				Drain test:
Pneumatic: dry Equipment oper					Reading of gage located near water supply test pipe:
Drain:			•	•••••	Static presurePSI
SPRINKLERS	OR SPRAY	NOZZLES			Residual pressure with valve in test pipe open wide:
Make	Model	Size	Quantity	Temperature Rating	PSI
FIREMATK	5 s U	1/2	67	1600	BLANK TESTING GASKETS
	***************************************	***************************************		***************************************	Number used NOVE Locations Number removed
***************************************		***************************************	***************************************		WELDED OR BRAZED PIPING Yes □ No 🛣
	***************************************	***************************************	***************************************	***************************************	If Yes, do you certify as the sprinkler contractor that the welders or brazers
PIPE AND FI		1.001 #1.	2		are qualified for welding or brazing in accordance with the requirements of ASME Boiler and Pressure Vessel Code, Section IX. Qualification Standard
		to NECA *1			for Welding and Brazing Procedures, Welders, Brazers, and Welding and Brazing Operators-1968 Edition.
ii none, explain			•••••••	•••••••••••••••••••••••••••••••••••••••	A.
ALARM VALV	E OR FLOW	INDICATOR	MAVIMIII	AC CUTACES	REMARKS
AT.	ARM DEVIC	CE	MAXIMUI TO OPE THROUGH	RATE	Date left in service with all control valves open
Туре	Make	Model	Min	Sec	PART "C" SIGNATURES
***************************************			•••••••••••	** ************************************	Name of sprinkler contractor Boune & Dan
DRY PIPE VA	ALVES				For sprinkler contractor (signed) Hervice M. Daws
Operating Test	Results: Ma	skeMode	elSeria	l No	For property owner (signed) Title Tests Witnessed By A.C., Title Title Title Title Title
Time to Trip Test Pi					Tests witnessed By L. A. A. S. Hilloff J. Date Co. M.
Without	With		. Trip Point	Time Water	Lee LARSA INSP 6/18/8/
Q.O.D.	Q.O.D.	Water Air		Reached Test	
Min Sec	Min Sec I	Pressure Press PSI PS	ure Pressure		
Alarm operated	properly?		Yes 🗌	No 🗆	
If no, explain	********************************				
DELUGE AND	PREACTIO	N VALVES			
Operation: Pneu	ımatic 🗌	Electric [Hydraulic [
Piping supervise	ed: Yes 🗌	No 🗆			
Detecting media	supervised:	Yes 🗌 💮	No 🗆		- armsu
Does valve ope Yes	rate from the	manual trip and	d/or remote co	ntrol stations?	INTECETY ED JUN 23 1981 FIRE DEPARTMENT
Is there an acces	ssible facility is	n each circuit for	testing? Yes [□ No □	JUN 23 1302
If no, explain					DEPARTMENT
Make		Mod	el		FIRE DELL
Does each circu	it operate sup	ervision loss alaı	m? Yes 🗌	No 🗌	

Yes 🗌

Min Sec

No 🗆

'oes each circuit operate valve release?

ximum time to operate release:

FIRE PREVENTION	ON BUREAU
4	DATE May 13 19,75 TIME
STATION T DISTRICT	
LOCATION 2270 DLATT A	2D.
OCCUPANT JUVENILE DE	TENTION HOME
EXECUTIVE OFFICIAL TODO WE	00 LFRY PHONE 434 5/68
OCCUPANT EXECUTIVE OFFICIAL RESIDENCE OCCUPANT TUVENILE DE TODO L)6	
BUILDING OWNER WUSHTENWAY	COUNTY PHONE
ADDRESS	MAIN - 5/16018 - Theele
BUILDING	ONHLD SOLGOIS DEREC
STORIES CONSTRUCTION Masonry:	HOUSEKEEPING? COOK
FIRE WALLS? YES. OPENINGS PROTECTED? .	
ELEVATOR SHAFTS: OPEN? NOWESED?	
DOORS OPERATE PROPERLY?	FLAMMABLE LIQUIDS? Wood shop & Ga
	WHERE STORED?
STAIRWAY DOORS SELF CLOSING? 785.	PERMITS?
	SPECIAL HAZARDS?
EXITS: B 4, 1 4, 2 -, 3 , 4 , .	TLL'
5, 6, 7, 8, 9, 10	Feation
MARKED? YES AGEQUATE? YES.	
PROPERLY MAINTAINED? 725	
ROOF CONSTRUCTION Built UP	WELDING: LOCATION? NOWE
Access? CINEC WHERE?	WELDING. LOCATION.
Main CORRIDOR DETENTION	TYPE? PERMIT?
All Can	COMBUSTIBLE STORAGE: WHERE?
HEATING: HOW? GAS J.W.	in Sorinkequed Rooms.
CONDITION?	IN DOKINKEGIED KOOWIS.
UK 1	
VENTILATION SYSTEM? YES	
AIR CONDITIONING: YES	FLOODS OVER OADS AND
ELECTRICAL CONDITIONS?	FLOORS OVERLOADER NO NE
LLECTRICAL CONDITIONS.	REQUIRED PERMIT? NO.
FIRE PROTECTION	•
Yantia	• _
	. Conditions referred to other depts.
Sources of supply and capacity of	
EACH?	
VALVES OPEN? SEALED?	
CONTROL VALVES READILY ACCESSIBLE?	
	. REGARDING VIOLATIONS, INTERVIEWED?
CONDITION OF STAMESE CONNECTION?	. 1. Wolley -
	TITLE
	REMARKS:
STANDPIPE SYSTEM? WET NO NEY.	: Marin System lested your 75
COUNCE OF COFFEE AND CAFACITY	· · · · · · · · · · · · · · · · · · ·
Hose Size? Condition?	
CAN FIRE DEPT. USE QUIL ETS?	
FIRE EXTINGUISHERS?	·
	INSPECTOR OF THE PARTY OF THE P
LAST SERVICE DATE? (CORE 1415	Additional Information (Over)
•	DUDITIONAL INFORMATION (OWER)



CITY OF ANN ARBOR MICHIGAN

219 East Huron Street, Ann Arbor, Michigan 48108

Phone (313) - 994-2772

May 13, 1975

Ann Arbor Fire Department

Mr. Tod: Woolery

Juvenile Detention Home

2270 Platt Road

Ann Arber, Michigan 48104

Re: Emergency Procedures

Dear Mr. Woolery:

Regarding the <u>Emergency Procedures</u> established for your facility, I would like to make the following suggestions:

- 1. Upon notification of a fire or smoke odor the Superintendent or Assistant Superintendent should notify the Fire Department.
- 2. A staff member with keys should be designated to meet fire personnel and direct them to the problem area.
- 3. Staff members should be aware that in the event of a serious problem, rescue attempts without the Fire Department may compound the problem as they do not have the equipment and breathing apparatus to be effective in a fire situation.
- 4. One representative of your staff should be designated to provide information to the Fire Department Chief Officer.
- 5. Any order by the Chief Officer must be complied with as the building is under the jurisdiction of the Fire Officer until such time as it is turned back to your personnel.

Enclosed please find an outline of the Extinguisher Demonstration for your record.


Charles J. Osborn

Fire Anspector

Cordially.

CJO:ap

cc: Station #4



CITY OF ANN ARBOR MICHIGAN FIRE DEPARTMENT

July 27, 1977

Mr. Todd W. Woolery, Superintendent Washtenaw County Juvenile Detention Center 2270 Platt Road Ann Arbor, Michigan 48104

Re: Your letter of July 7, 1977

Dear Mr. Woolery:

Regarding your letter concerning the Emergency Evacuation Procedures, I offer the following comments:

- 1. One of the very first items on your list should be to notify the Fire Department.
- 2. An individual should be designated to meet the Fire Department.
- 3. Personnel should be advised that no one is to re-enter the building until permission is granted by the Fire Officer in Charge.
- 4. Also be advised that State Law requires all fire incidents to be reported.

If there are any questions regarding the above, please call the Department.

Cordially,

CJO:ap

Charles J. Osborn Fire Inspector



PROBATE COURT JUVENILE DIVISION

2270 PLATT ROAD

ANN ARBOR, MICHIGAN 48104

(313) 971-7100

FRANCIS L. O'BRIEN
Probate and Juvenile Court Judge

GEORGE E. FOLTZ, ACSW Director of Juvenile Services GERALDINE TOLONEN Juvenile Register

June 7, 1977

Ann Arbor Fire Department 219 East Huron Street Ann Arbor, Michigan 48107

Attention:

Charles J. Osburn

Fire Inspector

Dear Mr. Osburn:

During attendance at a recent Ways and Means meeting of the Board of Commissioners, discussion was given to the importance of up to date and comprehensive emergency procedures for county buildings. Attached are the Emergency Procedures for the Juvenile Court Detention facility at 2270 Platt Road, Amn Arbor, Michigan.

A review of the fire procedure by yourself or a member of your staff, together with suggested changes or additions, would be helpful toward an even more precise manual.

Your cooperation will be genuinely appreciated.

Thank you.

Sincerely yours,

Jodd W. Woolevy
Superintendent
Detention

TWW/sdh

To: All Detention Staff

From: Todd Woolery

Date: lay 7, 1975

Re: Emergency Procedures

I. Fire

Our first obligation as detention staff is to prevent the onset of fire by careful supervision and safety precautions. However, if a fire does occur the following procedures should be followed:

- I. When a fire is detected, immediately call the Superintendent or the Assistant Superintendents and institute the following:
- II. A verbal alert should be given to other staff and the supervisor or designated person in charge. Do not attend to the fire before giving an alert.
- III. Staff should immediately begin by moving youngsters to a part of the building or grounds away from the fire and smoke area. At least one staff should remain at all times with the youngsters. As you leave the affected areas, after making sure that all youngsters are out, close doors behind you to retard the spread of flames. Depending on the size and seriousness of the fire, the youngsters should be moved:
 - A. first, to another part of the secure detention area away from the fire,
 - B. second, to a non-secure area of detention (chapel, front hall),
 - c. third, outside in the recreation yard or court parking lot,
 - D. fourth, is weather is cold, to the vocational center.
- IV. After youngsters have been moved to safety, staff, if appropriate should attempt to contain the fire by closing doors and using fire extinguishers. The fire extinguishers are located:
 - 3 Control Station (1 water[cl.C], 1 CO₂[cl.A.B], 1 dry chemical [class ABC])
 - 1 Mitchen (1 chemical [class ABC])
 - 2 Shop (2 water)

Court

l each in East-West Hall (water)

Call the fire department as soon as youngsters are safe.

EMERGENCY NUMBERS

Ann Arbor Fire Department - 994-2770

Ann Arbor Police Department - 934-2911

Fontana Taylor Ambulance - 994-4111

University Hospital - Emergency - 764-5102

Emergency Haintenance Night Line - 971-7106

Full telephone list last page of this section

- V. All youngsters should be accounted for, after the fire is out or has been attended to by the fire department. If any youngsters have run away, initiate the Notification Policy for runaways.
- VI. Before re-occupying an area of detention where there has been a fire, the area should be fully clear of smoke.
- VII. After each fire, each staff member should submit a written incident report, describing their activity during the incident.

EXPLOSIONS

Follow above procedures

To: All Detention Staff

From: Todd Woolery

Date: May 7, 1975

Re: Bomb Threat Procedures

When a bomb threat call is received by telephone the following procedure should be executed:

- 1. Ask for as must information as possible. Such as where the bomb is located, when it is set to go off, what kind of bomb it is, and what kind of package is it wrapped in.
- 2. The supervisor or designated person in charge should immediately call the Superintendent or Asst. Superintendents while initiating the following:
 - A. assign staff to clear the wing of children, check each wing area including rooms, closets, and bathrooms. If the wings are clear then have all the youngsters go to the wing areas and have the youngsters second check their own rooms. Count and check against the population sheet each youngster.
 - B. The designated person in charge should notify the Ann Arbor Police and also (Robert Paul - 428-7607)
 - C. The staff should remain the in the wing area with the youngsters. The designated person in charge should then check the dayroom area, classrooms, art and home economics room.s
 - The designated person in charge should greet the Ann Arbor Police and escort them on a search through the front area of the building offices, the kitchen, basement, and also the gym.
 - E. In the case where an unusual object would be found in one of the wing area, remove the youngsters to the Chapel only after the staff "cleared" the chapel. Leave the unusual object alone, DON'T TOUCH IT. Direct the police to it.
 - F. Clear the wing areas and escort the youngsters there. Do not remove the youngsters to the pen.
 - G. A <u>written report</u> of the incident should be forwarded to the Director, Mr. Foltz, and to Judge O'Brien for their information and file.

SUGGESTED PROCEEDURE FOR HANDLING BOMB THREATS

Of primary consideration in calls of this nature is the type of business or establishment threatened, the extent to which the threat can be construed as being in earnest, and the degree to which the officials of such a firm wish to go in handling in the approved manner.

Initial handling of a bomb call requires the following system:

I Evacuation
II Identification

III Isolation
IV Deactivation

I EVACUATION

- A. Map and locate exits.
 - 1. Check for least directional traffic.
 - 2. Check outward opening doors. (All exterior should be)
 - 3. Establish priorities for exiting from the premises.
- B. Special handling.
 - 1. Possibly critical machinery to be shut down.
 - 2. Sensitive or classified materials or items to be protected.
- C. Outside care.
 - 1. Checking of personnel to ascertain their presence.
 - 2. Temporary shelter during incliment weather.
- D. Re-entering the premises.
 - 1. Priority of re-entry.
 - 2. Clarification of any local problems during re-entry.

II IDENTIFICATION

- A. Location of possible suspect items.
 - 1. Janitorial or supervisory staff will be expected to assist local officers, where possible .
 - 2. Actual identification of the type of ordinance will be made normally by trained EOD personnel.

III ISOLATION

- A. Local materials will be used for temporary isolation if such isolation is considered possible or desirable.
- B. Movement of specialized or expensive equipment will be considered if it does not pose a threat to the ordinance, with special emphasis placed on items, which may add to an explosive situation.

IV DEACTIVATION-REMOVAL

This is a problem to be attempted by trained personnel, and will not normally be attempted by local business personnel, nor by the routine search officers on the scene.

LIMBALEMING PHOR

Time call received	Time caller hung up
Exact words of person placing call	
Questions to Ask:	
1. When is bomb going to explode	e?
2. Where is the bomb right now?	
3. What kind of a bomb is it?	
The state of a solid to the sol	
4. What does it look like?	
The William Good to look like	
5. Why did you place the bomb?	
or way are you place the house	
. Person (receiving) (monitoring) ca	all
Dept.	
Home Address	
Home Telephone No.	
Date	

DESCRIPTION OF CALLER'S VOICE

Male	•	Female		
Young	Middle Age		Old	
Tone of Voice				
Accent	•			
Background Noise				
Is voice familiar?				
If so, who did it soun	d like?			
Remarks:				
		•		
				•
	•	•	and the second	
			H 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	•			
	· · · · · · · · · · · · · · · · · · ·			
				te .
				-

EMERGENCY MEDICAL PROCEDURES FOR AFTERNOONS AND WEEKENDS

- I. If a youth complains of a severe illness, the following procedures should be used:
 - Λ . All complaints should be noted in the log

l. Date and Time

- 2. Symptoms and relevant facts (temperature, exact nature of pain, and any other descriptive terms)
- B. The doctor on call should be notified; if he can't be reached call the emergency room at St. Joseph's or the University of Michigan Hospital. (the call should be places by the supervisor or the designated person in charge.)

1. have youth nearby when talking to the doctor

2. record in the log which doctor was reached

- 3. doctor's recommendations or procedures to follow
- 4. any concluding statement or follow-ups and signed by caller
- c. If the nature of the illness (example: broken arm) warrants, the judgement as to whether the youth should go to the hospital will be made by the supervisor or the designated person in charge.
- II. If the doctor orders the youth to be taken to the hospital, the following procedures should be used:
 - A. If, in the estimate of the supervisor or person in charge, an unsatisfactory answer was given or the youth continues to complain, the supervisor or designated person in charge, based on information already obtained, may then take steps for transport of the child to the hospital.

1. this should also be recorded in the log

2. if the decision is to transport, these steps should be followed:

a. call an ambulance (transport in personal vehicle is not feasible)

b. a staff member should accompany the youth if possible; at no time should the staff fall below two males and one female; if transport would bring the staff under this limit, the supervisor should be notified. If the supervisor on weekends is called at this time, he should be fully informed of the nature of the illness and all relevant facts. (Supervisors: Mike Giraud, Ron Gallinger, Todd Woolery) It is now possible for a male to accompany a female if an ambulance is taken.

c. return to detention should be in a cab or by police escort.

3. as of this date, June 1, 1972, all venereal disease complaints can be handled within detention unless the youth has severe cramping, extreme temperature, and it will be more than a day before our doctor will see the youth. In this case, our doctors

5-14-73- D	1. COUNTY	2. DATE OF REPORT	20-921-69 4.5
Department of State Police	Washtenaw	5. DATE OF ORIGINAL REPORT	6. (a) FIRST INSPECTION
FIRE SAFETY INSPECTION REPORT	4. TOWNSHIP	September 25, 1969 9. PLAN REVIEW JOB NUMBER	(a) FIRST INSTECTION (b) FINAL INSPECTION
OST, DISTRICT, DIVISION OR BUREAU	8. CITY OR VILLAGE	F-110-67 6608-12	(c) RECHECK
Div. Detroit SP/20	Ann Arbor	11. FOR FM OFFICE USE ONLY	(d) ANNUAL INSPECTION
YPE OF FACILITY			
1 m 11 1 m 11	htensw Juvenile Cou O Platt Road, Ann A	rt Center Ther. Michigan	
	Pall - Maintenance		TO LODUE UNIT
C) CONTINC	ADDITION	TEMPORARY REMODELING	MOBILE UNIT
(d) X INCW			
FIRE SAFETY CERTIFICATION.	seatisfactory compliance with th	ne fire safety requirements, therefore, is certifi equirements, however, temporary certification i	ied.
(a) The above named facility is in	not fully meet the fire safety re	equirements, however, temporary certification in the fire safety requirements, therefore, is not	s granted until
(b) The above named facility is no	ot in acceptable compliance with	equirements, however, temporary certification h the fire safety requirements, therefore, is not	Certified.(Sec flame)
(c) The above named factority to the			
ORIGIN:			
ADDRESS		NSPECTING OFFICER(S) D/Sgt. John 1). MacDougall
RECEIVED BY	a Sankara Inda	a County Court House, Ann	Arbor, Michigan
DISTRIBUTION Washtensw I	Pire Dont. 219 E.	Buron, Ann Arbor	Grand Pandda ADS07
ire Marshal, Ann Arpor	mon Associates. Van	Huron, Arm Arbor denberg Center, 200 Houroe, Levis Cass Bldg., 4th Floo	Grand Mapide 47304
BCK M. TALLASTER TOLAND		Landa France Eldo, 4th Floo	r-Lansing, mich.
acon lerpatra, button	Ulutaton 24870 Gra	and River, Michigan State Po	lice, vetroit
t. Rove, Fire Marshar	DAY TO SOME		
The above certification of the State Fire Safety S		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	itions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	itions by the
		nding promulgation of regula	itions by the
		nding promulgation of regula	itions by the
		nding promulgation of regula	tions by the
		nding promulgation of regula	tions by the
State Fire Safety i	Soard.	nding promulgation of regula	19. REVIEWING OFFICER
	Soard.	John D. MacDougall, D/Sgt	19. REVIEWING OFFICER

should be notified of the emergency.

- 4. Medical Supplies location:
 - fourth shelf Alka-Seltzer, Tyneal (liquid),
 Neotizine and Primatene Hist
 - b. third shelf Q-Tips, Gelusil, bandages, Phisohex, Milk of Magnesia, Alcohol, Hydrogen Peroxide
 - c. second shelf Vitamins, Cough Syrup, Midol, Sucrets, Aspirin, Tape, Cotton Balls
 - d. first shelf Active Prescriptions
 - e. right hand drawer thermometer and other medical equipment, TB tests
 - f. right hand cabinet in medical cabinet plastic test tubes, plastic cups
 - g. middle cabinet in medical cabinet Cough Syrup, bandages, Alcohol, etc.
 - h. left cabinet in medical cabinet Refrigerator: cultures for gonorrhea, strep throat, penicillin, adaptic
 - right hand drawer, cabinet against the wall microscope slides
 - j. cabinet below right hand drawer syringes and needles, medication cups
 - k. medical files are located in the top drawer in the file cabinet; folders and forms are behind them.
 - 1. White sterilizing unit next to sink

Nichael Giraud	449-4009
Todd Woolery	434-5168
Ron Gallinger	561-6013
Cathy Lindstrom	878-9085
Val Eaglin	482-7427
Ell Dudley	482-4515
University Hospital Emergency	764-5102
St. Joseph's	665-4141 (ask for emergency)
Dr. Seaman Dr. Koepke	971-3859))refer to call 971-4977)sheet in rm.
Dr. Bossung)#22 (C. 971-4974)Lindstrom office)
Fontana-Taylor Ambulance	994-4111
Ann Arbor Police Department	994-2911

971-8400

432-1211

Washtenaw County Sheriff's Dept.

Michigan State Police - Ypsi Post

STATION 4 DISTRICT	DATE MARCH 27, 19,72 TIME
LOCATION 2210 RAI RD. OCCUPANT WASHIENAW COUNTY JUVE	MIE DETENTION
EXECUTIVE OFFICIAL	PHONE
RESIDENCE BUILDING OWNER COUNTY OF WASHIENAW	PHONE
ADDRESS	
BUILDING	OCCUPANCY
STORIES 16 B. CONSTRUCTION MOSCNRY CONDITION GOOD	Housekeeping? GOOD
FIRE WALLS? YES OPENINGS PROTECTED? . VERY	
ELEVATOR SHAFTS: OPEN? NONE OSED? .	ELEVATOR PIT CLEAN? NONE FLAMMABLE LIQUIDS? FASOLINE
Doors operate property? Floor openings protected? YES .	WHERE STORED? IN GARAGE
STAIRWAY DOORS SELF CLOSING?	PERMITS? SPECIAL HAZARDS? AREA LOCKED
EXITS: B , 1 , 2 , 3 , 4 , , 5 , 6 , 7 , 8 , 9 , 10	THROUGHOUT
PROPERLY MAINTAINED?	
ROOF CONSTRUCTION BUILT UP. ACCESS? YES WHERE? THRU ROOM 22. ALSO F.D. LADDERS OUTSIDE	WELDING: LOCATION? ARC & ACETELYENE IN BOILER ROOM Type? PERMIT? NONE
HEATING: HOW? GAS FIRED HOT WATER. CONDITION? 3 BOILERS	COMBUSTIBLE STORAGE: WHERE? NONE EXCEPT IN SPRINKLERED STORAGE AREAS
VENTILATION SYSTEM? YES AIR CONDITIONING? YES	
ELECTRICAL CONDITIONS? GOOD	FLOORS OVERLOADER? NO. WHAT FLOORS?
	REQUIRED PERMIT?
FIRE PROTECTION	•
SPRINKLER SYSTEM? YES WETV DRY SOURCES OF SUPPLY AND CAPACITY OF EACH?	CONDITIONS REFERRED TO OTHER DEPTS. LHR TO MICH. DEPT. OF SOCIAL SERVICES.
VALVES OPEN? YES SEALED? YES CONTROL VALVES READILY ACCESSIBLE?	
CONDITION OF STAMESE CONNECTION?	REGARDING VIOLATIONS, INTERVIEWED?
LOCATED NEAR HYD @ So. RWING FRONT OBSTRUCTED AT ANY POINT? NO	. TITLE
STANDPIPE SYSTEM? WET NONE DRY Source of supply and CAPACITY 6"MAIN	REMARKS: ALARM SYSTEM LOCAL - EDWARDS CO.
HOSE SIZE? NONE CONDITION?	
CAN FIRE DEPT. USE OUTLETS?NO FIRE EXTINGUISHERS?THROUGHOUT	•
LAST SERVICE DATE? MARCH 7	. INSPECTOR: ADDITIONAL INFORMATION (OVER)

Mr. James Kinkema Licensing Consultant State Department of Social Services Kalamazoo Field Office 42628 W. South Street Kalamazoo, Michigan 49006

Dear Mr. Kinkema:

A fire inspection made this date at the Washtenaw County Juvenile Detention Home, 2270 Platt Road, Ann Arbor, Michigan revealed that there are no major problems that would interfere with licensing as far as this office is concerned and that we are working to correct some minor problems. I am planning on making a reinspection April 10th and I see no reason for holding up their relicensing at this time.

If there are any questions in this regard please feel free to contact me at this office.

Cordiall

Charles Osborn, Inspector Fire Revention Bureau

City of Ann Arbor

cc: Mr. George Foltz

CJO/ks

Mr. Omar Simon Ann Arbor Public School Supply 1212 H. Main Street Ann Arbor, Michigan

Dear Mr. Simon:

As a result of a fire inspection made March 16, 1972, I would like to comment on the excellent housekeeping of your warehouse facility.

The only problem I can see is in the storage and handling of your flammable liquids. All flammable liquids for use and storage in the public schools should be in labeled one gallon metal containers. Quantities stored at the schools should be limited to no more than 6 gallons total.

As it is understood that you are moving your warehouse operation to the State Road location. I would suggest you contact this office regarding your drum storage as it dows not presently conform with the requirements of state law.

Cordially,

Charles J. Osborn, Inspector Fire Prevention Bureau

City of Ann Arbor

cc! Guy Finch

CJO/ks

March 27, 1972

Mr. Todd Woolery Washtenaw County Juvenile Detention Center 2270 Platt Road Ann Arbor, Michigan 48104

Dear Mr. Woolery:

A fire inspection made this date revealed the following conditions which require your attention.

- 1. It was noted that there was storage in rooms 16 and 18. These are not approved storage areas. Storage in these rooms should be removed to the sprinkled storage area between these two rooms, thereby taking advantage of the fire protection gained by the two fire-labeled doors.
- 2. It was noted that in the wood shop area that the spray booth has no means of being vented to the outside. Proper vents should be provided.
- 3. It was noted in the woodshop area that a container should be provided for rags used for wood refinishing, etc. This should be a metal can with a tight-fitting lid, either a garbage can or a safety can specifically designed for this purpose.
- 4. It was noted that light extension cords were used for your electric hand tools in this area. It is recommended that a heavy cord with a ground receptible and plug be provided for use with hand tools. It is recommended that several of these be obtained.
- 5. It was noted in several areas that fire-labeled doors with self-closers were propped open. These should be maintained in a closed position at all times.
- 6. It was noted that the fire extinguisher was missing from the incinerator room. This should be provided.

- 7. During the course of the inspection in the gym area the fire-labeled door was noted to have been damaged and propped open. This door should be repaired and maintained in a closed position.
- 8. The aisleways to the exitway from the classroom area were obstructed by storage. This area should be maintained free and clear so that rapid egress may be gained in case of emergency.
- 9. The exit lights were in need of new bulbs in the girls detention area.
- 10. It is recommended that a self-closer be installed on the door separating the hallway from the kitchen and laundry areas and that this door be maintained in a closed position. This is door 91 on your blueprints.

Enclosed please find some door labels to place on the fire doors and if more are needed please let me know. As we discussed, a reinspection will be made Monday, April 10th, at 1:00 P.M. I appreciate your cooperation and am looking forward to meeting with your personnel to discuss fire extinguishers and fire related problems.

Charles J. Osborn, Inspector

Fire Prevention Sureau City of Ann Arbor

Copdially

Encoosure
1
CJO/ks

STATE OF MICHIGAN



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

			DATE 3-22-72
то:		FROM:	FILE#
	Mr. Arthur L. Stauch, Fire Chief Ann Arbor Fire Department	James H. Kink	ema, Licensing Consultant
	219 East Huron Ann Arbor, Michigan 48108	State Department Kalamazoo Field 423-28 West Sout Kalamazoo, Michi	h Street

This is a request that a member of your staff make an inspection of the child care facility listed. According to Act 47, P.A. 1944, Act 280, P.A. 1939, and Act 288, P.A. 1939, it is the responsibility of this Department to evaluate all child care facilities prior to initial operation and annually thereafter. This evaluation requires the assurance of the health and safety of the children. Therefore, we are asking your assistance in this essential service on behalf of children

We appreciate your help and thank you for your cooperation.

Washtenaw County Juvenile Det. Center ADDRESS (NUMBER AND STREET) 2270 Platt Road		TYPE OF FACILITY			
		1. Day Nursery: Full-Time Proposed Part-Time Capacity			
Ann Arbor ZIP CODE 48104		2. X Child-Caring Inst.: X County X Secure Custody Private Open			
COUNTY Washtenaw CONTACT Todd Woolery		3. Group Home: County Private			
TELEPHONE (AREA) (NUMBER) 61 313 971 7100		4. Camps: Residential Day			
SPECIAL INSTRUCTIONS		STATUS Proposed Relocation Addition Annual Inspection Reinspection			
		DATE REPORT DUE 4-1-72			

- 1. Please send a copy of your findings and recommendations to this office at the address given above and inform us if the facility meets with your approval.
- 2. Please mail a second copy of your findings and recommendations to:

NAME				
George Foltz, Director of Court Services				
ADDRESS	CITY	ZIP CODE		
COUNTRICATE 2270 Platt	Ann Arbor	481054		



STATION	DISTRICT		DATE	19,	TIME
OCCUPANT_	22 70 Platt Rd. Vashtenaw Coun	ty Juveni	e Detent Phon	ion Center	
RESIDENCE BUILDING O					
• • • • • • • • •	BUILDING	• • • • • • • • • • • • • • • • • • •	<u>occi</u>	<u>JPANCY</u>	• • • • • • •
STORIES FIRE WALLS	CONSTRUCTION CONDITION CONDITION CONDITION CONDITION CONDITION PRO	TECTED? . Hous	SEKEEPING?		
Doors oper Floor open	HAFTS: OPEN? CLO RATE PROPERLY? HINGS PROTECTED? OOORS SELF CLOSING?	. FLAI	MMABLE LIQUII RE STORED?	os?	
EXITS: B	1 5 , 2 , 3 , 9 , 9 ADEQUATE?	, 4, ,10 Yes .		?	
		. WEL	DING: LOCATION		
HEATING: H	dow? Oil - Hot wa.	Com	BUSTIBLE STOI	RAGE: WHERE?	
AIR CONDIT	ON SYSTEM? No				
ELECTRICAL	CONDITIONS? 200 A	Service . WHA . REQ	ORS OVERLOAD T FLOORS? UIRED PERMIT	? <u> </u>	
	FIRE PROTECTION	• • • • • • • • • • • •	• • • • • • • • • • • • • •	• • • • • • • • • • •	
Sources of	SYSTEM? WET D SUPPLY AND CAPACIT		DITIONS REFE	RRED TO OTHER	DEPTS.
	EN?SEALED?_ ALVES READILY ACCESS				
CONDITION	of Slamese connecti	• REG	ARDING VIOLA	TIONS, INTERV	TEWED?
STANDPIPE	O AT ANY POINT? SYSTEM? WET DR SUPPLY AND CAPACITY	Y : Ba	1 1	TITLE_	
FIRE EXT	DEPT. USE OUTLETS? NGUISHERS? Press. H	•		s - Smake	
LAST SERVE		. TNS	PECTOR: ITIONAL INFO	RMATION (OVER	2)

STATION DISTRICT	DATE 3-8 19,7/ TIME
OCCUPANT TO CATIONAL TEST DUNCT	
RESIDENCE NON TESPONSIVE BUILDING OWNER JAS	
ADDRESS	
BUILDING	OCCUPANCY •
CONSTRUCTION MASSACY. CONDITION FIRE WALLS? OPENINGS PROTECTED?	
ELEVATOR SHAFTS: OPEN? CLOSED? DOORS OPERATE PROPERLY? FLOOR OPENINGS PROTECTED?	<u></u>
STAIRWAY DOORS SELF CLOSING?	PERMITS?
EXITS: B , 1-5, 2 , 3 , 4 , 5 , 6 , 7 , 8 , 9 , 10 MARKED?	- Kear to Courte
ROOF CONSTRUCTION ACCESS? WHERE?	WELDING: LOCATION?
HEATING: How? O' / / / / / / CONDITION?	TYPE? PERMIT? COMBUSTIBLE STORAGE: WHERE?
VENTILATION SYSTEM? 1/3 AIR CONDITIONING? 1/5	
ELECTRICAL CONDITIONS?	FLOORS OVERLOADE®? WHAT FLOORS? REQUIRED PERMIT?
FIRE PROTECTION	• • • • • • • • • • • • • • • • • • • •
SPRINKLER SYSTEM? WET DRY SOURCES OF SUPPLY AND CAPACITY OF EACH?	CONDITIONS REFERRED TO OTHER DEPTS.
VALVES OPEN? SEALED?	
CONDITION OF STAMESE CONNECTION? .	REGARDING VIOLATIONS, INTERVIEWED?
OBSTRUCTED AT ANY POINT? STANDPIPE SYSTEM? WET DRY SOURCE OF SUPPLY AND CAPACITY	REMARKS:TITLE
Hose Size? Condition? CAN FIRE DEPT. USE OUTLETS? FIRE EXTINGUISHERS?	
LAST SERVICE DATE?	INSPECTOR: De GOOR ADDITIONAL INFORMATION (OVER)



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

March 17, 1971

Mr. John R. Williams
Fire Marshall
Fire Department
214 E. Huron
Ann Arbor, Michigan 48108

Re: Washtenaw County Juvenile Home

According to state law* it is the responsibility of this Department to annually evaluate all child care facilities. As part of the overall evaluation and to assure the health and safety of the children in such facilities, the licensing requirements established by our Department provide for annual health, sanitation and fire inspections. As your staff is highly qualified to provide evaluations of these programs, we request your assistance in providing this essential service on behalf of children.

Will you please forward your report to this office with a copy to: James H. Kinkema

James H. Kinkema
426 W. South Street
Kalamazoo, Michigan
49006

by 4-15-71

If you have any questions concerning this inspection, I can be contacted at this address or by telephone at:

We appreciate your help and thank you for your cooperation.

Sincerely,

James H. Kinkema, Licensing Consultant

JHK:sj



*Act 47, PA 1944 Act 280, PA 1939 Act 288, PA 1939

April 1, 1971

Mr. James H. Kinkema 426 W. South Street Kalamazoo, Michigan 49006

Re: Washtenaw County Juvenile Home

Dear Sir:

Inspection was made of the above captioned facility by the undersigned inspector and as far as this department is concerned it meets current fire regulations.

Very truly yours,

N.J. Lee, Inspector Fire Prevention Bureau City of Ann Arbor

cc: Mr. George E. Foltz

NJL/ks

7613825



WILLIAM G. MILLIKEN, Governor

DEPARTMENT OF SOCIAL SERVICES

R. BERNARD HOUSTON, Director

February 2, 1971

Mr. John R. Williams City of Ann Arbor Fire Dept. 219 East Huron Ann Arbor, Michigan 48108

WW43/1

Re:

Vocational Residential Center 2260 Platt Road Ann Arbor, Michigan

This letter is written to request that a member of your staff make an inspection of the above-named child care facility court operated child care facility.

According to state law* it is the responsibility of this Department to annually evaluate all child care facilities. As part of the overall evaluation and to assure the health and safety of the children in such facilities, the licensing requirements established by our Department provide for annual health, sanitation and fire inspections. As your staff is highly qualified to provide evaluations of these programs, we request your assistance in providing this essential service on behalf of children.

Will you please forward your report to this office with a copy to:

Mr. Dohn Hoyle, Director

by February 15, 1971

If you have any questions concerning this inspection, I can be contacted at this address or by telephone at:

We appreciate your help and thank you for your cooperation.


State Department of Social Services Kalamazoo Field Office

423-23 West South Street

Kalamazoo, Michigan 49006

Sincerely,

Licensing Consultant



Mr. Tom Woolery Juvenile Court Center 2270 Platt Road Ann Arbor, Michigan

Dear Sir:

Confirming our conversation of this morning, this department has no objection to your use of plastic or wired glass in the windows of the detention reception area.

We appreciate your contacting us in this regard. If we can be of further service please call us.

Thank you,

Charles J. Osborn, Inspector

Fire Prevention Bureau

City of Ann Arbor

August 17, 1970

Mr. K. Ross Childs

Wounty Administrator

Washtenaw County Building

Ann Arbor, Michigan 48108

Re: Former Juvenile Detention Home 2260 Platt Road

Dear Sir:

Inspection was made of the above captioned facility in the company of Mr. Stanley J. Dulgeroff of your office. As I understand it, this facility will be used as a rehabilitation and training center for girls. Following are my recommendations for fire safety should this facility be utilized in the above manner.

- 1. The present security doors in the hallway may be replaced with solid core doors. The proposed change in occupancy will not require the use of labeled fire doors in place of the present seaurity doors.
- 2. Smoke Barriers. There are presently solid doors installed in the hallways of each wing that serve as smoke barriers. These doors should be kept intact.
- 3. Fire Alarm System. The present fire alarm system is adequate, but should be maintained in working order once the building is recucupied.
- 4, Fire Extinguishers. It is my recommendation that one ABC (all purpose) fire extinguisher be installed in the kitchen near the doorway which also may serve as the extinguisher for the boiler room. Pressurized water extinguishers should be placed in each wind of the building, one 2½ gallon size per wing.
- 5. Heat Plant. The heat plant should be checked by a qualified service man and whatever repairs are necessary should be made.
- 6. Fireplace. Should the fireplace by used the contents of the room should be protected by a screen, especially if carpeting is installed.
- 7. If carpeting is installed in any portions of the building is should be of a fire resistant type.

Mr. K. Ross Childs

If you have any questions concerning the above recommendations you may contact me at 664-4130.

Bery truly yours,

N.J. Lee, Inspector Fire Prevention Bureau City of Ann Arbor

Proposed hange to Rehal & Ir anter 1 Replace Security dons son hallways with Sold core towns. 2. Leane Snoke barrier boors intect 3. Maintain etesti g fin alam system in automatic broileigt is 4. Fine ettergeriches IABC Kitchen. Pressure water near each exit 5. Theh + repair heating float 6. If findlow is used, probert by Sew Sul to Know child Legal Val

February 5, 1967

Mr. R. Bernard Houston, Director Department of Social Services Lewis Cass Building Lansing, Michigan 48913

Re: Washtenaw Co. Facility 2260 Platt Road Ann Arbor, Michigan

Dear Sir:

Inspection was made of the above named facility and as far as this Department is concerned, it meets with our approval major existing fire regulations.

The director and Superintendent of this Detention Facility are to be commended for the efficient manner in which the premises are kept.

cc: The Hon. Francis O'Brien Judge of Probate

Mr. Voltz, Director Washtenaw County Detention Facility Yours Truly,

N. J. Lee, Fire Inspector Fire Prevention Bureau Ann Arbor Fire Department MR. HELBER 2260 PLATT RD. ANN ARBOR, MICH.

DEAR MR. HELBER:

AN INSPECTION WAS MADE OF THE PREMISES AT THE WASHTENAW COUNTY DETENTION HOME FOR THE PURPOSE OF PLACING INTO USE, AN ELECTRIC HEATED KILN.

Two areas were found to be satisfactory for this Kiln:

- 1. THE AREA IN THE BOILER ROOM.

 IF THIS AREA IS TO BE USED, NO COMBUSTIBLE MATERIAL SHALL

 BE ALLOWED IN THIS ROOM. (ANY SHELVING MUST BE METAL.)
- 2. THE WORK-SHOP AREA.
 THIS ROOM ALSO MEETS WITH OUR APPROVAL.

IF WE CAN BE OF FURTHER SERVICE, PLEASE FEEL FREE TO CALL.

Yours TRULY,

BEN J. ZAHN

cc: Mr. Wm. Day
Washtenaw County Blog.
Ann Arbor, Mich.



GEORGE ROMNEY, Governor

DEPARTMENT OF SOCIAL SERVICES

LEWIS CASS BUILDING, LANSING, MICHIGAN 48913

R. BERNARD HOUSTON, Director

January 30, 1967

Mr. John R. Williams, Fire Marshal Ann Arbor Fire Department 219 East Huron Ann Arbor, Michigan 48108

Re: Washtenaw County Detention Facility 2260 Platt Road Ann Arbor, Michigan

Dear Mr. Williams:

This is to request that a member of your staff make the annual inspection at the above address.

Will you please forward your report to this office at your earliest convenience, with a copy to:

Honorable John O'Brien Judge of Probate - Juvenile Division Washtenaw County Courthouse Ann Arbor, Michigan 48108

Thank you for your cooperation in this matter.

Sincerely.

Jake Terpstra

Consultant to Children's Agencies

JT:cd



101U 2-

STATE OF MICHIGAN DEPARTMENT OF SOCIAL SERVICES



GEORGE ROMNEY
GOVERNOR

Field Office 1447 Washington Heights Ann Arbor, Michigan 48106

March 25, 1966

R. BERNARD HOUSTON

LYNN G. KELLOGG
DEPUTY DIRECTOR

Mr. Ernest Heller
Fire Chief
Ann Arbor Fire Department
Ann Arbor, Michigan

Re: Washtenaw Co. Detention Facility
Platt Road
Ann Arbor, Michigan

Dear Mr. Heller:

We are responsible under the provisions of Act 280 of the Public Acts of 1939, as amended, for the inspection of juvenile detention facilities. To assure the safety of the children in such institutions the rules of and regulations fixed by the Social Welfare Commission necessitate an annual fire inspection. Therefore, we would appreciate having a member of your Department inspect the above facility.

Please send your report to Monorable John W. Conlin, Judge of Probate, Court House, Ann Arbor, with two copies to this office at the above address.

Should your representative wish to confer with me please call me at 663-4296.

Thank you for your cooperation.

Sincerely,

(Miss) Catherine Hudie, Field Representative

ie Mudie

ed

MARCH 28, 1966

FONORABLE JOHN W. CONLIN JUDGE OF PROBATE WASHTENAW COUNTY COURT HOUSE ANN ARBOR, MICHIGAN

RE: WASHT. CO. DETENTION FACILITY

DEAR JUDGE CONLIN:

A FIRE SAFETY INSPECTION WAS MADE FEBRUARY TO, 1966 OF THE JUVE-NILE HOME LOCATED AT 2260 PLATT ROAD.

WE WERE PLEASED TO FIND THE FACILITY TO BE IN A VERY NEAT AND DRDERLY FASHION. NO SERIOUS HAZARDS WERE OBSERVED. IT IS THE OPINION OF THIS INSPECTOR THAT THE DIRECTOR OF THIS HOME BE COM-MENDED FOR HIS INTEREST IN FIRE SAFETY FOR HIS CHARGES.

SHOULD THERE BE ANY FURTHER QUESTIONS, OR IF WE MAY BE OF ANY FURTHER SERVICE, PLEASE CONTACT OUR OFFICE.

YOURS TRULY,

BEN J. ZAHN, FIRE INSPECTOR FIRE PREVENTION GUREAU

CITY OF ANN ARSOR

cc: Miss Catherine Mudie 1447 Washington Hts. Ann Arbor, Michigan

BJZ:LMM

JANUARY 29, 1965

HONORABLE JOHN W. CONLIN JUDGE OF PROBATE WASHTENAW COUNTY COURT HOUSE ANN ARBOR, MICHIGAN 48108

RE: WASHTENAW CO. DETENTION FACILITY 2260 PLATT ROAD ANN ARBOR, MICHIGAN

DEAR SIR:

A FIRE INSPECTION WAS MADE, AS REQUESTED, OF THE ABOVE NAMED FACILITIES ON JANUARY 29, 1965.

MR. J. SHANAHAN, SUPERINTENDENT OF JUVENILE DETENTION FACILITIES OF WASHTENAW COUNTY, SHOWED US THROUGH THE FACILITIES. IT HAS BEEN INTERESTING TO SEE THE IMPROVEMENTS IN THE FACILITIES DEVELOP SINCE HE WAS GIVEN THIS RESPONSIBILITY.

ALL HOUSEKEEPING WAS FOUND TO BE VERY GOOD. CONDUCT OF RESIDENTS HAS GREATLY IMPROVED. THE RESIDENTS WERE CLEAN, COURTEOUS, AND WELL BEHAVED. ROOMS OF RESIDENTS WERE VERY NEAT AND ORDERLY.

AS FAR AS FIRE HAZARDS EXIST, THEY ARE KEPT TO AN ABSOLUTE MINI-MUM BECAUSE OF THE HIGH STANDARDS HAINTAINED. FOR THE FIRST TIME WE WERE UNABLE TO FIND ANYTHING SERIOUS ENOUGH, IN OUR ESTIMATION. TO CALL TO THE ATTENTION OF THE AUTHORITIES.

WE FEEL THAT MR. SHANAHAN AND HIS STAFF ARE TO BE COMMENDED FOR THEIR EFFORTS TO IMPROVE THE FACILITIES AND THEIR EFFORTS TO IM-PROVE AND REHABILITATE THE RESIDENTS UNDER THEIR CARE AND SUPERVISION.

SHOULD YOU WISH TO CONFER WITH US, WE CAN BE REACHED BY CALLING 663-4130.

SINCERELY,
John R. WILLIAMS, FIRE MARSHAL

NOLAN J. LEE, FIRE INSPECTOR

CC: MR. J. SHANAHAN 2260 PLATT ROAD

> MISS CATHERINE MUDIE 1447 WASHINGTON HEIGHTS

JRW/BBB



SOCIAL WELFARE COMMISSION W. REED ORR, CHAIRMAN

JACK POWELL
REV. CHESTER J. PILARSKI
MRS. ELOISE WHITTEN

STATE OF MICHIGAN DEPARTMENT OF SOCIAL WELFARE

Washtenaw County District Office 1447 Washington Heights Ann Arbor, Michigan 48106

R. BERNARD HOUSTON

W. REED ORR, CHAIRMAN
HERBERT SCHINDLER, JR., VICE-CHAIRMAN

January 26, 1965

Mr. Ernest Heller Fire Chief Ann Arbor Fire Department Ann Arbor, Michigan

Re: Washtenaw Co. Detention Facility
Platt Road
Ann Arbor, Michigan

Dear Mr. Heller:

We are responsible under the provisions of Act 280 of the Public Acts of 1939, as amended, for the inspection of juvenile detention facilities. To assure the safety of the children in such institutions the rules of and regulations fixed by the Social Welfare Commission necessitate an annual fire inspection. Therefore, we would appreciate having a member of your Department inspect the above facility.

Please send your report to Honorable John W. Conlin, Judge of Probate, Court House, Ann Arbor, with two copies to this office at the above address.

Should your representative wish to confer with me please call me at 663-4296.

Thank you for your cooperation.

Sincerely,

(Miss) Catherine Mudie, Field Representative

êd

87

FEBRUARY . 1964

CLARENCE HAMBER, DIST. DONCOLTANT
DEPT. OF OCIAL WELFARE
URILDSEN'S SIVISION
WASHTENAW COURTY WIT
P. J. JOX 1086
PNO PROCES, ICHICAN

ANN TENN, FICHTORS

- THE INSPECTION WAS MADE OF THE PROVE WARM , FACILITY OR I HUARY 4, 1964, AS REQUESTED.
- FOUND THE FACILITIES CLEAN END ONDERLY. THE DMLY CONTECTIONS NECESSARY FOR COMPLETE COMPLIANCE WITH STATE AND LIDAL REVENUENT. SIE AS FOLLOWS:
- T. FIRE EXTINGUICHERS THE FIRE EXTINGUICHE & THROUGH-OUT THE FACILITIES HAVE NOT BEEN CHECKED PINGE ARCIE, 1302. IT IS OUR RECOMMENDATION THAT A QUALIFIED FIRE EXTINGUICHER SERVICEMAN AGAIN DE CALLES TO CHECK AND SERVICE THE EXTING-UICHERD.
- OF THE OFFICE TEST AGENTALIZED THE CONTRICT OF THE CORD TEST OF THE CORD A LONG ELECTRICAL CORD OF THE OFFICE OF THE COLOR OF THE COLOR

THE ELECTRICAL CORD IS NOT AN APPROVE A TYPE FOR CULTAL UNDERCHOUSE AND WHENE IT PASSES UNDER SHE SAFES SOOR A BREAKBOOK COULD OCCUR AT ANY TIME.

IF THIS UNIT IS TO CONTINUE TO BE ESSUED OF SECONMERCO THAT AN EXTENSON OUTLES HAN BE PROVIDED OF THE GARAGE AND APPROVED UNDERSHOULD CALLE SE USED TO COMMENT THE UNIT TO THE ELECTRICAL SOURCE AT THE CANAGE.

IF THES TWO ITEMS AND CORRECTES, IACILIFIED VILL THESE DE IN VERY GOOD CONDITION.

IF THE LANE ANY QUESTIONS SHIF WE CAN HE OF ANY FORTHER BLEVICE, N. MAY BE CONTACTED BY PROSE AT COU-FION OR BY MAIL.

Yours TRULY, .

John Pellelleaux John W. AILLIAMS, FIRE ARSHAL Malan J. Le, FIRE INSPECTOR

W.: COM W. GRANAHN June 1. JONET+, JUDGE OF PROBATE COURT HOUSE KAR ARBOA, BICHIGER

UTA/ TAB



STATE OF MICHIGAN DEPARTMENT OF SOCIAL WELFARE

Children's Division Washtenaw County Unit P.O. Box 1085 Ann Arbor, Michigan JOHN B. SWAINSON GOVERNOR

> W. J. MAXEY DIRECTOR

February 6, 1962

JACK POWELL, CHAIRMAN W. REED ORR, VICE-CHAIRMAN MRS. A. A. BANKS, JR. HERBERT SCHINDLER, JR. REV. CHESTER J. PILARSKI

SOCIAL WELFARE COMMISSION

Mr. Ernest Heller
Fire Chief
Ann Arbor Fire Department
Ann Arbor, Michigan

Dear Mr. Heller:

Re: Washtenaw County Detention Facility
Platt Road

Ann Arbor, Michigan

We are responsible under the provisions of Act 280 of the Public Acts of 1939, as amended, for the inspection of juvenile detention facilities. To assure the safety of the children in such institutions the rules of and regulations fixed by the Social Welfare Commission necessitate an annual fire inspection. Therefore, we would appreciate having a member of your Department inspect the above facility.

Please send your report to Honorable John W. Conlin, Judge of Probate, Court House, Ann Arbor, with two copies to this office at the above address.

Should you representative wish to confer with me please call me at Normandy 3-4296.

Sincerely,

CH:ed

District Consultant

The honorable John . Conlingues of Probate Court House Arm Arbor, Michigan

war dir

As requested by the somethers of locked offuse, a fire inspection was made this date of the capitons count. Detention Pacifity, 25%) Platt Room, and recommendate and This inspection was made by the maderal median engagement officers accompanied by the installation, director of the facility.

I wish to make the following recormendations so that it may be brought to the attention of the proper authorities for correction.

building are of the type 102 (Carbon diomide). There are four of these. I recommend replacing two of these with a pressurized water type which should be readly accessible to a responsible person. One 112 should be left in the present locations of the furnace room and the bitchen. All exting ishers to be ensched and annually or immediately after use.

Ritchen area: The vent-a-hood was found to contain excess prease. I would like to recommen weeply clean-ing of this went and filters. This would eliminate a great fire hazard.

Housekeeping: The housekeeping at the time of this inspection was good. The director is to be commended for his efforts in keeping a neat and presentable javenile nome.

If there should be any questions concerning the inspection or if I may be of further service, please of not hesitate to call me at 10-130.

downs trolly,

h. d. we. 126 inspector

OO:

(2) Milareno dviaian

(1) by armilo relice, irector

Sept. 5, 1957

State of Michigan Department of Social Welfare Marion M. Livingston, District Consultant 206 Municipal Court Tldg. Ann Arbor, Mich.

Dear Madam:

As requested, we have this day completed an inspection of the Juv nile Detention Home; 2260 Platt-Rd.; Washtenaw County. The following is our description of the home and hazards noted during his inspection.

- 1. Fire-warning devices in every room and hallway. GOOD.
- 2. Five 15# CO2 type fire extinguishers strategically located for emergency use. GOOD.
- 3. Housekeeping. Good.
- 4. Night lights. GOOD. It might be recommended that one night light be located in the main hallway instead of necessitating the bu burning of all the lights in this hallway at night.
- 5. Electric wiring. Good except for:
 (a) Proken switch in the boys lavatory.
 - (b) Water meter should be electrically bonded.
- 6. Waste material. Kept at a minimum
- 7. Incinerator is kept clean and location in the garage at rear of building. Goop.

Generally we found the home to be in very good condition and except for the two minor problems ther is no serious fire or electrical hazards in existance at this time.

Respectfull submitted,

Solm Retributions

Solm R. Williams, yire

Edward C. Hines, Electrical Inspector

cc/ Pldg. & Salety Dept. Cit. of Ann Arbor

Director Juvenile Home.



STATE OF MICHIGAN DEPARTMENT OF SOCIAL WELFARE

Children's Division Washtenaw County Unit P.O. Box 1085 Ann Arbor, Michigan JOHN B. SWAINSON GOVERNOR

W. J. MAXEY

SOCIAL WELFARE COMMISSION

JACK POWELL, CHAIRMAN W. REED ORR, VICE-CHAIRMAN MRS. A. A. BANKS, JR. HERBERT SCHINDLER, JR. REV. CHESTER J. PILARSKI

February 13, 1963

Mr. Ernest Heller Fire Chief Ann Arbor Fire Department Ann Arbor, Michigan

Re: Washtenaw County Detention Facility
Platt Road
Ann Arbor, Michigan

Dear Mr. Heller:

We are responsible under the provisions of Act 280 of the Public Acts of 1939, as amended, for the inspection of juvenile detention facilities. To assure the safety of the children in such institutions the rules of and regulations fixed by the Social Welfare Commission necessitate an annual fire inspection. Therefore, we would appreciate having a member of your Department inspect the above facility.

Please send your report to Honorable John W. Conlin, Judge of Probate, Court House, Ann Arbor, with two copies to this office at the above address.

Should your representative wish to confer with me please call me at Normandy 3-4296.

Sincerely,

CH:ed

District Consultant

February 20, 1963

The conorable John W. Conlin Judge of Probate Washtenaw County Court House Ann Arbor, Michigan

> Re: Washtenaw County Dotention Pacifities Platt Road Ann Arbor, Michigan

Dear Sir:

A fire inspection was made, as requested, of the above named facilities on February 20, 1963. Supervisor of the detention home, John W. Shanahn, was interviewed at the time of the inspection.

At the time of the inspection there were seven male and four female residents beside the Supervisor and his wife. Mr. Shanahn informed me that there were two week end directors. Mr. Grimm and wife from Ypsilanti and Mr. Thompson and wife from Ann Arbor.

Housekeeping within the home itself was very good and the director should be commended for his efforts. The only problem was to have the Washtenaw County refuse collection truck pick up the refuse in the garage and the Christmas trees outside and to the rear of the garage. The director informed me that he had been promised pick-up service but because of the weather conditions had been unable to get it on a regular basis.

If there should be any question concerning this inspection, or if I may be of any further service, feel free to call 663-4130 at any time.

Yours truly,

John R. Williams, Pire darshal City of Ann Arbor, Eichigan

Jan Relyllians

cc: Childrens Division
Washtenaw County Unit
Department of Social Welfare

Mr. John W. Shanalm



STATE OF MICHIGAN

DEPARTMENT OF SOCIAL WELFARE

Children's Division Washtenaw County Unit P.O. Box 1085 Ann Arbor, Michigan

R. BERNARD HOUSTON
DIRECTOR

SOCIAL WELFARE COMMISSION

W. REED ORR, CHAIRMAN
HERBERT SCHINDLER, JR., VICE-CHAIRMAN
JACK POWELL
REV. CHESTER J. PILARSKI
MRS. ELOISE WHITTEN

January 30, 1964

Mr. Ernest Heller
Fire Chief
Ann Arbor Fire Department
Ann Arbor, Michigan

Re: Washtenaw Co. Detention Facility
Platt Road
Ann Arbor, Michigan

Dear Mr. Heller:

We are responsible under the provisions of Act 280 of the Public Acts of 1939, as amended, for the inspection of juvenile detention facilities. To assure the safety of the children in such institutions the rules of and regulations fixed by the Social Welfare Commission necessitate an annual fire inspection. Therefore, we would appreciate having a member of your Department inspect the above Facility.

Please send your report to Honorable John W. Conlin, Judge of Probate, Court House, Ann Arbor, with two copies to this office at the above address.

Should your representative wish to confer with me please call me at 663-4296.

Sincerely,

CH:ed

Clarence Hammer, District Consultant

(UofM, - School of Tublin Mottel)

CO2 - Lorder Room - 1962 -

Male - 7 Fanale - 4

FEBRUARY 4, 1964

CLARENCE HAMMER, DIST. CONSULTANT DEPT. OF OCIAL WELFARE CRILDREN'S DIVISION WASHTENAW COUNTY ONIT P.O. DOX 1085 AND ARBOR, CICHIGAN ARBOR, CICHIGAN

AE: WASHTERAU CO. SETENTION FACILITY
2250 PLATT RD.
ANN ARBOR, RICHISAN

DEAR MAR MARMER:

A FIRE INSPECTION MAS MADE OF THE ABOVE NAMED FACILITY ON JANUARY 4, 1904, AS REQUESTED.

OR. J. SHANAPN SHOWED U. THROUGH THE FACILITIES. WE FOUND THE FACILITIES CLOAD AND ORDERLY. THE ONLY CONSECTIONS NECESSARY FOR COMPLETE COMPLIANCE WITH STATE AND LOCAL REQUIREMENTS ARE AS FOLLOWS:

- 1. Fine extinguishers The fire extinguiohe is throughout the facilities have not been checked singe April, 1962. It is our recommendation that a qualified fine extinguioher serviceman again be called to check and service the extinguioher uishirs.
- 2. AIR POLUTION TEST EQUIPMENT THIS EQUIPMENT, STATIONED WEST OF THE GARAGE, IS OPERATING ON A LONG ELECTRICAL CORD PLUSSED INTO AN OUTLET IN THE GARAGE. THIS COLD IS GUN UNDER THE GARAGE DOOR AND THEN UNDERGROUND TO THE EQUIPMENT.

THE ELECTRICAL CORD IS NOT AN APPROVED TYPE FOR SURTAL UNDERGROUND AND WHERE IT PASSES UNDER THE BARAGE BOOR A BREAKDORN COULD OCCUR AT ANY TIME.

IF THIS UNIT IS TO CONTINUE TO BE USED WE RECOMMEND THAT AN EXTERIOR OUTLET BOX BE PROVIDED ON THE WE T SIDE OF THE SARAGE AND APPROVED UNDERGROUND CASLE SE USED TO CONNECT THE UNIT TO THE ELECTRICAL SOURCE AT THE MARKER.

IF THE A THE AREA TO ARE OUT LOTED, PROTESTED WILL THE . IT IN NORW GOOD CONDITION.

FORTHER DESCRIPTION, WE WAY SE CONTRACTED BY YOUR AT SECTION OF BY MAIL.

Yours TRULY,

Special allians, I me source

Melan J. Lee, Francisco

Do: John A. AFAMANN

John A. BONLIN, JUDGE OF PROBLE

DOURT HOUSE

AND THOMAS, FIGHIERS

J -/ AB

Mr. Radmilo Grdjich, Mgr. Juvenile Detention Home 2260 Platt Rd. Ann Arbor, Mich.

Dear Sir:

For our record and to confirm our conversation of Jan 5,1961 at which time a fire inspection was made of the Juvenile Home at 2260 Platt Rd., the following conditions were found.

Extinguishers: 1. Extinguishers should be checked annually and a dated tag should be on them.

Electrical: 1. A wall switch in bathroom was found to be broken. This should be replaced.

Any questions concerning this inspection or on fire prevention will be answered by contacting the fire prevention bureau of the Ann Arbor Fire Dept. at NO 3-4130.

cc: Mr. Carl Johnson County Administrator

Mrs Koons, Juvenile Div.

Yours Truly

Nolan Lee, Fire Inspector

Ben J. Zahn Jr., Fire Inspector

2270 Platt.

Memorandum

To:

Scott Ryan, Fire Marshal City of Ann A rbor RON HEEMSTO

From:

Anne King-Hudson Add

Date:

October 8, 1997

Subject:

Review of Washtenaw County Juvenile Court Emergency

Response Plan

Fire Marshall Ryan, enclosed is a copy of the Juvenile Court's Emergency Response Plan. Thank you for your willingness to review our plan. We would like to, at your availability, train staff as soon as possible. Thank you.

Anne King-Hudson 971-3147

·

4 7 000

tropped?

WASHTENAW COUNTY JUVENILE COURT

EMERGENCY RESPONSE PLAN

GENERAL EMERGENCY PLANNING

<u>PURPOSE:</u> This emergency manual sets forth the procedures and responsibilities for responding to certain emergencies which may occur within the Juvenile Court building. While not every conceivable emergency can be planned for, it is feasible to identify major possibilities and to consider the best general approach to dealing with them.

<u>SCOPE:</u> This plan concerns itself with the Washtenaw County Juvenile Court facility and the occupants.

<u>CONCEPT OF OPERATIONS:</u> The concept of this plan is to provide an outline for dealing with specific emergencies. The Court Administrator, as the on-site coordinator of the emergency response plan, will authorize non-court personnel to take command of the emergency situation and a command site will be established. And at such point in time that the non-court emergency commander declares the area safe, the Court Administrator will resume command of the court facility.

DEFINITIONS:

- A. <u>Emergency:</u> An unforeseen, sudden event that calls for immediate, extraordinary action to protect human safety and/or public property. Examples: Fire, Bomb Threat, Hostage Situation, Flood, CivilDisturbance, Riot, Shooting, SniperSituation, Tornado, Chemical/Biological/Radiological Incident, Armed Robbery, Medical Emergency, Courtroom/Building Seizure, etc.
- B. <u>Emergency Response Team</u>: Team of staff, which includes a decision-maker, and staff from departments who assist in an emergency. Their main functions include (establishing and maintaining communication with the command center and building evacuation). Court Administrator as a team leader will designate Emergency Response Team members.
- C. <u>Command Center</u>: The location of the command center will be the O'Brien Center, to be staffed by emergency personnel in an emergency or evacuation. The source of primary communication with emergency response agencies will be landline, with (staff emergency alert systems) and an announcement over the paging system. The secondary means of communication with emergency response agencies will be cellular phones and with verbal commands to the court staff.
- D. <u>Evacuation</u>: When an emergency evacuation is needed, the same evacuation plan described in this manual will be utilized.

E. <u>Accommodation of Physically Handicapped:</u> When an emergency evacuation is necessary, handicapped individuals may need special assistance. The following will be helpful in a safe evacuation and communication during an emergency. Above all else, involve the individual. They are the experts on their own disabilities and how best to move them out of a building in an emergency. Make sure that he/she understands what is happening and what procedure must be followed. Many disabled people are vulnerable to respiratory complications – remove them from smoke or fumes immediately.

<u>Mobility Impairments Persons:</u> Individuals having mobility impairments may or may not use wheelchairs. Immediately notify emergency personnel about the location and condition of the person with the mobility impairment so that emergency personnel can safely transport the individual to a safe area.

<u>Visual Impairments:</u> Most blind or visually impaired persons will be familiar with their immediate work area, it is necessary to:

- a. Explain the nature of the emergency.
- b. Offer to guide him/her. As you walk, explain your destination, where you are, any obstacles, which way you are going to turn, the number of steps, etc.
- c. Upon reaching safety, orient the individual to his/her surroundings. Ask if further assistance is needed. Stay with him/her.
- d. Be alert to presence or use of assist aids, i.e. Guide Dog, cane, etc.

<u>Hearing/Speech Impairments:</u> Communication varies with persons who are deaf, hard of hearing, or speech impaired. Audible alarms may not be heard. It is important that everyone understand what is happening, how and where to proceed. To gain attention, turn the light switch on and off, tap his/her shoulder, wave your hands, etc. Indicate through gestures, or in writing (short concise words), what is happening and what to do. Example: FIRE – out rear door to the right and down. Leave NOW!

ABOVE ALL, REMEMBER THAT PEOPLE WITH SIMILAR DISABILITIES ARE UNIQUE. THROUGH BRIEF COMMUNICATION AND ASKING QUESTIONS, EVACUATION CAN BE QUICK AND SAFE.

- D. <u>Annual Review of Emergency Response Plan:</u> A annual review of the emergency response plan will occur by the Safety/Security Committee updating:
- a. Emergency Response Team assignments.
- b. Updating evacuations routes diagram and directions
- c. Training on new policy (distribution of the new policy)
- d. Review annual checklist (evaluate performance on drills)
- e. Update emergency response equipment
- f. Update Staff/Family Emergency notification list

G. Command, Control and Communications:

For All Emergencies: The Court Administrator is the designated Team Leader. In the event that the Court Administrator is not available, the chairperson of the Safety/Security Committee will provide leadership, etc. Otherwise the Safety/Security chair will assist the Court Administrator in coordinating communication and disseminating information. The Emergency Response Teams will be made up of members of the Safety/Security Committee and designated supervisors. Three teams will be established to ensure an orderly evacuation of the court facility. The Court's receptionist is the official roll caller. Casework Supervisors, the Chief Clerk, and Probate Register will report to her and account for staff in their department. The receptionist will take roll call for all other personnel including the Legal staff, auxiliary staff and the public. The receptionist will report to the team leader. The bailiff will establish the safety of the Judge and escort him/her to the command center.

SECTION: ALL STAFF

SUBJECT: EMERGENCY EVACUATION

<u>POLICY:</u> TO ENSURE A SAFE AND ORDERLY RESPONSE TO AN EMERGENCY. ALL STAFF WILL ADHERE TO THE EMERGENCY EVACUATION PLAN AS OUTLINED BELOW:

<u>RATIONALE:</u> To establish a systematic method of safe and orderly evacuation of the building and its occupants in an emergency,

<u>DEFINITIONS:</u> All fire alarms orders for evacuation and drills require evacuation of the building.

Designated assembly area – the field beyond the front parking lot.

Designated command center - O'Brien Center.

<u>PROCEDURE:</u> The occupants are to exit from the designated emergency door and proceed to the designated assembly area.

All building occupants must report to the designated assembly area, the Receptionist will take roll call. <u>DO NOT</u> leave this area until instructed to do so. All instructions will come from the command center. No one is to leave the assembly area for any reason without instruction from one of the Emergency Response Team members.

NOTE: For those involved, take your personal belongings with you before leaving the building, if they happen to be next to you, as you may not be allowed to re-enter the building for an extended period of time. DO NOT GO BACK INTO THE BUILDING TO FIND YOUR PERSONAL BELONGINGS!

RESPONSIBILITY:

ACTION STEPS

Emergency Response Team

- A. Put in identification tags.
- B. Take a copy of this plan with you.
- C. Assign a specific person(s) to assist any handicapped employee. Assist physically the Physically handicapped as the first priority
- D. Implement the evacuation plan, and have the staff assemble in the designated assembly area.
- 1. Use pre-planned fire evacuation routes.
- 2. Ensure the evacuation of your entire area.
- 3. Proceed to pre-assigned assembly areas.
- 4. Report progress to the command center.
- 5. Keep staff together and await instructions.
- E. Assist the Command Center
- F. Maintain liaison with the on-scene professional commander and report developments to the Court's Command and Control Team.
- F. Verify evacuation of the Youth Home with designated Team Leader from the facility.

<u>Team #1</u>

Area covered: Lobby-waiting area. Courtroom #2, Public restrooms, clerical offices, staff lunchrooms and Judges chambers, and everything to the left of the courtyard hallway.

Emergency Team members will be stationed at the following points to assist in the evacuation.

- 1. One team member at the front entrance/exit.
- 2. One team member mid hallway (at the detention door).
- One team member to roam the designated area, to alert and assist in the evacuation of Handicapped individuals. Occupants will be directed to use the front door and proceed to the designated assembly area.

Team #2

Area covered: Courtroom #1, Casework wing, Courtroom #3, staff restrooms, Conference room – everything to the right of the courtyard hallway. Team member will be stationed in the following manner:

- 1. One team member stationed at the rear entrance.
- 2. One team member to notify Casework staff
- 3. One team member to alert occupants of the conference room and Courtroom #1&3,

Team #3

Area covered: The outside perimeter of the Court facility. Team members will be stationed in the following matter:

- 1. Security personnel will walk the perimeter of the Court facility to ensure that staff assemble in the designated assembly area
- 2. One staff will be posted at the front of the court and one in the street at the entrance to the court facility, to direct emergency vehicles.

Court Administrator

Report the Command Center. Make necessary decisions regarding the Emergency. Assist responding agencies.

- a. Call the Ann Arbor Fire Department (911), if needed. \
- b. Notify: Washtenaw County Sheriff's Department to cancel prisoner appearances (971-8400 x 1314), if necessary.
- c. Place public notice signs on the inside of the glass doors advising the Public of the necessary procedures. The Administrative Secretary will keep the signs.
- d. Secure cash, checks, and money orders in the safe. If no time, lock the cash drawers and take the keys.
- e. Maintain a chronological log of events.
- f. Ensure that the court is secure. Maintain watch on building. See that private citizens remain in safe areas.

NOTE: IF THERE IS NO TIME TO DO THE ABOVE DURING EVACUATION END THE DESIGNATED STAFF TO REMOTE PHONES AND MAKE ALL CALLS FROM THERE.

Court Administrator:

Determine whether the Judges and staff are to remain in the assembly areas or to be sent home.

Probate Register:

Upon returning to the building, check all calendars and docketed appearances that were missed, reschedule and notify all parties as required.

Washtenaw County Sheriff's Dept. and Department Of Corrections Transport Officers:

Follow your department's procedures for evacuating prisoners from the courtroom and/or prisoner holding areas.

FIRE EMERGENCY

PROCEDURE

REPONSIBLILITY:

ACTION STEPS

ALL STAFF

A. Reporting

1. Notify the Court Administrator, Judge, and Supervisor.

2. Activate the fire alarm by pulling the alarm located by the back vestibule.

- 3. Dial 8-911. State "that this is a fire emergency." When connected with the fire department, or at the operators request:
- a. Your name
- b. The court's address: 2270 Platt Road, Ann Arbor, MI 48104.
- c. Exact location of the fire.
- d. Describe any injuries, if any.

A. Response

WHEN A FIRE ALARM IS ACTIVATED:

- 1. Proceed to the nearest safe EXIT. FOLLOW DIRECTIONS OF THE EMERGENCY
- 2. Feel the top of the door. If it is hot or smoke is visible, do not open.
- 3. Do not attempt to save possessions at the risk of personal injury.
- 4. DO NOT BREAK WINDOWS. Oxygen feeds fires.
- 5. Stay low if moving through smoke.
- 6. Go to the designated assembly area.
- 7. Await further instructions from the assembly area.

IF TRAPPED IN A ROOM.

- 8. Place cloth material around/under the door to prevent smoke from entering.
- 9. Close as many doors as possible between you and the fire.
- 10. Be prepared to signal your location through the window.
- 11. Use the fire extinguisher (if appropriate).
- 12. Refer to the Court Emergency Closure Checklist

Upon arrival of the Fire Department

- 13. Senior Fire Officer assumes command.
- 14. Follow Fire Department orders

Assembly, Reporting, and Recall

Following evacuation, all personnel will assemble in the designated area. The receptionist will take roll call and report to the Emergency Response Team leader. If anyone is thought to be trapped in the building or is unaccounted for, report the information to the Fire Department Commander at once

Fire Extinguisher

INSTRUCTIONS:

- P PULL the safety pin from the handle
- A AIM the nozzle at the base of the fire
- S SQUEEZE the trigger handle
- S SWEEP the spray from side to side

Telephone Bomb Threat or Suspected Mail Bomb

RESPONSIBILITY

ACTION STEPS

ALL STAFF

- A. Telephone Procedures Threat
- 1. Use the Telephone Bomb Threat Checklist
- 2. Get all the information possible
- 3. Take every threat seriously, treat as real until proved otherwise
- B. Suspected Mail or Package Bomb

If a suspicious letter or parcel arrives DO NOT OPEN IT. When in doubt, treat the package as a real bomb. DO NOT HANDLE OR TRANSPORT. NOTE: DO NOT USE CELLULAR TELEPHONES OR RADIOS. DO NOT ACTIVATE OR DEACTIVATE ANY ELECTRICAL MACHINES OR SWITCHES. ELECTRICAL DEVICES MAY DETONATE BOMB.

A. Reporting

- 1. Notify the Court Administrator, Judge or Supervisor.
- 2. Dial 8-911. State that this is a Bomb Threat Emergency.
- 3. When connected to the police department, or at Operators request give:
- a. Your name
- b. The court address: 2270 Platt Road, Ann Arbor, MI 48104
- c. Exact location of bomb, if known time when the bomb is to explode, if known

RESPONSIBILITY

ACTION STEPS

COURT ADMIN. WCSD, AAPD

- A. Will alert all appropriate persons/agencies
- B. Will respond to location and take command
- C. Evacuate the building or area instructed by the on-scene Police Commander to do so. Assemble in the designated assembly area.

NATURAL/CIVIL DISASTER

PROCEDURE

RESPONSIBILITY

ALL STAFF

ACTION STEPS

- 1. Reporting
- a. Locate the nearest working telephone. If no working phones can be found, use the cellular phone located in the receptionist's desk. If no phones or radios can be located, a Emergency Response Team member will be sent to the Sheriff's Department to report on the situation.
- b. Call 8-911. State the type of emergency. When connected with the Ann Arbor Fire Department or WCSD/Ann Arbor Police Department, or at the operators request:
- 1. Your name
- 2. The court address: 2270 Platt Road, Ann Arbor, MI, 48104
- 3. Nature of the emergency
- 4. Situation and extent of injuries as known.

Emergency Response Team

- A. Take command and begin organizing relief/assistance groups to help the injured.
- B. Use fire extinguishers as necessary.
- C. Evacuate the building and assemble in designated area.

Upon arrival of Emergency Response Professionals

- A. Senior responding agency official assumes command.
- B. Follow professional's orders.

MEDICAL EMERGENCY

Procedure

RESPONSIBILITY ALL STAFF

ACTION STEPS

Medical emergencies are likely to occur in the court environment. Key points to follow in establishing a medical emergency policy are:

Key people will be trained in First Aid or Advanced First Aid, and CPR. *An updated list of trained staff will be kept at the front desk and will be notified by the Receptionist (in an order to keep a calm and secure atmosphere, NO PUBLIC announcement will be made). *First aid kits, including a Blood Borne Pathogen kit will be available in each courtroom, the front lobby the staff lounge, the library, the conference room, the hallway of the casework wing, as well as each staff restroom accessible to staff in the event of an emergency.

For use event of a Medical Emergency an updated emergency family notification list will be kept by the receptionist as well with Human Resources for notification of family members.

Accessibility Issues:

Emergency vehicle arrival area and parking. In the event that a medical emergency should occur, the Emergency Response Team will ensure that the emergency vehicles have clear access from the building.

RESPONSIBILITY CPR TRAINED STAFF

ACTION STEPS

- A. Provide emergency first care as the situation requires .
- B. Unconscious victims (if the rescuer is trained in CPR)
- 1. YELL FOR HELP, THEN HAVE SOMEONE CALL 911
- 2. Establish airway
- 3. Check for breathing
- 4. Check for circulation
- 5. Start ventilation or CPR if necessary

C. Conscious victims

- 1. YELL FOR HELP, THEN HAVE SOMEONE CALL 911
- 2. Do not move patient or allow the patient to move around
- 3. Try to control any heavy bleeding using direct pressure on the wound.
- 4. Try to keep the patient from going into shock by maintaining body temperature and elevating the lower extremities if possible.

D. Reporting

- 1. Call 911. State "this is a Medical Emergency" when the EMS Department is on the line, or as requested by the operator, give:
- 1. Your name
- 2. The court address: 2270 Platt Road, Ann Arbor, MI, 48104
- 3. The nature of the emergency.
- 4. Description of the victim.
- 5. Give exact location of the victim and suggest which building entrance to use.
- 6. Write an incident report

ALL STAFF

- 1. Remain with the victim(s) and continue care.
- 2. Soothe and calm the victim.
- 3. Do not move the victim unless required by life-threatening circumstances.
- 4. Clear obstructions from the area.
- 5. Send someone outside to direct Paramedics

When Paramedics arrive

- 6. Senior Paramedic assumes command
- 7. Follow Paramedics orders
- 8. Write an incident report

SEVERE WEATHER

PROCEDURE

ACTION STEPS

RESPONSIBILITY EMERGENCY MANAGEMENT

 Family Court Juvenile Division through the county quick call and SYSM of Severe Weather

COURT ADMINISTRATOR

- A. Will determine at which point the building occupants will be instructed to take cover.
- B. Will instruct the Receptionist to make a general announcement over the paging system THAT ALL BUILDING OCCUPANTS ARE TO TAKE COVER IMMEDIATELY.

ALL STAFF

- C. All building occupants should immediately report to Courtroom #2.
- D. If there is time, all staff should power off all electrical equipment.
- E. Roll call will be taken by the receptionist

Emergency Response Team

F. Emergency Response Team will follow the directions of the Court Administrator or the designee as outlined in the Command, Control and Communication policy

Court Administrator

- G. Teams 1 & 2 will evacuate their specified areas.
- H. Once notice of the all clear is received from the office of Emergency Management will make the determination on when all building occupants can return to work and/or leave the building.
- Court Administrator along with the Emergency Response Team will check the building for damage, and report such damage to Facilities Management

GENERAL POWER FAILURE

RESPONSIBILITY COURT ADMINISTRATOR

ACTION STEPS


- A. Will decide on whether or not staff is to remain at their work stations or released to leave the building.
- B. All office machines (i.e. computers, printers, etc.) shall be powered off

NATURAL GAS LEAKS

RESPONSIBILITY ALL STAFF

ACTION STEPS

- A. Upon detection of an odor suspected to be natural gas, immediately inform the Administrator 971-2182, Michigan Consolidated Gas and Facilities Management B. Follow the Evacuation policy.



ANN ARBOR FI 111 N. Fifth		DEPARTMENT enue 994-2774	F-3	40104		A FIRE PREVENTION CODE IC OCCUPANCY REPORT	
ADDRESS 2777		Platt Par Su Jun A	<i>K</i>	48104		- 92 . .	
Property Names /		The state of the s	7	Date: 7/2	· —	- 73 Time:	
Topant Name:	4.3.	, Su and	72	Emergency Conta	cts		· · · · · · · · · · · · · · · · · · ·
Personality Parker	5 =	- VKV 4	Je -	tent, N dy HR	17	771-137 1/04-134-79 131-131	0
Auto Contain Party:		2/1 Dudle	"//-	<u> </u>	111	104 134- 79	61
Auto Sprinkler:	. A .	Standpipe & Hose C	a bın	ets: Fire	Pump): <u>/</u> 37, 13,	54
Cocation of Fire Depart	ment	Standpipe & Hose C Connection: 50 a ic Manu	<u> </u>	THORN	2/6)	
rire Alarm: Aut	omat	el: Contral	al	Alarm Co	• _		
Fixed Property Head	ran	el: Con not	120	CM			
Number Of Steries Comme	- برانست الداما	By Tenant: / +	0	Type Of Bldg. C	onst	Makonky	
wamper of Scories occup	160	by Tenant:	<u> </u>	Total Floor Are	a 01	Tenant Space:	
Viola	tior	Viola	tion	Viola	tio	Violat:	ion
EXITWAYS	1	ELECTRICAL	T+	SPRINK & STANDPIPE	Ī	SPRINK CONTROL	1
Proper Number		CONTROL PANEL		RISERS & VALVES	I	Open	
Obstructed		Access		Condition	1	Accessible	
Arrangement		Properly Marked	1	Accessible	1-	Condition	
Door Swing		CIRCUITS	I	DRAINS	11	F.D. CONNECTION	- 1 /
Locks	7-	Proper Sizes	1	Marked	+=	Accessible	- -
Panic Hardware		Identified	1	Accessible	+	Swivels Working	
STAIRWAYS	7	Unused Opening	1	SPARE HEADS	1	Cap & Plugs	-+-
Proper Number		OUTLETS	1	Available	+	Threads	
Width	ļ	Proper Location	17	Wrench	 		
Arrangement		Proper Number	 	FIRE PUMP	ر ا	S, E, GRINGR COMPRESSED GAS	
Door Swing	ļ	Covers	 	Enclosed in Room		 	-
Hold Open Device		EXTENSION CORDS	+-	Condition	 	Chained	
Locks		Condition	/	SPRINKLER COVERAGE	-	Storage	
Panic Hardware		. Use	├	HOSE STATIONS	P	Other	
AISLES		CHESS LIBERTY	La	HUSE STATIONS	<u> </u>	FLAMMABLE LIQUID	$-\!$
Proper Width			1	COTHER ESCULIFICAS	0		
		Adequate Ger	0	LIN DINING ROOM	<u> </u>	Dispensing	
Arrangement INTERIOR	7	BATTERY UNITS	a	FIRE ALARM SYSTEM	ļ	Sources Of Ignition	
	土	EXIT LIGHTS Garage	1 2	CONTROL PANEL	1+	No Smoking Signs	
Condition		EXIT LIGHTS Care	0	Accessible		Class B Extin.	
5705 (444.6		Working		Identified	<u>. </u>	OTHER	
FIRE WALLS	+	Properly Located		PULL STATIONS	4		
Condition	· .	EXPLOSION PROOF		Accessible		PORT FIRE EXTING.	1-
Fire Doors		Condition	<u> </u>	Working		Condition	
Operation		Seal Offs		DETECTORS	1	Location	
Hold Open Device		ELEVATOR SHAFTS		Location	Ľ	Type	
STORAGE		Emergency Key:		Working		Access	
Condition Paring	0	Stop		OTHER		Other	
Height		Equipment Room				GAS METER	1
Housekeeping 🗼	0	HOOD & DUCT SUPP.		SUPERVISION		Condition	
No Smoking Signs		Condition Wetwo	17	Sprinkler System		Protection	
CEILING	1	Serviced ///		Fire Alarm System		ADDRESS	+
Condition		Serviced A/5		Sprinkler Valve	-	Adequate	+
PERSON INTERVIEWED: // Remarks Or Instructions	For	Elimination Of Fire Haza	ards	in concidor		OK 16-20-4 OK 10-20-9	§ ,3
You are hereby requested A re-inspection will be	d to mad	remedy the above noted	viol	ations of the Fire Prevent	ion	Ode within 14 days.	}
Symbols: 0-Violation 1-7 Revised 1/1		+-No Violation /-I		Not Pertain		•	



Exposed area for Phase I: Approximately 775 ft. square Washtenaw County Juvenile Detention Center

APPENDIX C CITY DIRECTORIES



BONDS

Phone
Normandy

8-7769

LIBERTY STREET

	1940
PLATT ROAD - From 2960 Washtenaw	3424 H
rd south to city limits	
2131 Hobbs L P	
2153 Bell Peter W ⊚ △NO3-0193	
2203 Wilson Dairy Co (ice cream div) ANO3-2459	3432 D
2231 Vacant	3521 E
2257 Stadium Tool & Die Co ANO2-6132	3540 A
2260 County Juvenile Detention Home ANO5-5501	3545 S
Grdiich Radmilo	3570 Y
2275 Pittsfield Products Inc mfrs agts	3580 T
ANO3-5753	3592 P
Veega Inc ming a men Allon	3604 N
es Community Park	3616 M
EQUEWOOD hand-	3630 G
	3680 N
2551 DeSautel Henry A @ ANO3-8833	3596 R
2551 DeSautel Henry A © ΔNO3-8833 2579 Lowther Allen T © ΔNO3-4919	JOBO AL
	3746 Za
The state of the s	-
2709 No Both J @ ANO3-2389	
2723 Kroon Fd.	PLEASAN
2723 Kroon Edwin H © ΔNO3-6809 2737 Soll Carl H © ΔNO3-6819	SON AV

101 -

		1465
76	PLATT RD-From 2960 Washtenaw rd	3472 Ja
	south to city limits	3476 W
dy	2131 Vacant	Lorrai
35	2153 Bell Peter W @ NO3-0193	3521 E
	2203 Wilson Dairy Co (stge)	3540 T
(16 (868))	Mitchell D J Assoc pub relations	3546 S
	NO5-7658	Washir
	2231 Mich Tub Benders Inc 665-8511	3570 D
	A A Welding Sup Co NO3-7826	3580 T
	2260 County Juvenile Detention Home	3592 P
	2275 Applied Dynamics Inc electronic	3604 P
	equip 662-4493	3616 N
	es Community Park Edgewood begins	3630 C
	Edgewood begins	3680 S
	2504 Brundage Harold non responsive	3696 R
	2510 Ferguson Arth E	3746 Z
	2516 Hantula Carl W	Name of Street, or other Designation
	2520 Barroso Andre A @ non responsive	
	2537 Kerwin Thos J	PLEAS
2 1	2551 DeSautel Henry A @ NO3-4010	sou
	2551 DeSautel Henry A © NO3-4919 2579 Lowther Allen T © NO3-2970	101 Gr
	Ownwood begins	105 Jo
4	2647 Witcher Chas P @ NO2-7225	106 Ch
	2673 Bindeman John H @ 662 5420	1 100 0

PLATT RD -FROM 2960 WASHTENAW RD SOUTH TO CITY LIMITS

ZIP CODE 48104

2153 Bell Peter W @

2203 Vacant




2253 Vacant

2260 County Juvenile Detention Home 971-4030


2270 County Juvenile Court Center 971-7100

2275 Applied Dynamics Inc marketing 971-4444

Community Park EDGEWOOD BEGINS



117	ZIP CODE 48104 non responsive	3050 B
7	2153 Bell Peter W @ non responsive	3051 M
13	2231 Ann Arbor Welding Supply Co-A A	3053 A
	Therapy Oxygen 971-3330	3071 N
	Chemotronics Development Co (Div	3080 1
	Internl Inc) research & development	3083 V
	971-4060	3100 S
-4308	2260 Washtenaw County Vocational	
	Residential Center 971-7870	3110 8
	Center For Occupational & Personalized	3122*
	Educ	3123 N
	2270 County Juvenile Detention Home	3140 I
	971-7100	3150 F
	County Juvenile Court Center 971-7100	3165 (
	2275 K L T Industries Inc 973-0600	3166 S
52	Delton Somian M. d. J. O.	3178 H
CKARD RD	Dalton Service Master hae cln 973-1555	3190 H
RD	Communities International consultants 971-1723	RED
		3207 V
	Environmental Products waste water	3210 S
3	a caunent equip 973-1666	3222 R
62	ALL Arbor Art Assoc 972 0500	3241 V
	VIICII Pr Park	- N
0	EDGEWOOD BEGINS	3243 V
325	Washtenaw United Wass 071 8900	3245 m 3250 M
1457	Voluntary Action Conton welf and	0800 1



PLA	TT RD -FROM 3000 WASHTENAW	3150 Vacant 3165 Cruse Ro
KI	SOUTH	3166 Salow W
Z1)	P CODE 48104	3178 Kelp W
2203	Transplantation Society Of Michigan	REDWOOD 3210 Wright 1
9921	clearing agey 973-1577	3222 Vacant
LLUI	Ann Arbor Welding Supply Co (A A Therapy Oxygen) 971-3330	3241 Trembla
	U C R Automotive auto repr 971-6362	3243 Carlisle 3245 No Retu
2260	O'Brien Francis L Center For Youth Dev-Cope 971-7870	3247 Mills Vi 3249*Yvon M
	Center For Occupational &	3250 Flora Cl
	Personalized Educ alternative educ 971-7870	3251 Freed K 3253*D'Angel
	O'Brien Youth Development Center counseling serv 971-7870	3255 O'Drisco
2270	County Juvenile Detention Home	3261 * Moorehe 3263 * Butler J
441V	994-1800	3265 Arbour I
	County Juvenile Court Center	3266*Fields S
	994-1800	3267 Vacant

		1984
	2275 Ann Arbor Skate Co amusement	326
	places 971-2211	327
	Sheffler Park	32
	2301 Washtenaw United Way 971-8200	32
	Volunteer Action Center 971-5852	32
	Washtenaw Camp Placement Assn	32
	971-4537	32
	Washtenaw Council On Alcoholism	32
	971-7900	32
59	Child & Family Service Of	32
6	Washtenaw County 971-6520	33
12	Child & Family Service drug	
	treatment prog 971-8132	
237	Ann Arbor Area Foundation 971-23	33
	Hemophilia Foundation Of M.	55 33
970	Hemophilia Foundation Of Mi 973-0305	
1		
	2504 Tapp Kenneth C non responsive	33
-8250	2510 Ferguson Arth E @ non responsive	
	2516 Hantula Carl W 💿	
	EUEV Wentworth Was 1 6 on a new	

9 Meredith Wm 10 Taylor Stella

PLATT RD -FROM 3000 WASHTENAW RD SOUTH

ZIP CODE 48104

2203 Organ Procurement Agency Of Michigan organ procurement agey 973-1577

2231 V C R Automotive repr 971-6362

Rear Ann Arbor Welding Supply Co 971-3330 Rear Ann Arbor Therapy Oxygen Co 971-8353 ws County Farm Park 2260 Francis L O'Brien Center For Youth Dev-C O P E 971-7870	189
Rear Ann Arbor Therapy Oxygen Co 971-8353 ws County Farm Park 2260 Francis L O'Brien Center For Youth Dev-C O P E 971-7870	32
ws County Farm Park 2260 Francis L O'Brien Center For Youth Dev-C O P E 971-7870	32
2260 Francis L O'Brien Center For Youth Dev-C O P E 971-7870	32
Dev-C O P E 971-7870	32
	32
Center For Occupation & Personalized	32
Educ (COPE) alternative educ 971-7870	32
O'Brien Youth Development Center	82
counseling serv 971-7870	82
2270 County Juvenile Cntr 971-2240	32
County Juvenile Court 971-2240	32
2275 Ann Arbor Skate Co 971-2212	32
2301 United Way Building	32
Washtenaw United Way 971-8200	32
Volunteer Action Center 971-5852	32
Washtenaw Council On Alcoholism	32

FLATT RALL FROM 3000 WARRITENAW

· ZIF CODE 48104

EXECUTE OF CAN PROVIDE MENT AGENCY OF MICHIGAN OFFAR DOWNERS OF ACTION OF AC

REST SELECT ATTEMPTIME INC. tops 971 6063

& mery 677 1211

ME COUNTY FARM PARK

2303 FRANCIS L OTHRIEN CENTER FOR SOUTH DEV C O P E 071-7870 CENTER FOR OCCUPATION & PERSONALIZED EDUC (COPE)

Mistablive educ 971-7870

COUNTY JUVENILE COURT 971 1364
COUNTY JUVENILE COURT 971 2240

2001 INFORMATION LINE 971 9191 UNITED WAY BUILDING

WASHTENAW UNITED WAY 971.8200

2275 ANN ARBOR CIVIC THEATRE 971-0605 2301 INFORMATION LINE 971-9191 UNITED WAY BUILDING WASHTENAW UNITED WAY 971-8200 VOLUNTEER ACTION CENTER 971-5852 WASHTENAW COUNCIL ON ALCOHOLISM 971-7900 FAMILY COUNSELING CHILD & FAMILY SERV 971-6520 DOMESTIC VIOLENCE PROJECT INC SAFE HOUSE crisis intervention 995-5444

- * HURON PKWY INTERSECTS
- · CANTERBURY INTERSECTS

2504 Not Verified

es SCHEFFLER PARK city park

2510 Ferguson Arth E & Mary J 9+ @

non responsive

2516 Berube Julie [2]

2520 Wentworth Wm L & Debra 9+ @

non responsive


2526 Vacant

669

5 0

non responsive	2203	Beyersdorf T M III A TRANSPLANTATION SOCIETY MICH hith alld svcs	3250 Not Verified 3251@Colwell Kimberly J Colwell Charles
work Lynne D III om Marchalf J III	2231	CHARLES CUSTOMWORKS furniture stores 975-0050 Cho Steve Y 🗓+ 🏚 Cho Joong H	Gore K [2]
non responsive		V C R AUTOMOTIVE pnt & body rpr	3265 Kocisky Jo A [2] 3266 Not Verified 3267@Adamczak Kaine M @Williams Terrie L975-12 3269@Heeter Kathleen M @
non responsive A STORE A STORE 769-7610		Bullard Nadine E C O P E schs edotl svcs 971-7870 EDUCATION TRAINING RES SVCS spty otpnt clns	Heeter Adam J 975-68 3271 Fields Cecile V [7] & 3273 Allen Joseph T [2] Allen Mariloli P
Verified on Stephen B 19)+ A non responsive san Stephen A ar Todd F 121 A	2275	WASHTENAW COUNTY OF WASHTENAW JUVENILE COURT courts971-2240 ANN ARBOR CIVIC THEATRE thtrcl prdcrs svcs971-2228	3275 Strathearn Mark D 15 3277 Salow Wilbur A 15+ 4 3278 Barrett Jason M 151973-9 Barrett Deana B973-9
P Fanda P non responsive	2301	DOMESTIC VIOLENCE	3279 Kelsay R P 🖾
Marting C erner Benjamin A & 769-4867 rest Denyce G		WASHTENAW UNITED WAY social sycs971-8200 3 WASHTENAW AFFORDARI F HOUSING	+REDWOOD AVE INTERSECTS 3301 Psaros Michael W 15 3303@Marcum William T Jr973-1 Marcum Janice 973-1 3304@Pawittranon Tearawat

This d




ctory is property of Palk City De

PLATT RD Cont'd PLATT RD Cont'e WASHTENAW COUNTY 3165 Anderson Par JUVENILE DIV government offices-Anderson Pf 2275 VINEYARD CHURCH OF ANN ebbora A [28] 3166 Alzehairy Sa ARBOR churches 734-477-9135 .734-439-2033 2301 EXIMWARE INC computer serv NG & TRIM Chavis La .734-417-4565 @ Jefferson ILIUM SOFTWARE INC computer 3178 Peters Rene .734-439-5655 software734-973-9388 + REDWOOD AVE IN .734-439-5655 20 Morse Ken 3210 Young Yvonr is J 30 4 100 KAPLAN MITCH DDS dentists .734-439-8465 Young Yann 200 ARBOR DENTAL dentists 3222 Olegario Gil .734-439-1162 Richmond Ci 200 Jaffer Muhammad A 4 3238 Harrison Kev 200 Jaffer Amin M Harrison Mic 30 4 300 WASHTNAW COUNTY LEGAL 3241 @ Dobbin An .734-439-7626 NEWS newspapers .. 734-477-0201 Silcox Mark / 400 LEADE HEALTH health care ch Williams F

APPENDIX D AERIAL PHOTOGRAPHS






PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN






PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN






PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN PREPARED FOR

DOWNRIVER COMMUNITY CONFERENCE
SOUTHGATE, MICHIGAN






PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN PREPARED FOR

DOWNRIVER COMMUNITY CONFERENCE
SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN

PREPARED FOR DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN






PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN PREPARED FOR

DOWNRIVER COMMUNITY CONFERENCE SOUTHGATE, MICHIGAN





PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN PREPARED FOR

DOWNRIVER COMMUNITY CONFERENCE
SOUTHGATE, MICHIGAN







PHASE I ENVIRONMENTAL SITE ASSESSMENT WASHTENAW COUNTY JUVENILE CENTER 2260 AND 2270 PLATT ROAD ANN ARBOR, MICHIGAN PREPARED FOR

DOWNRIVER COMMUNITY CONFERENCE
SOUTHGATE, MICHIGAN



APPENDIX E SITE PHOTOGRAPHS





SITE PHOTOGRAPHS



Photo #1. Overview of the site.



Photo Eastern portion of the site looking #3: northwest.



Photo #5: Western portion of the site looking south.



Photo #2: Northern portion of the site looking west.



Photo #4: Southern portion of the site looking west.



Photo #6: Court and detention building.



SITE PHOTOGRAPHS



Photo #7: Pad mounted transformer.



Photo #8: Portable emergency generator.



Photo #9: Portable classroom.




Photo #10: Representative office.



Photo #11: Conference room.



Photo #12: Break area.



SITE PHOTOGRAPHS



Photo Northerly adjoining Washtenaw County #13: Park.



Photo Southerly adjoining single-family residential #15: property.



Photo #14: Easterly adjoining United Way (2305 Platt Road) and Vineyard Church (2275 Platt Road) beyond Platt Road.



Photo #16: Westerly adjoining Washtenaw County Park.

APPENDIX F ENVIRONMENTAL DATABASE REPORT



WCJC

2270 Platt Road Ann Arbor, MI 48104

Inquiry Number: 2738992.2

April 07, 2010

Certified Sanborn® Map Report



Certified Sanborn® Map Report

4/07/10

Site Name: Client Name: WCJC TTL Associates

2270 Platt Road 1915 North 12th Street
Ann Arbor, MI 48104 Toledo, OH 43604

EDR Inquiry # 2738992.2 Contact: Danielle Green



The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by TTL Associates were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: WCJC

Address: 2270 Platt Road City, State, Zip: Ann Arbor, MI 48104

Cross Street:

P.O. # 6324 **Project:** 6358.01

Certification # 77BE-4BDF-8491



Sanborn® Library search results Certification # 77BE-4BDF-8491

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress

✓ University Publications of America

▼ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

TTL Associates (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

WCJC 2270 Platt Road Ann Arbor, MI 48104

Inquiry Number: 2738992.1s

April 07, 2010

The EDR Radius Map™ Report with GeoCheck®




TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary	4
Map Findings.	7
Orphan Summary	
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map.	A-7
Physical Setting Source Map Findings.	A-8
Physical Setting Source Records Searched	

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2270 PLATT ROAD ANN ARBOR, MI 48104

COORDINATES

Latitude (North): 42.254300 - 42° 15' 15.5" Longitude (West): 83.702900 - 83° 42' 10.4"

Universal Tranverse Mercator: Zone 17 UTM X (Meters): 277031.5 UTM Y (Meters): 4681335.5

Elevation: 824 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 42083-C6 ANN ARBOR EAST, MI

Most Recent Revision: 1983

South Map: 42083-B6 YPSILANTI WEST, MI

Most Recent Revision: 1983

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 7 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
WASHTENAW CO JUVENILE DET 2270 PLATT RD	FINDS	N/A
ANN ARBOR, MI 48104		

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list	
NPL	National Priority Lis

Proposed NPL..... Proposed National Priority List Sites NPL LIENS..... Federal Superfund Liens Federal Delisted NPL site list Delisted NPL..... National Priority List Deletions Federal CERCLIS list CERCLIS..... FEDERAL FACILITY..... Federal Facility Site Information listing Federal CERCLIS NFRAP site List CERC-NFRAP..... CERCLIS No Further Remedial Action Planned Federal RCRA CORRACTS facilities list CORRACTS..... Corrective Action Report Federal RCRA non-CORRACTS TSD facilities list RCRA-TSDF...... RCRA - Treatment, Storage and Disposal Federal RCRA generators list RCRA-LQG RCRA - Large Quantity Generators RCRA-SQG..... RCRA - Small Quantity Generators Federal institutional controls / engineering controls registries US ENG CONTROLS..... Engineering Controls Sites List US INST CONTROL..... Sites with Institutional Controls Federal ERNS list ERNS..... Emergency Response Notification System State and tribal landfill and/or solid waste disposal site lists SWF/LF..... Solid Waste Facilities Database State and tribal leaking storage tank lists INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land State and tribal registered storage tank lists Aboveground Tanks INDIAN UST..... Underground Storage Tanks on Indian Land FEMA UST..... Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP..... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

ODI..... Open Dump Inventory

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

HIST LF..... Inactive Solid Waste Facilities

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

DEL SHWS...... Delisted List of Contaminated Sites CDL...... Clandestine Drug Lab Listing

US HIST CDL...... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System

LIENS....Lien List

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

SPILLS Pollution Emergency Alerting System

Other Ascertainable Records

CONSENT...... Superfund (CERCLA) Consent Decrees

TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

UIC...... Underground Injection Wells Database

DRYCLEANERS...... Drycleaning Establishments

NPDES.....List of Active NPDES Permits

AIRS..... Permit and Emissions Inventory Data

INDIAN RESERV..... Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER_____PCB Transformer Registration Database

COAL ASH...... Coal Ash Disposal Sites

COAL ASH DOE...... Sleam-Electric Plan Operation Data FINANCIAL ASSURANCE____ Financial Assurance Information Listing

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 01/13/2010 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GORDON CADILLAC LLC	3120 WASHTENAW	NNE 1/8 - 1/4 (0.220 mi.)	C10	16

State- and tribal - equivalent CERCLIS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Quality's' Contaminated Sites List on Diskette With Address.

A review of the SHWS list, as provided by EDR, and dated 02/01/2010 has revealed that there are 4 SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ANN ARBOR CIVIC THEATER Facility Status: Evaluation conducted	2275 PLATT ROAD	0 - 1/8 (0.000 mi.)	А3	7
ARBOR WASH Facility Status: See Leaking Undergro	3031 WASHTENAW AVE bund Storage Tank Site Database	N 1/8 - 1/4 (0.219 mi.)	B9	15
ARBOR DODGE Facility Status: Evaluation conducted	3365 WASHTENAW AVE	ENE 1/4 - 1/2 (0.384 mi.)	17	37
ARBORLAND MALL Facility Status: Interim Response in p	3693 WASHTENAW progress	E 1/2 - 1 (0.663 mi.)	19	45

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Quality's Leaking Underground Storage Tank (LUST) Database.

A review of the LUST list, as provided by EDR, and dated 02/22/2010 has revealed that there are 10 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STEVEN MURILLO Facility Status: Closed	3000 WASHTENAW AVE	N 1/8 - 1/4 (0.225 mi.)	13	26
GOODYEAR AUTO SERVICE CENTER Facility Status: Closed	3451 WASHTENAW	ENE 1/4 - 1/2 (0.477 mi.)	18	42
Lower Elevation	Address	Direction / Distance	Map ID	Page
ANN ARBOR FIRE DEPT #4 Facility Status: Closed	2415 S HURON PKWY	E 0 - 1/8 (0.074 mi.)	4	8
FISCA OIL CO INC #83 Facility Status: Open	3060 WASHTENAW AVE	NNE 1/8 - 1/4 (0.214 mi.)	B6	9
BUDDY'S MINI-MART INC #39 Facility Status: Open	3031 WASHTENAW AVE	N 1/8 - 1/4 (0.219 mi.)	B8	13
JOHN LEE OLDSMOBILE Facility Status: Closed	3120 WASHTENAW AVE	NNE 1/8 - 1/4 (0.220 mi.)	C11	19
ANN ARBOR BUICK CO Facility Status: Closed	3165 WASHTENAW AVE	NE 1/8 - 1/4 (0.225 mi.)	C12	21
UNCLE EDS OIL SHOPPE Facility Status: Closed	3160 WASHTENAW AVE	NE 1/8 - 1/4 (0.234 mi.)	D14	27

Lower Elevation	Address	Direction / Distance	Map ID	Page
GOLDEN FUEL LLC Facility Status: Closed Facility Status: Open	3240 WASHTENAW	NE 1/4 - 1/2 (0.277 mi.)	16	32
ARBOR DODGE Facility Status: Closed	3365 WASHTENAW AVE	ENE 1/4 - 1/2 (0.384 mi.)	17	37

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Quality's Michigan UST database.

A review of the UST list, as provided by EDR, and dated 02/22/2010 has revealed that there are 7 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STEVEN MURILLO	3000 WASHTENAW AVE	N 1/8 - 1/4 (0.225 mi.)	13	26
Lower Elevation	Address	Direction / Distance	Map ID	Page
ANN ARBOR FIRE DEPT #4	2415 S HURON PKWY	E 0 - 1/8 (0.074 mi.)	4	8
FISCA OIL CO INC #83	3060 WASHTENAW AVE	NNE 1/8 - 1/4 (0.214 mi.)	B6	9
BUDDY'S MINI-MART INC #39	3031 WASHTENAW AVE	N 1/8 - 1/4 (0.219 mi.)	B8	13
JOHN LEE OLDSMOBILE	3120 WASHTENAW AVE	NNE 1/8 - 1/4 (0.220 mi.)	C11	19
ANN ARBOR BUICK CO	3165 WASHTENAW AVE	NE 1/8 - 1/4 (0.225 mi.)	C12	21
UNCLE EDS OIL SHOPPE	3160 WASHTENAW AVE	NE 1/8 - 1/4 (0.234 mi.)	D14	27

State and tribal institutional control / engineering control registries

AUL: A listing of sites with institutional and/or engineering controls in place.

A review of the AUL list, as provided by EDR, and dated 01/04/2010 has revealed that there is 1 AUL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHELL SERVICE STATION (ANN ARB	3240 WASHTENAW	NE 1/4 - 1/2 (0.253 mi.)	D15	31

State and tribal Brownfields sites

BROWNFIELDS: Brownfields and USTfield Site Database.

A review of the BROWNFIELDS list, as provided by EDR, and dated 02/12/2010 has revealed that there is 1 BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARBOR WASH	3031 WASHTENAW AVE	N 1/8 - 1/4 (0.219 mi.)	B9	15

ADDITIONAL ENVIRONMENTAL RECORDS

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 01/13/2010 has revealed that there are 3 RCRA-NonGen sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WHOLE FOODS MARKET GROUP INC	3135 WASHTENAW AVE	NNE 1/8 - 1/4 (0.218 mi.)	C7	11
ANN ARBOR BUICK CO	3165 WASHTENAW AVE	NE 1/8 - 1/4 (0.225 mi.)	C12	21
UNCLE EDS OIL SHOPPE	3160 WASHTENAW AVE	NE 1/8 - 1/4 (0.234 mi.)	D14	27

BEA: Baseline Environmental Assessment.


A review of the BEA list, as provided by EDR, and dated 03/01/2010 has revealed that there are 4 BEA sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2275 PLATT RD	0 - 1/8 (0.000 mi.)	A2	7
Not reported	3060 WASHTENAW AVE	NNE 1/8 - 1/4 (0.214 mi.)	B5	9
ARBOR WASH	3031 WASHTENAW AVE	N 1/8 - 1/4 (0.219 mi.)	B9	15
ARBOR DODGE	3365 WASHTENAW AVE	ENE 1/4 - 1/2 (0.384 mi.)	17	37

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
HIDEAWAY LANE	SHWS
MICH CON BEAKES ST	SHWS
UM NORTH CAMPUS LANDFILL AREA	SHWS
PLATT ROAD DUMP	SHWS
AVFUEL BULK FACILITY	SHWS
UNIVERSITY OF MICH LF NO 1	SHWS
32581 NORTHWESTERN HWY	RCRA-NonGen, FINDS, LUST
BROADWAY OVER HURON RIVER	RCRA-NonGen
312314 N HURON ST	RCRA-NonGen
HURON PKY	RCRA-NonGen, FINDS
4001 S STATE	RCRA-CESQG, FINDS
4714 STATE ST	RCRA-CESQG
PARCELS B & C	BEA
2235TH & S STATE	BEA
212216 S STATE ST	BEA

OVERVIEW MAP - 2738992.1s




SITE NAME: WCJC ADDRESS:

2270 Platt Road Ann Arbor MI 48104 LAT/LONG: 42.2543 / 83.7029

CLIENT: TTL Associates CONTACT: Danielle Green TTL Associates INQUIRY#: 2738992.1s

April 07, 2010 11:37 am DATE:

DETAIL MAP - 2738992.1s



SITE NAME: WCJC ADDRESS: 2270 F

ADDRESS: 2270 Platt Road Ann Arbor MI 48104 LAT/LONG: 42.2543 / 83.7029 CLIENT: TTL Associates CONTACT: Danielle Green INQUIRY#: 2738992.1s

DATE: April 07, 2010 11:37 am

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENT	TAL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS		1.000 1.000 TP	0 0 NR	0 0 NR	0 0 NR	0 0 NR	NR NR NR	0 0 0
Federal Delisted NPL sit	e list							
Delisted NPL		1.000	0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS FEDERAL FACILITY		0.500 1.000	0 0	0 0	0 0	NR 0	NR NR	0 0
Federal CERCLIS NFRA	P site List							
CERC-NFRAP		0.500	0	0	0	NR	NR	0
Federal RCRA CORRAC	TS facilities lis	st						
CORRACTS		1.000	0	0	0	0	NR	0
Federal RCRA non-COR	RACTS TSD fa	acilities list						
RCRA-TSDF		0.500	0	0	0	NR	NR	0
Federal RCRA generator	rs list							
RCRA-LQG RCRA-SQG RCRA-CESQG		0.250 0.250 0.250	0 0 0	0 0 1	NR NR NR	NR NR NR	NR NR NR	0 0 1
Federal institutional con engineering controls reg								
US ENG CONTROLS US INST CONTROL		0.500 0.500	0 0	0 0	0 0	NR NR	NR NR	0 0
Federal ERNS list								
ERNS		TP	NR	NR	NR	NR	NR	0
State- and tribal - equiva	lent CERCLIS	;						
SHWS		1.000	1	1	1	1	NR	4
State and tribal landfill a solid waste disposal site								
SWF/LF		0.500	0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST INDIAN LUST		0.500 0.500	1 0	6 0	3 0	NR NR	NR NR	10 0
State and tribal registered storage tank lists								
UST		0.250	1	6	NR	NR	NR	7

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
AST INDIAN UST FEMA UST		0.250 0.250 0.250	0 0 0	0 0 0	NR NR NR	NR NR NR	NR NR NR	0 0 0
State and tribal institution control / engineering control /		es						
AUL		0.500	0	0	1	NR	NR	1
State and tribal voluntary cleanup sites								
INDIAN VCP		0.500	0	0	0	NR	NR	0
State and tribal Brownfie	elds sites							
BROWNFIELDS		0.500	0	1	0	NR	NR	1
ADDITIONAL ENVIRONMEN	ITAL RECORDS	S						
		_						
Local Brownfield lists								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
Local Lists of Landfill / S Waste Disposal Sites	Solid							
ODI DEBRIS REGION 9		0.500 0.500	0	0 0	0 0	NR NR	NR NR	0 0
HIST LF		0.500	0	0	0	NR	NR	0
INDIAN ODI		0.500	0	0	0	NR	NR	0
Local Lists of Hazardous Contaminated Sites	s waste /							
US CDL		TP	NR	NR	NR	NR	NR	0
DEL SHWS CDL		1.000 TP	0 NR	0 NR	0 NR	0 NR	NR NR	0 0
US HIST CDL		TP	NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2 LUCIS		TP	NR	NR	NR	NR NR	NR NR	0
LIENS		0.500 TP	0 NR	0 NR	0 NR	NR NR	NR NR	0 0
Records of Emergency Release Reports								
HMIRS SPILLS		TP TP	NR NR	NR NR	NR NR	NR NR	NR NR	0 0
Other Ascertainable Records								
RCRA-NonGen		0.250	0	3	NR	NR	NR	3
DOT OPS DOD		TP 1.000	NR 0	NR 0	NR 0	NR 0	NR NR	0 0
FUDS		1.000	0	0	0	0	NR	0
CONSENT ROD		1.000 1.000	0	0 0	0 0	0 0	NR NR	0 0
UMTRA		0.500	0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
MINES		0.250	0	0	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
HIST FTTS		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
ICIS		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
RADINFO		TP	NR	NR	NR	NR	NR	0
FINDS	Χ	TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
UIC DRYCLEANERS		TP	NR	NR	NR	NR	NR	0
DRYCLEANERS NPDES		0.250 TP	0 NR	0 NR	NR NR	NR NR	NR NR	0
AIRS		TP	NR NR	NR NR	NR NR	NR NR	NR NR	0 0
BEA		0.500	1	2	1	NR	NR	4
INDIAN RESERV		1.000	0	0	0	0	NR	0
SCRD DRYCLEANERS		0.500	0	0	0	NR	NR	0
COAL ASH EPA		0.500	0	0	0	NR	NR	0
PCB TRANSFORMER		TP	NR	NR	NR	NR	NR	0
COAL ASH		0.500	0	0	0	NR	NR	0
COAL ASH DOE		TP	NŘ	NR	NŘ	NR	NR	Ö
FINANCIAL ASSURANCE		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY RECOR	<u>DS</u>							
EDR Proprietary Records								
Manufactured Gas Plants		1.000	0	0	0	0	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Direction Distance

Elevation Site Database(s) EPA ID Number

1 WASHTENAW CO JUVENILE DET FINDS 1004534211
Target 2270 PLATT RD N/A

Target 2270 PLATT RD
Property ANN ARBOR, MI 48104

FINDS:

Actual: Registry ID: 110011866178

824 ft.

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions,

and settlements.

A2 BEA \$105768043

2275 PLATT RD N/A

< 1/8 ANN ARBOR TOWNSHIP, MI 48104

1 ft.

Site 1 of 2 in cluster A

Relative: BEA:

Lower Secondary Address: Not reported

BEA Number: 268

Actual: District: Jackson

804 ft. Date Received: 11/29/2000 12:59:00 AM

Submitter Name: Vineyard Christian Fellowship of Milan

Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: massonp

Division Assigned: Environmental Response Division

A3 ANN ARBOR CIVIC THEATER SHWS S110126795 2275 PLATT ROAD N/A

< 1/8 ANN ARBOR, MI 48104

1 ft.

Site 2 of 2 in cluster A

Relative: SHWS:

Lower Facility ID: 81000544

Facility Status: Evaluation conducted
Actual: Source: Not reported

804 ft. SAM Score: 32

SAM Score Date: 5/25/2005
Township: 03S
Range: 06E
Section: 2

Quarter: Not reported
Quarter/Quarter: Not reported
Pollutants: Not reported

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

4 ANN ARBOR FIRE DEPT #4 LUST U000266285
East 2415 S HURON PKWY UST N/A

< 1/8 0.074 mi. 389 ft.

Relative: LUST:

Lower Facility ID: 00010252

ANN ARBOR, MI 48104

Source: STATE OF MICHIGAN
Actual: Owner Name: City of Ann Arbor
801 ft. Owner Address: PO Box 8647 100 N Fif

Owner Address: PO Box 8647 100 N Fifth Ave

Owner City,St,Zip: Ann Arbor, MI 48107
Owner Contact: Not reported
Owner Phone: (734) 794-6000

Country: USA

District: Jackson District Office
Site Name: Ann Arbor Fire Station #4

Latitude: 42.2533000000 Longitude: -83.6992610000 Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-2115-91
Release Date: Oct 18 1991
Substance Released: Unknown,Unknown

Release Status: Closed Release Closed Date: Aug 19 1992

UST:

 Facility ID:
 00010252

 Facility Type:
 CLOSED

 Latitude:
 42.2533000000

 Longitude:
 -83.6992610000

 Owner Name:
 City of Ann Arbor

Owner Address: PO Box 8647 100 N Fifth Ave

Owner City,St,Zip: Ann Arbor, MI 48107

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (734) 794-6000
Contact: DANIEL J. CULLEN
Contact Phone:

Date of Collection: 01-11-2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID: Phantom

Tank Status: Non-Registered Tank

Capacity: Not reported Install Date: Not reported Product: Unknown

EDR ID Number

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ANN ARBOR FIRE DEPT #4 (Continued) U000266285

Remove Date: Not reported Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 550 Install Date: Mar 19 1978 Product: Gasoline Sep 15 1991 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Not reported

Asphalt Coated or Bare Steel Constr Material:

Impressed Device: No

В5 BEA S107812205 N/A

NNE **3060 WASHTENAW AVE** 1/8-1/4 ANN ARBOR CITY, MI 48104

0.214 mi.

1131 ft. Site 1 of 4 in cluster B

BEA: Relative:

Secondary Address: Not reported Lower

BEA Number: 707 Actual: District: Jackson

815 ft. 3/27/2006 12:59:00 AM Date Received:

3120 Washtenaw LLC Submitter Name:

Petition Determination: No Request

Petition Disclosure:

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: hisket

Division Assigned: Storage Tank Division

U000266329 **B6** FISCA OIL CO INC #83 LUST NNE **3060 WASHTENAW AVE** UST N/A

1/8-1/4 ANN ARBOR, MI 48104 0.214 mi.

Site 2 of 4 in cluster B 1131 ft.

LUST: Relative:

Facility ID: 00002910 Lower

STATE OF MICHIGAN Source: Actual: Owner Name: Fisca Oil Co Inc 815 ft. Owner Address: PO Box 3363

> Owner City,St,Zip: Kansas City, KS 66103-0363

Owner Contact: Not reported Owner Phone: 913-236-7000

USA Country:

Direction Distance

Elevation Site Database(s) EPA ID Number

FISCA OIL CO INC #83 (Continued)

U000266329

EDR ID Number

District: Jackson District Office
Site Name: Fisca Oil Co Inc #83
Latitude: 42.2573500000
Longitude: -83.6993040000
Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0074-06 Release Date: Mar 3 2006

Substance Released: Gasoline, Gasoline, Gasoline

Release Status: Open
Release Closed Date: Not reported

UST:

Facility ID: 00002910
Facility Type: CLOSED
Latitude: 42.2573500000
Longitude: -83.6993040000
Owner Name: Fisca Oil Co Inc
Owner Address: PO Box 3363

Owner City, St, Zip: Kansas City, KS 66103-0363

Owner Country: USA Owner Contact: Not reported Owner Phone: 913-236-7000 Contact: MICHAEL J. SZABO (916) 236-7000 Contact Phone: Date of Collection: 01-11-2001 Accuracy: 100 Accuracy Value Unit: **FEET**

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

NAD83

Tank ID: 2

Horizontal Datum:

Tank Status:Removed from GroundCapacity:20000Install Date:May 7 1972Product:GasolineRemove Date:Jul 19 1990Tank Release Detection:Not reportedPipe Realease Detection:Not reportedPiping Material:Galvanized Steel

Piping Type: Suction: No Valve At Tank
Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 1

Tank Status: Removed from Ground

Capacity: 20000 Install Date: May 7 1972

Direction Distance

Elevation Site Database(s) EPA ID Number

FISCA OIL CO INC #83 (Continued)

U000266329

MIK288238249

EDR ID Number

Product: Gasoline
Remove Date: Jul 19 1990
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel

Piping Type: Suction: No Valve At Tank
Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 8000
Install Date: May 7 1972
Product: Gasoline
Remove Date: Jul 19 1990
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel

Piping Type: Suction: No Valve At Tank
Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

WHOLE FOODS MARKET GROUP INC RCRA-NonGen 1007097030

NNE 3135 WASHTENAW AVE 1/8-1/4 ANN ARBOR, MI 48104

0.218 mi.

C7

1153 ft. Site 1 of 4 in cluster C

Relative: RCRA-NonGen:

Lower Date form received by agency: 09/01/2003

Facility name: WHOLE FOODS MARKET GROUP INC

Actual: Facility address: 3135 WASHTENAW AVE

Actual: Facility address: 3135 WASHTENAW AVE 806 ft. ANN ARBOR, MI 48104

EPA ID: MIK288238249
Contact: ADAM MITCHEL

Contact address: 3135 WASHTENAW AVE ANN ARBOR, MI 48104

Contact country: Not reported
Contact telephone: (734) 975-4500
Contact email: Not reported

EPA Region: 05

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: WHOLE FOODS MARKET GROUP INC

Owner/operator address:

Owner/operator country:

Owner/operator telephone:

Not reported

Not reported

Not reported

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/01/2003
Owner/Op end date: Not reported

Owner/operator name: WHOLE FOODS MARKET GROUP INC

Direction Distance Elevation

vation Site Database(s) EPA ID Number

WHOLE FOODS MARKET GROUP INC (Continued)

1007097030

EDR ID Number

Owner/operator address:

Not reported
Not reported
Owner/operator country:
Owner/operator telephone:
Legal status:
Owner/Operator Type:
Owner/Op start date:
Owner/Op end date:

Not reported
Not reported
Ooperator
Not reported
Not reported
Operator
Operator
Operator
Oy/01/2003
Owner/Op end date:
Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No Generated waste on-site: No

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY SWITCHES

Accumulated waste on-site: No Generated waste on-site: No

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WHOLE FOODS MARKET GROUP INC (Continued)

1007097030

Historical Generators:

Date form received by agency: 11/27/2002

WHOLE FOODS MARKET GROUP INC Facility name: Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B8 BUDDY'S MINI-MART INC #39 LUST U000266327 North **3031 WASHTENAW AVE** UST N/A

1/8-1/4 0.219 mi.

1155 ft. Site 3 of 4 in cluster B

LUST: Relative:

Lower Facility ID: 00003042

ANN ARBOR, MI 48104

STATE OF MICHIGAN Source: Actual: Owner Name: Pipeline Oil Sales 823 ft. Owner Address: 744 E South St

Jackson, MI 49203-4462 Owner City, St, Zip:

Owner Contact: Not reported (517) 784-3400 Owner Phone: Country: USA

District: Jackson District Office Site Name: Arbor Wash, Inc. Latitude: 42.2578700000 Longitude: -83.6993030000 Date of Collection: 01-10-2004

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Accuracy: 40 FEET Accuracy Value Unit: Horizontal Data: NAD83 Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-0615-91 Release Date: May 6 1991 Substance Released: Not reported Release Status: Open Release Closed Date: Not reported

UST:

Facility ID: 00003042 Facility Type: **ACTIVE** Latitude: 42.2578700000 Longitude: -83.6993030000 Pipeline Oil Sales Owner Name: Owner Address: 744 E South St

Jackson, MI 49203-4462 Owner City, St, Zip:

Owner Country: USA Owner Contact: Not reported Owner Phone: (517) 784-3400 Contact: **Thomas Crist** Contact Phone: Date of Collection: 01-10-2004

Accuracy: 40 Accuracy Value Unit: **FEET** Horizontal Datum: NAD83

STATE OF MICHIGAN Source:

Point Line Area: **POINT**

Direction Distance

Elevation Site Database(s) EPA ID Number

BUDDY'S MINI-MART INC #39 (Continued)

U000266327

EDR ID Number

Desc Category: Plant Entrance (Freight)

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Tank ID:

Tank Status: Currently In Use

Capacity: 21000
Install Date: Feb 3 2000
Product: Gasoline
Remove Date: Not reported

Tank Release Detection: Automatic Tank Gauging, Inter Monitoring Double Walled Tank, Inter

Monitoring/Second Containment

Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material: APT FLEX Piping Type: Pressure

Constr Material: Double Walled, Fiberglass Reinforced plastic

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 10000
Install Date: Jan 1 1971
Product: Gasoline
Remove Date: May 10 1999
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Bare Steel, Fiberglass reinforced plastic, Galvanized Steel

Piping Type: Pressure,Repaired

Constr Material: Cathodically Protected Steel

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 10000
Install Date: May 8 1971
Product: Gasoline
Remove Date: May 11 1999
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Bare Steel, Fiberglass reinforced plastic, Galvanized Steel

Piping Type: Suction: No Valve At Tank
Constr Material: Cathodically Protected Steel

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 10000
Install Date: Jan 1 1971
Product: Gasoline
Remove Date: May 11 1999
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Bare Steel, Fiberglass reinforced plastic, Galvanized Steel

Piping Type: Pressure, Repaired

Constr Material: Cathodically Protected Steel

Direction Distance

Elevation Site Database(s) EPA ID Number

BUDDY'S MINI-MART INC #39 (Continued)

U000266327

BEA

EDR ID Number

Impressed Device: No

B9 ARBOR WASH SHWS S105768036
North 3031 WASHTENAW AVE BROWNFIELDS N/A

1/8-1/4 ANN ARBOR, MI

0.219 mi.

1155 ft. Site 4 of 4 in cluster B

Relative: SHWS:

Lower Facility ID: 81000218

Facility Status: See Leaking Underground Storage Tank Site Database

Actual: Source: Not reported 823 ft. SAM Score: 41

SAM Score: 41
SAM Score Date: 8/8/2006
Township: 03S
Range: 06E
Section: 2

Quarter: Not reported Quarter/Quarter: Not reported Pollutants: Not reported

BROWNFIELD:

Facility ID: 00003042 Region: 1

Status: In Progress
Properry Use: Not reported

BEA: A

Ernie Id Number: 81000218 Redevelop Status: Not reported

Before Redevelopment: Photo

After Redevelopment: Not reported

BEA:

Secondary Address: Not reported BEA Number: 137 District: Jackson Date Received: 4/30/1998

Submitter Name: Buddy Mini-Marts, Inc.

Petition Determination: No Request

Petition Disclosure: 0

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: temppm

Division Assigned: Storage Tank Division

Secondary Address: Not reported BEA Number: 132 District: Jackson Date Received: 4/30/1998

Submitter Name: Legacy Investment Company, LLC

Petition Determination: Affirmed

Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: Pending Reviewer: temppm

Division Assigned: Storage Tank Division

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ARBOR WASH (Continued)

S105768036

1000121027

MID016712325

FINDS

Secondary Address: Not reported BEA Number: 133 District: Jackson Date Received: 4/30/1998

Submitter Name: Pipeline Oil Sales, Inc.

Petition Determination: No Request

Petition Disclosure:

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: temppm

Division Assigned: Storage Tank Division

C10 **GORDON CADILLAC LLC** RCRA-CESQG

NNE **3120 WASHTENAW** 1/8-1/4 ANN ARBOR, MI 48104

0.220 mi.

1162 ft. Site 2 of 4 in cluster C

RCRA-CESQG: Relative:

Date form received by agency: 02/18/2005 Lower

Land type:

GORDON CADILLAC LLC Facility name:

Actual: Facility address: 3120 WASHTENAW AVE 805 ft. ANN ARBOR, MI 48104

> EPA ID: MID016712325 Contact: JEAN ROBERTSON Contact address: 3120 WASHTENAW AVE

> > ANN ARBOR, MI 48104 Not reported

Contact country: (734) 971-8100 Contact telephone: Contact email: Not reported EPA Region: 05

Classification: Conditionally Exempt Small Quantity Generator

Private

Handler: generates 100 kg or less of hazardous waste per calendar Description:

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: **GORDON STEWART**

Owner/operator address: Not reported

Not reported Not reported

Owner/operator country: Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: 06/02/2004

Direction Distance

Elevation Site Database(s) EPA ID Number

GORDON CADILLAC LLC (Continued)

1000121027

EDR ID Number

Owner/Op end date: Not reported

Owner/operator name: GORDON STEWART

Owner/operator address: Not reported

Owner/operator country:
Owner/operator telephone:
Legal status:
Owner/Operator Type:
Owner/Operator Type:
Owner/Op start date:
Owner/Op end date:

Not reported
Owner
Owner
Owner
Owner
Owner
Owner
Owner/Op end date:
Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No Generated waste on-site: No

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY SWITCHES

Direction Distance

Elevation Site Database(s) EPA ID Number

GORDON CADILLAC LLC (Continued)

1000121027

EDR ID Number

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 11/30/2004

Facility name: GORDON CADILLAC LLC

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/11/2003

Facility name: GORDON CADILLAC LLC Classification: Small Quantity Generator

Date form received by agency: 01/01/2002

Facility name: GORDON CADILLAC LLC Classification: Small Quantity Generator

Date form received by agency: 09/11/1986

Facility name: GORDON CADILLAC LLC Classification: Small Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 05/03/2002
Date achieved compliance: 05/20/2002
Violation lead agency: State
Enforcement action: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 03/13/2002
Date achieved compliance: 05/20/2002
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/15/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 03/13/2002
Date achieved compliance: 05/20/2002
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 05/15/2002

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

GORDON CADILLAC LLC (Continued)

1000121027

Enf. disposition status: Not reported Not reported Enf. disp. status date: Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 05/03/2002

Evaluation: FOLLOW-UP INSPECTION Area of violation: Generators - General

Date achieved compliance: 05/20/2002 Evaluation lead agency: State

Evaluation date: 03/13/2002

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Generators - General

Date achieved compliance: 05/20/2002 Evaluation lead agency: State

FINDS:

Registry ID: 110003586156

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

C11 JOHN LEE OLDSMOBILE NNE **3120 WASHTENAW AVE** 1/8-1/4 ANN ARBOR, MI 48104 0.220 mi.

1162 ft. Site 3 of 4 in cluster C

Relative: Lower

805 ft.

LUST:

Facility ID: 00005622

Source: STATE OF MICHIGAN Actual: Owner Name: John Lee Olds

Owner Address: 3120 Washtenaw Ave Owner City, St, Zip: Ann Arbor, MI 48104-5122

Owner Contact: Not reported Owner Phone: (734) 971-8100

Country: USA

District: Jackson District Office Site Name: John Lee Oldsmobile, Inc.

Latitude: 42.2570100000 Longitude: -83.6977550000 Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100 Accuracy Value Unit: FEET Horizontal Data: NAD83 Point Line Area: **POINT**

LUST

UST

U000266334

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

JOHN LEE OLDSMOBILE (Continued)

Desc Category: Plant Entrance (Freight)

Leak Number: C-1581-94
Release Date: Dec 12 1994
Substance Released: Unknown
Release Status: Closed
Release Closed Date: Sep 11 1997

UST:

Facility ID: 00005622
Facility Type: CLOSED
Latitude: 42.2570100000
Longitude: -83.6977550000
Owner Name: John Lee Olds
Owner Address: 3120 Washtenaw Ave

Owner City,St,Zip: 3120 Washtenaw Ave
Ann Arbor, MI 48104-5122

Owner Country: USA
Owner Contact: Not reported
Owner Phone: (734) 971-8100
Contact: JOHN LEE
Contact Phone: (734) 971-8100
Date of Collection: 01-11-2001
Accuracy: 100

Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID:

Tank Status: Removed from Ground

Capacity: 550
Install Date: May

Install Date: May 9 1970
Product: Used Oil
Remove Date: Dec 12 1994
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 1000
Install Date: May 9 1970
Product: MOTOR OIL
Remove Date: Dec 12 1994
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

EDR ID Number

U000266334

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

JOHN LEE OLDSMOBILE (Continued)

U000266334

Tank ID: Phantom

Tank Status: Non-Registered Tank

Capacity: Not reported Install Date: Not reported Product: Unknown Not reported Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 1000 Install Date: May 10 1979 Product: Gasoline Remove Date: Dec 12 1994 Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: Nο

C12 ANN ARBOR BUICK CO RCRA-NonGen 1000102254 **FINDS** ΝE 3165 WASHTENAW AVE MID016708554

1/8-1/4 ANN ARBOR, MI 48104 0.225 mi.

1189 ft. Site 4 of 4 in cluster C

RCRA-NonGen: Relative:

Date form received by agency: 12/31/2001 Lower

Facility name: ANN ARBOR BUICK CO Actual: Facility address: 3165 WASHTENAW AVE 802 ft. ANN ARBOR, MI 48104

> MID016708554 EPA ID: HARRY DILDING Contact: Contact address: 3165 WASHTENAW AVE ANN ARBOR, MI 48104

Contact country: Not reported Contact telephone: (313) 971-6410 Contact email: Not reported

EPA Region: 05

Other land type Land type: Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported Not reported

Owner/operator country: Not reported Owner/operator telephone: Not reported Private Legal status:

LUST

UST

Direction Distance Elevation

Site Database(s) **EPA ID Number**

ANN ARBOR BUICK CO (Continued)

1000102254

EDR ID Number

Owner/Operator Type: Owner 01/01/2002 Owner/Op start date: Owner/Op end date: Not reported

NO ACTIVE O/OP AS NOT GENERATING WASTE Owner/operator name:

Owner/operator address: Not reported

Not reported Not reported

Owner/operator country: Owner/operator telephone: Not reported Legal status: Private Operator Owner/Operator Type: 01/01/2002 Owner/Op start date: Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: Nο On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: **Batteries** Accumulated waste on-site: No Generated waste on-site: No

Waste type: Lamps Accumulated waste on-site: No Generated waste on-site: Nο

Waste type: Pesticides Accumulated waste on-site: No Generated waste on-site: No

Waste type: **Thermostats**

Accumulated waste on-site: No Generated waste on-site: No

DEVICES CONTAINING ELEMENTAL MERCURY Waste type:

Accumulated waste on-site: Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ANN ARBOR BUICK CO (Continued)

1000102254

Waste type: MERCURY SWITCHES

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 10/02/1986

ANN ARBOR BUICK CO Facility name: Small Quantity Generator Classification:

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 09/22/1993

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

FINDS:

110003586101 Registry ID:

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste, RCRAInfo allows RCRA

program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LUST:

Facility ID: 00006255

STATE OF MICHIGAN Source: Ann Arbor Buick Owner Name: 3165 Washtenaw Ave Owner Address: Owner City, St, Zip: Ann Arbor, MI 48104-5121

Owner Contact: Not reported Owner Phone: (734) 971-6410

Country: USA

District: Jackson District Office Site Name: Ann Arbor Buick Latitude: 42.2570610000 Longitude: -83.6966930000 Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100 Accuracy Value Unit: FEET Horizontal Data: NAD83 Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-0090-93 Release Date: Jan 19 1993

Substance Released: Gasoline.Other.Other

Release Status: Closed

Direction Distance

Elevation Site Database(s) EPA ID Number

ANN ARBOR BUICK CO (Continued)

1000102254

EDR ID Number

Release Closed Date: Mar 29 1995

UST:

Facility ID: 00006255
Facility Type: CLOSED
Latitude: 42.2570610000
Longitude: -83.6966930000
Owner Name: Ann Arbor Buick
Owner Address: 3165 Washtenaw Ave
Owner City, St, Zip: Ann Arbor, MI 48104-5121

Owner Country: USA

Owner Contact: Not reported
Owner Phone: (734) 971-6410
Contact: JOHN ZAHNER
Contact Phone: (734) 971-6410
Date of Collection: 01-11-2001
Accuracy: 100
Accuracy Value Unit: FEET

Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID: 4

Tank Status: Removed from Ground

Capacity: 550

Install Date: Jan 22 1985
Product: Used Oil
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

Tank ID: 5

Tank Status: Removed from Ground

Capacity: 1000
Install Date: Jan 23 1976
Product: Gasoline
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

Tank ID: 6

Tank Status: Removed from Ground

Capacity: 6000 Install Date: Jan 23 1976

Direction Distance

Elevation Site Database(s) EPA ID Number

ANN ARBOR BUICK CO (Continued)

1000102254

EDR ID Number

Product: Gasoline
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 550

Install Date: Jan 22 1985
Product: 5W30 OIL
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 550

Install Date: Jan 22 1985
Product: 10W30 OIL
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

Tank ID: Phantom

Tank Status: Non-Registered Tank

Not reported Capacity: Install Date: Not reported Unknown Product: Remove Date: Not reported Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Impressed Device: No

Tank ID: 3

Tank Status: Removed from Ground

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

ANN ARBOR BUICK CO (Continued)

1000102254

Capacity: 550

Install Date: Jan 22 1985
Product: TRANS OIL
Remove Date: Jan 28 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel, Cathodically Protected Steel, Lined

Interier

Impressed Device: No

 13
 STEVEN MURILLO
 LUST
 U003211925

 North
 3000 WASHTENAW AVE
 UST
 N/A

1/8-1/4 0.225 mi. 1190 ft.

Relative: Higher

LUST:

ANN ARBOR, MI 48104

Facility ID: 00039356

Source: STATE OF MICHIGAN

Actual: 827 ft.

Owner Name: Steven Murillo

Owner Address: 3000 WASHTENAW AVE SUITE A

Owner City,St,Zip: ANN ARBOR, MI 48104

Owner Contact: Not reported
Owner Phone: (734) 973-2323

Country: USA

District: Jackson District Office
Site Name: Steven Murillo
Latitude: 42.2575990000
Longitude: -83.7004350000
Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD8

Horizontal Data: NAD83 Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-0349-97
Release Date: May 23 1997
Substance Released: Gasoline
Release Status: Closed
Release Closed Date: Dec 9 1997

UST:

 Facility ID:
 00039356

 Facility Type:
 CLOSED

 Latitude:
 42.2575990000

 Longitude:
 -83.7004350000

 Owner Name:
 Steven Murillo

Owner Address: 3000 WASHTENAW AVE SUITE A

Owner City,St,Zip: ANN ARBOR, MI 48104

Owner Country:
Owner Contact:
Owner Phone:
Contact:
Contact:
Contact Phone:
Conta

Direction Distance

Elevation Site Database(s) EPA ID Number

STEVEN MURILLO (Continued)

U003211925

EDR ID Number

Date of Collection: 01-11-2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID: Phantom

Tank Status: Non-Registered Tank

Not reported Capacity: Install Date: Not reported Product: Unknown Remove Date: Not reported Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Not reported Constr Material:

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 1000
Install Date: Not reported Product: Gasoline
Remove Date: May 23 1997
Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

UNCLE EDS OIL SHOPPE RCRA-NonGen 1000528359
3160 WASHTENAW AVE FINDS MID985596428

1/8-1/4 0.234 mi.

Actual:

800 ft.

D14

NE

1236 ft. Site 1 of 2 in cluster D

ANN ARBOR, MI 48104

Relative: RCRA-NonGen:

Lower Date form received by agency: 12/31/2001

Facility name: UNCLE EDS OIL SHOPPE Facility address: 3160 WASHTENAW AVE

ANN ARBOR, MI 48104

EPA ID: MID985596428
Mailing address: 2515 CAPITAL AVE SW

BATTLE CREEK, MI 49015

Contact: PATRICK DAY

Contact address: 3160 WASHTENAW AVE

ANN ARBOR, MI 48104

Contact country: Not reported
Contact telephone: (269) 968-9307
Contact email: Not reported

EPA Region: 05

Classification: Non-Generator

LUST

UST

Distance Elevation

on Site Database(s) EPA ID Number

UNCLE EDS OIL SHOPPE (Continued)

1000528359

EDR ID Number

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: UNCLE EDS OIL SHOPPE

Owner/operator address: Not reported

Not reported

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Not reported

Not reported

Private

Owner

Owner/Operator Type: Owner
Owner/Op start date: 01/01/1970
Owner/Op end date: Not reported

Owner/operator name: UEOS ANN ARBOR, LLC

Owner/operator address: Not reported

Not reported

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Private

Operator

Operator

04/14/1998

Not reported

Owner/operator name: UEOS ANN ARBOR, LLC

Owner/operator address: Not reported

Not reported Not reported

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

Owner

Owner

Not reported

Owner/operator name: UNCLE EDS OIL SHOPPE

Owner/operator address: Not reported Not reported

Owner/operator country:
Owner/operator telephone:
Legal status:
Owner/Operator Type:
Owner/Op start date:
Owner/Op end date:
Not reported
Private
Operator
Operator
O1/01/1970
Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No

Distance

Elevation Site Database(s) EPA ID Number

UNCLE EDS OIL SHOPPE (Continued)

1000528359

EDR ID Number

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No Generated waste on-site: No

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY SWITCHES

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 08/19/1991

Facility name: UNCLE EDS OIL SHOPPE Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110003646494

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LUST:

Facility ID: 00019432

Direction Distance

Elevation Site Database(s) EPA ID Number

UNCLE EDS OIL SHOPPE (Continued)

1000528359

EDR ID Number

Source: STATE OF MICHIGAN
Owner Name: Uncle Ed's Oil Shoppes Inc

Owner Address: 2515 Capital Ave
Owner City, St, Zip: Battle Creek, MI 49017

Owner Contact: Not reported
Owner Phone: (616) 968-9307

Country: USA
District: Jackson District Office
Site Name: Use Fds Oil Shapes

 Site Name:
 Uncle Eds Oil Shoppe

 Latitude:
 42.2568180000

 Longitude:
 -83.6968880000

 Date of Collection:
 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-1122-99
Release Date: Sep 1 1999
Substance Released: Unknown
Release Status: Closed
Release Closed Date: Aug 15 2000

UST:

 Facility ID:
 00019432

 Facility Type:
 CLOSED

 Latitude:
 42.2568180000

 Longitude:
 -83.6968880000

Owner Name: Uncle Ed's Oil Shoppes Inc

Owner Address: 2515 Capital Ave
Owner City,St,Zip: Battle Creek, MI 49017

Owner Country: USA
Owner Contact: Not reported

Owner Phone:

Contact: PATRICK DAY
Contact Phone:
Date of Collection: 01-11-2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

(616) 968-9307

Tank ID: Phantom

Tank Status: Non-Registered Tank

Not reported Capacity: Install Date: Not reported Product: Unknown Remove Date: Not reported Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

UNCLE EDS OIL SHOPPE (Continued)

1000528359

EDR ID Number

Impressed Device: No

Tank ID: 23998

Tank Status: Removed from Ground

Capacity: 550
Install Date: May 1 1984
Product: NEW OIL
Remove Date: Aug 1 1999
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Cathodically Protected Steel

Impressed Device: No

Tank ID: 22755

Tank Status: Removed from Ground

Capacity: 1500 Install Date: May 1 1984 Product: NEW/OIL Aug 23 1999 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Galvanized Steel Piping Type: Suction: Valve at Tank Constr Material: Cathodically Protected Steel

Impressed Device: No

Tank ID: 25801

Tank Status: Removed from Ground

Capacity: 3000
Install Date: May 1 1984
Product: NEW/OIL
Remove Date: Aug 23 1999
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Cathodically Protected Steel

Impressed Device: No

D15 SHELL SERVICE STATION (ANN ARBOR)

NE 3240 WASHTENAW 1/4-1/2 ANN ARBOR CITY, MI 48104

0.253 mi.

1337 ft. Site 2 of 2 in cluster D

Relative: AUL:

Lower Status: Filed
Site Name: Not reported

Actual: Property: On-site location 797 ft. Land Use Restriction Type: RC

Program Type: Part 213

Program Support Assigned User: Nicholas Swartz
Program Support Assigned Date: 5/1/2009 09:17:12.657

S109846791

N/A

AUL

Direction Distance

Elevation Site **EPA ID Number** Database(s)

SHELL SERVICE STATION (ANN ARBOR) (Continued)

S109846791

EDR ID Number

Legal Description Of Property: Not reported Based On The Deq Ref #: 11121309037 MDEQ Reference Number: RC-RRD-213-09-037

Property Or Description Restricted Area: 3240 Washtenaw Ave., Ann Arbor

Lead Division: **RRD**

File Name Of Hyperlinked Legal Doc: U:\\KERMIT\\11121309037.PDF

Mapped Polygon S Area In Acres: 1.1399 Mapped Polygon S Area In Square Miles: 0.0018

Date Data Entry Started: 5/1/2009 00:00:00 Date Data Entry Finished: 5/1/2009 00:00:00

Individual Or Staff Assoc With The Mapping: Nicholas Swartz Program Used To Map Restricted Features: ArcInfo 9.3 and IcoM

Map Comments: 20090408 - LUR is NOT mapped in KERMIT - Nick Ekel LUR is mapped in

KERMIT as of 20090501 - Nick Swartz

Comment: 3/19/2009, CP requested on-site reference number for a 2003 recorded

> RC. This 2002 RC will be submitted with the closure report. The 2002 RC has a map, but not a legal survey. RRD Project Manager is Terry

Hiske. Linda Fowler sent an e-mail to Terry wit

Date Legal Paperwork Stamped/Filed/Register Of Deeds: 6/25/2002 00:00:00

Commercial I Land Use Restriction: 0 Commercial li Land Use Restriction: 0 Commercial lii Land Use Restriction: 1 Commercial Iv Land Use Restriction: 0 Industrial Land Use Restriction: 0 Residential Land Use Restriction: 0 Recreational Land Use Restriction: 0 Multiple Land-Use Restrictions: n Site Specific Restrictions: 0 Groundwater Consumption Restrictions: 1 **Groundwater Contact Restrictions:** Special Well Construction Requirements: 0 Special Building Restrictions:

Excavation And Soil Movement Restrictions: 0 Soil Movement Requirements: There Is A Restriction On All Construction: 0 Monitoring Well Protected, No Tampering Or Removal: 0 There Is An Exposure Barrier In Place: 0 There Is A Health And Safety Plan: 0 There Is A Permanent Marker On The Site: 0

RCRA-CESQG **GOLDEN FUEL LLC** 1000529306 3240 WASHTENAW **FINDS** MID985617448

1/4-1/2 0.277 mi. 1465 ft.

16

NE

RCRA-CESQG: Relative:

Date form received by agency: 09/04/2001 Lower

ANN ARBOR, MI 48104

Facility name: **GOLDEN FUEL LLC** Facility address: 3240 WASHTENAW

Actual: 793 ft. ANN ARBOR, MI 48104

EPA ID: MID985617448 12700 NORTHBOROUGH DR

Mailing address: HOUSTON, TX 77067

Contact: NORA CORTEZ Contact address: 3240 WASHTENAW

ANN ARBOR, MI 48104

Contact country: Not reported **LUST**

UST

Direction Distance Elevation

on Site Database(s) EPA ID Number

GOLDEN FUEL LLC (Continued)

1000529306

EDR ID Number

Contact telephone: (281) 874-2224 Contact email: Not reported

EPA Region: 05

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: EQUILON ENTERPRISES LLC

Owner/operator address: Not reported

Not reported

Owner/operator country: Not reported Owner/operator telephone: Not reported Legal status: Private

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1970
Owner/Op end date: Not reported

Owner/operator name: SHELL OIL CO
Owner/operator address: Not reported
Not reported

Owner/operator country: Not reported Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 07/09/1998 Owner/Op end date: Not reported

Owner/operator name: EQUILON ENTERPRISES LLC

Owner/operator address: Not reported

Not reported

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Not reported

Private

Operator

Operator

01/01/1970

Owner/Op end date:

Owner/operator name: SHELL OIL CO
Owner/operator address: Not reported

Not reported

Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator

Direction Distance

Elevation Site Database(s) EPA ID Number

GOLDEN FUEL LLC (Continued)

1000529306

EDR ID Number

Owner/Op start date: 07/09/1998 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No Generated waste on-site: No

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY SWITCHES

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 06/25/1991

Facility name: GOLDEN FUEL LLC
Classification: Small Quantity Generator

Violation Status: No violations found

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

GOLDEN FUEL LLC (Continued)

1000529306

FINDS:

110003660155 Registry ID:

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LUST:

Facility ID: 00010426

STATE OF MICHIGAN Source:

Owner Name: Safeway Acquisitions Group LLC

Owner Address: 8700 Brandt Dearborn, MI 48126 Owner City, St, Zip: Owner Contact: Tim McCafferty Owner Phone: (313) 624-9911

Country: USA

District: Jackson District Office Site Name: **Shell Service Station** 42.2567220000 Latitude: Longitude: -83.6964870000 Date of Collection: 21-10-2003

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Accuracy: 10 Accuracy Value Unit: **METERS** Horizontal Data: NAD83 Point Line Area: **POINT**

Desc Category: Plant Entrance (Freight)

Leak Number: C-0120-97 Release Date: Mar 25 1997 Substance Released: Used Oil, Unknown

Release Status: Closed Release Closed Date: Apr 2 1998

Leak Number: C-0812-99 Release Date: Aug 12 1999 Substance Released: Unknown Release Status: Open Release Closed Date: Not reported

UST:

Facility ID: 00010426 Facility Type: **ACTIVE** Latitude: 42.2567220000 Longitude: -83.6964870000

Owner Name: Safeway Acquisitions Group LLC

8700 Brandt Owner Address: Owner City,St,Zip: Dearborn, MI 48126

Owner Country: USA

Owner Contact: Tim McCafferty Owner Phone: (313) 624-9911

Direction Distance

Elevation Site Database(s) EPA ID Number

GOLDEN FUEL LLC (Continued)

1000529306

EDR ID Number

Contact: Tim McCafferty
Contact Phone: (313) 624-9911
Date of Collection: 21-10-2003
Accuracy: 10

Accuracy: 10
Accuracy Value Unit: METERS
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: GPS Code Meas. Standard Positioning Service SA Off

Tank ID: Phantom

Tank Status: Non-Registered Tank

Capacity: Not reported Install Date: Not reported Product: Unknown Not reported Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Impressed Device: No

Tank ID: 2

Tank Status: Currently In Use

Capacity: 10000
Install Date: Aug 1 1983
Product: Gasoline
Remove Date: Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Pipe Realease Detection: Line Tightness Testing
Piping Material: Fiberglass reinforced plastic

Piping Type: Pressure

Constr Material: Fiberglass Reinforced plastic

Impressed Device: No

Tank ID:

Tank Status: Currently In Use

Capacity: 8000
Install Date: Apr 17 1983
Product: Gasoline
Remove Date: Not reported
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Fiberglass reinforced plastic

Piping Type: Pressure

Constr Material: Fiberglass Reinforced plastic

Impressed Device: No

Tank ID: 4

Tank Status: Removed from Ground

Capacity: 1000 Install Date: Apr 16 1965

Direction Distance

Elevation Site Database(s) EPA ID Number

GOLDEN FUEL LLC (Continued)

1000529306

EDR ID Number

Product: Used Oil
Remove Date: Jan 1 1988
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 1000
Install Date: Apr 17 1983
Product: Used Oil
Remove Date: Mar 6 1997
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Fiberglass reinforced plastic

Piping Type: Not reported

Constr Material: Fiberglass Reinforced plastic

Impressed Device: No

Tank ID:

Tank Status: Currently In Use

Capacity: 10000
Install Date: Jun 1 1969
Product: Gasoline
Remove Date: Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Pipe Realease Detection: Line Tightness Testing
Piping Material: Fiberglass reinforced plastic

Piping Type: Pressure

Constr Material: Fiberglass Reinforced plastic

Impressed Device: No

 17
 ARBOR DODGE
 RCRA-NonGen
 1000340398

 ENE
 3365 WASHTENAW AVE
 FINDS
 MID106752280

1/4-1/2 ANN ARBOR, MI 48104 0.384 mi. 2029 ft.

Relative:

Actual:

Lower RCRA-NonGen:

EPA ID:

Date form received by agency:11/01/2002
Facility name: ARBOR DODGE

797 ft. Facility address: 3365 WASHTENAW AVE

ANN ARBOR, MI 48104 MID106752280

Contact: ROBERT PRICE
Contact address: 3365 WASHTENAW AVE

ANN ARBOR, MI 48104

Contact country: Not reported
Contact telephone: (734) 971-5000
Contact email: Not reported

EPA Region: 05

Classification: Non-Generator

SHWS

LUST

UST BEA

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

ARBOR DODGE (Continued)

1000340398

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Owner/operator country:
Owner/operator telephone:
Legal status:
Owner/Operator Type:
Owner

Not reported
Not reported
Private
Owner

Owner/Operator Type: Owner
Owner/Op start date: 11/02/2002
Owner/Op end date: Not reported

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

11/02/2002

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No

Direction Distance

Elevation Site Database(s) EPA ID Number

ARBOR DODGE (Continued) 1000340398

Generated waste on-site: No

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY THERMOMETERS

Accumulated waste on-site: No Generated waste on-site: No

Waste type: MERCURY SWITCHES

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 06/01/1987
Facility name: ARBOR DODGE

Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110003610664

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

SHWS:

Facility ID: 81000553

Facility Status: Evaluation conducted

Source: Not reported

SAM Score: 32
SAM Score Date: 5/27/2005
Township: 03S
Range: 06E
Section: 2

Quarter: Not reported
Quarter/Quarter: Not reported
Pollutants: Not reported

LUST:

Facility ID: 00021467

Source: STATE OF MICHIGAN Owner Name: Chrysler Realty Corp

Owner Address: 1450 W LONG LAKE RD STE 280

Owner City,St,Zip: TROY, MI 48098 Owner Contact: Not reported Owner Phone: (313) 737-0299

Country: USA

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

ARBOR DODGE (Continued)

1000340398

EDR ID Number

District: Jackson District Office
Site Name: Arbor Dodge

Latitude: 42.2562490000 Longitude: -83.6925720000 Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-1184-85
Release Date: May 24 1990
Substance Released: Not reported
Release Status: Closed
Release Closed Date: Nov 12 1995

UST:

Facility ID: 00021467
Facility Type: CLOSED
Latitude: 42.2562490000
Longitude: -83.6925720000
Owner Name: Chrysler Realty Corp

Owner Address: 1450 W LONG LAKE RD STE 280

Owner City,St,Zip: TROY, MI 48098

Owner Country: USA Not reported Owner Contact: Owner Phone: (313) 737-0299 Contact: FRED NEUMAN (313) 737-0299 Contact Phone: Date of Collection: 01-11-2001 Accuracy: 100 Accuracy Value Unit: **FEET**

Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID: 2

Tank Status: Removed from Ground

Capacity: 1000
Install Date: Aug 14 1961
Product: ENGINE OIL
Remove Date: May 15 1990
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel

Piping Type: Not reported
Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID: 3

Tank Status: Removed from Ground

Capacity: 500

Install Date: Aug 14 1961

Direction Distance

Elevation Site Database(s) EPA ID Number

ARBOR DODGE (Continued)

1000340398

EDR ID Number

Product: Used Oil,WATER
Remove Date: May 15 1990
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

Tank ID:

Tank Status: Removed from Ground

Capacity: 2000
Install Date: Aug 14 1961
Product: Gasoline
Remove Date: May 15 1990
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported
Piping Material: Galvanized Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Impressed Device: No

BEA:

Secondary Address: Not reported BEA Number: 412
District: Jackson

Date Received: 10/7/2002 12:59:00 AM
Submitter Name: Cueter Chrysler Jeep LLC

Petition Determination: Affirmed

Petition Disclosure: 1

Category: Same Hazardous Substance(s)

Determination 20107A: No Request Reviewer: katkov

Division Assigned: Environmental Response Division

Secondary Address: Not reported BEA Number: 461
District: Jackson

Date Received: 6/3/2003 12:59:00 AM Submitter Name: LPN Properties LLC

Petition Determination: No Request

Petition Disclosure: 0

Category: No Hazardous Substance(s)

Determination 20107A: No Request Reviewer: hisket

Division Assigned: Storage Tank Division

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

18 GOODYEAR AUTO SERVICE CENTER RCRA-NonGen 1000194457

ENE 3451 WASHTENAW FINDS MID101575108
1/4-1/2 ANN ARBOR, MI 48104 LUST

0.477 mi. 2521 ft.

Relative: RCRA-NonGen:

Higher Date form received by agency: 02/28/1993

Facility name: GOODYEAR AUTO SERVICE CENTER

Actual: Facility address: 3451 WASHTENAW 824 ft. ANN ARROR MI 481

ANN ARBOR, MI 48104 EPA ID: MID101575108

Mailing address: 27700 NORTHWEST HWY

SOUTHFIELD, MI 48034

Contact: D OTTE

Contact address: 3451 WASHTENAW

ANN ARBOR, MI 48104

Contact country: Not reported
Contact telephone: (313) 423-5500
Contact email: Not reported

EPA Region: 05

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/01/1993
Owner/Op end date: Not reported

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported Not reported Owner/operator country: Not reported Owner/operator telephone: Not reported Legal status: Private

Owner/Operator Type: Owner
Owner/Op start date: 03/01/1993
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No UST

Direction Distance

Elevation Site Database(s) **EPA ID Number**

GOODYEAR AUTO SERVICE CENTER (Continued)

1000194457

EDR ID Number

Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: **Batteries** Accumulated waste on-site: No Generated waste on-site: No

Waste type: Lamps Accumulated waste on-site: Nο Generated waste on-site: No

Waste type: Pesticides Accumulated waste on-site: No Generated waste on-site: No

Waste type: Thermostats

Accumulated waste on-site: No Generated waste on-site: Nο

Waste type: DEVICES CONTAINING ELEMENTAL MERCURY

Accumulated waste on-site: Generated waste on-site: No

MERCURY THERMOMETERS Waste type:

Accumulated waste on-site: Generated waste on-site: No

MERCURY SWITCHES Waste type:

Accumulated waste on-site: No Generated waste on-site: No

Historical Generators:

Date form received by agency: 10/31/1986

Facility name: GOODYEAR AUTO SERVICE CENTER

Classification: **Small Quantity Generator**

Violation Status: No violations found

FINDS:

Registry ID: 110003610147

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LUST:

Facility ID: 00021710

Direction Distance

Elevation Site Database(s) EPA ID Number

GOODYEAR AUTO SERVICE CENTER (Continued)

1000194457

EDR ID Number

Source: STATE OF MICHIGAN
Owner Name: Goodyear Tire & Rubber Co
Owner Address: 1144 E Market St Dept 824

Owner City,St,Zip: Akron, OH 44305 Owner Contact: Not reported Owner Phone: (330) 796-9434

Country: USA

District: Jackson District Office
Site Name: Goodyear Asc 6548
Latitude: 42.2560770000
Longitude: -83.6915020000
Date of Collection: 01-11-2001

Method of Collection: Address Matching-House Number

Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Data: NAD83
Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Leak Number: C-1347-93
Release Date: Oct 22 1993
Substance Released: Used Oil
Release Status: Closed
Release Closed Date: Feb 11 1997

UST:

 Facility ID:
 00021710

 Facility Type:
 CLOSED

 Latitude:
 42.2560770000

 Longitude:
 -83.6915020000

Owner Name: Goodyear Tire & Rubber Co
Owner Address: 1144 E Market St Dept 824

Owner City,St,Zip: Akron, OH 44305

Owner Country: USA
Owner Contact: Not reported

Owner Phone: (330) 796-9434
Contact: MARVIN WOOD
Contact Phone: 01-11-2001
Accuracy: 100
Accuracy Value Unit: FEET
Horizontal Datum: NAD83

Source: STATE OF MICHIGAN

Point Line Area: POINT

Desc Category: Plant Entrance (Freight)

Method of Collection: Address Matching-House Number

Tank ID:

Tank Status: Removed from Ground

Capacity: 500
Install Date: Apr 17 1967
Product: Used Oil
Remove Date: Oct 22 1993
Tank Release Detection: Not reported
Pipe Realease Detection: Not reported

Piping Material: Bare Steel
Piping Type: Not reported

Constr Material: Asphalt Coated or Bare Steel

Direction Distance

Elevation Site Database(s) EPA ID Number

GOODYEAR AUTO SERVICE CENTER (Continued)

1000194457

EDR ID Number

Impressed Device: No

Tank ID: Phantom

Tank Status: Non-Registered Tank

Not reported Capacity: Install Date: Not reported Product: Unknown Remove Date: Not reported Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Not reported Piping Type: Not reported Constr Material: Not reported

Impressed Device: No

 19
 ARBORLAND MALL
 SHWS
 S105144779

 East
 3693 WASHTENAW
 N/A

1/2-1 ANN ARBOR, MI 48104

0.663 mi. 3499 ft.

Relative: SHWS:

Lower Facility ID: 81000492

Facility Status: Interim Response in progress

Actual: Source: Dry Cleaning Plants 819 ft. SAM Score: 37

SAM Score: 37
SAM Score Date: 7/2/2004
Township: 3S
Range: 6E
Section: 2
Quarter: NE

Quarter/Quarter: Not reported Pollutants: PCE; TCE

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
ANN ARBOR	S109847381	PARCELS B & C	1600TH HURON PKY & 3200 PLYMOU		BEA
ANN ARBOR	S110126793	HIDEAWAY LANE	2000 / 2018 TRAVER ROAD	48104	SHWS
ANN ARBOR	S107812200		2235TH & S STATE		BEA
ANN ARBOR	S103086285	MICH CON BEAKES ST	BEAKES & SUMMIT STS	48104	SHWS
ANN ARBOR	1007097483		BROADWAY OVER HURON RIVER		RCRA-NonGen
ANN ARBOR	1007101636		312314 N HURON ST	48104	RCRA-NonGen
ANN ARBOR	1001817515		HURON PKY		RCRA-NonGen, FINDS
ANN ARBOR	S103095426	UM NORTH CAMPUS LANDFILL AREA	HURON PKY	48104	SHWS
ANN ARBOR	1000248347		32581 NORTHWESTERN HWY	48108	RCRA-NonGen, FINDS, LUST
ANN ARBOR	S103595083	PLATT ROAD DUMP	5375 PLATT RD	48108	SHWS
ANN ARBOR	1004724331		4001 S STATE	48104	RCRA-CESQG, FINDS
ANN ARBOR	1008403289		4714 STATE ST	48108	RCRA-CESQG
ANN ARBOR	S106676482		212216 S STATE ST		BEA
ANN ARBOR	S103595047	AVFUEL BULK FACILITY	STATE AND ELLSWORTH RD	48104	SHWS
ANN ARBOR	S103595057	UNIVERSITY OF MICH LF NO 1	WASHINGTON HTS	48104	SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/01/2009 Source: EPA
Date Data Arrived at EDR: 01/14/2010 Telephone: N/A

Date Made Active in Reports: 02/18/2010 Last EDR Contact: 04/02/2010

Number of Days to Update: 35 Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 EPA Region 8

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/01/2009 Source: EPA
Date Data Arrived at EDR: 01/14/2010 Telephone: N/A

Number of Days to Update: 35 Next Scheduled EDR Contact: 04/26/2010 Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Source: EPA

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Telephone: 202-564-4267 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 05/31/2010 Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

INPL where no further response is appropria

Date of Government Version: 12/01/2009 Date Data Arrived at EDR: 01/14/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 35

Source: EPA Telephone: N/A

Last EDR Contact: 04/02/2010

Next Scheduled EDR Contact: 04/26/2010 Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/30/2009 Date Data Arrived at EDR: 08/11/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 41

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 03/30/2010

Next Scheduled EDR Contact: 07/12/2010 Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of NPL and Base Realighnment & Closure sites found in the CERCLIS database where FERRO is involved in cleanup projects.

Date of Government Version: 06/23/2009 Date Data Arrived at EDR: 01/15/2010 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 26

Source: Environmental Protection Agency

Telephone: 703-603-8704 Last EDR Contact: 01/15/2010

Next Scheduled EDR Contact: 04/26/2010 Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 06/23/2009 Date Data Arrived at EDR: 09/02/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 19

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 03/11/2010

Next Scheduled EDR Contact: 06/14/2010 Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/11/2009 Date Data Arrived at EDR: 12/29/2009 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 43

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 02/15/2010

Next Scheduled EDR Contact: 05/31/2010 Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 01/13/2010 Date Data Arrived at EDR: 01/15/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 34

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 02/19/2010

Next Scheduled EDR Contact: 04/19/2010 Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 01/13/2010 Date Data Arrived at EDR: 01/15/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 34

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 02/19/2010

Next Scheduled EDR Contact: 04/19/2010 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010

Number of Days to Update: 34

Source: Environmental Protection Agency

Telephone: 312-886-6186

Last EDR Contact: 02/19/2010

Next Scheduled EDR Contact: 04/19/2010 Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 01/13/2010 Date Data Arrived at EDR: 01/15/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 34

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 02/19/2010

Next Scheduled EDR Contact: 04/19/2010

Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/01/2009 Date Data Arrived at EDR: 10/09/2009 Date Made Active in Reports: 11/09/2009

Number of Days to Update: 31

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 03/15/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/01/2009 Date Data Arrived at EDR: 10/09/2009 Date Made Active in Reports: 11/09/2009

Number of Days to Update: 31

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 03/15/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 01/22/2010 Date Made Active in Reports: 02/11/2010

Number of Days to Update: 20

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 04/07/2010

Next Scheduled EDR Contact: 07/19/2010
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Contaminated Sites

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 02/01/2010 Date Data Arrived at EDR: 02/03/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 23

Source: Department of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 02/03/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Semi-Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Solid Waste Facilities Database

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 02/03/2010 Date Data Arrived at EDR: 02/04/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 22

Source: Department of Environmental Quality

Telephone: 517-335-4035 Last EDR Contact: 04/05/2010

Next Scheduled EDR Contact: 07/19/2010 Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank Sites

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 02/22/2010 Date Data Arrived at EDR: 02/24/2010 Date Made Active in Reports: 03/23/2010

Number of Days to Update: 27

Source: Department of Environmental Quality

Telephone: 517-373-9837 Last EDR Contact: 04/01/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/24/2009 Date Data Arrived at EDR: 11/25/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 21

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 12/07/2009 Date Data Arrived at EDR: 12/09/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 7

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Semi-Annually

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/02/2010 Date Data Arrived at EDR: 02/03/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 15

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/19/2009 Date Data Arrived at EDR: 02/19/2009 Date Made Active in Reports: 03/16/2009

Number of Days to Update: 25

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/12/2009 Date Data Arrived at EDR: 11/12/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 34

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/24/2009 Date Data Arrived at EDR: 05/20/2009 Date Made Active in Reports: 06/17/2009

Number of Days to Update: 28

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 12/01/2009 Date Data Arrived at EDR: 12/01/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 15

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

State and tribal registered storage tank lists

UST: Underground Storage Tank Facility List

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 02/22/2010 Date Data Arrived at EDR: 02/24/2010 Date Made Active in Reports: 03/17/2010

Number of Days to Update: 21

Source: Department of Environmental Quality

Telephone: 517-335-4035 Last EDR Contact: 04/01/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Annually

AST: Aboveground Tanks

Registered Aboveground Storage Tanks.

Date of Government Version: 11/30/2009 Date Data Arrived at EDR: 12/08/2009 Date Made Active in Reports: 12/30/2009

Number of Days to Update: 22

Source: Department of Environmental Quality

Telephone: 517-373-8168 Last EDR Contact: 02/23/2010

Next Scheduled EDR Contact: 06/07/2010

Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 12/01/2009 Date Data Arrived at EDR: 12/01/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 15

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/01/2008 Date Data Arrived at EDR: 12/30/2008 Date Made Active in Reports: 03/16/2009

Number of Days to Update: 76

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/19/2009 Date Data Arrived at EDR: 02/19/2009 Date Made Active in Reports: 03/16/2009

Number of Days to Update: 25

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/12/2009 Date Data Arrived at EDR: 11/20/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 26

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 12/07/2009 Date Data Arrived at EDR: 12/09/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 7

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Semi-Annually

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/02/2010
Date Data Arrived at EDR: 02/03/2010
Date Made Active in Reports: 02/18/2010

Number of Days to Update: 15

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 02/17/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 02/08/2010 Date Data Arrived at EDR: 02/09/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 9

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2009 Date Data Arrived at EDR: 11/05/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 41

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010

Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/01/2009 Date Data Arrived at EDR: 10/29/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 48

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 01/18/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

AUL: Engineering and Institutional Controls

A listing of sites with institutional and/or engineering controls in place.

Date of Government Version: 01/04/2010 Date Data Arrived at EDR: 01/05/2010 Date Made Active in Reports: 01/27/2010

Number of Days to Update: 22

Source: Department of Environmental Quality

Telephone: 517-373-4828 Last EDR Contact: 03/08/2010

Next Scheduled EDR Contact: 06/21/2010 Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 04/02/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 04/05/2010

Next Scheduled EDR Contact: 07/19/2010 Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009 Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields and USTfield Site Database

All state funded Part 201 and 213 sites, as well as LUST sites that have been redeveloped by private entities using the BEA process. Be aware that this is not a list of all of the potential brownfield sites in Michigan.

Date of Government Version: 02/12/2010 Date Data Arrived at EDR: 02/12/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 14

Source: Department of Environmental Quality

Telephone: 517-373-4805 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

BROWNFIELDS 2: Brownfields Building and Land Site Locations

A listing of brownfield building and land site locations. The listing is a collaborative effort of Michigan Economic Development Corporation, Michigan Economic Developers Association, Detrot Edison, Detroit Area Commercial Board of Realtors

Date of Government Version: 04/09/2007 Date Data Arrived at EDR: 04/10/2007 Date Made Active in Reports: 05/01/2007

Number of Days to Update: 21

Source: Economic Development Corporation

Telephone: 888-522-0103 Last EDR Contact: 03/08/2010

Next Scheduled EDR Contact: 06/21/2010

Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 10/01/2009 Date Data Arrived at EDR: 11/04/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 03/23/2010

Next Scheduled EDR Contact: 07/12/2010 Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004 Number of Days to Update: 39 Source: Environmental Protection Agency Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-972-3336 Last EDR Contact: 03/22/2010

Next Scheduled EDR Contact: 06/21/2010 Data Release Frequency: Varies

HIST LF: Inactive Solid Waste Facilities

The database contains historical information and is no longer updated.

Date of Government Version: 03/01/1997 Date Data Arrived at EDR: 02/28/2003 Date Made Active in Reports: 03/06/2003

Number of Days to Update: 6

Source: Department of Environmental Quality

Telephone: 517-335-4034 Last EDR Contact: 02/28/2003 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 02/08/2010

Next Scheduled EDR Contact: 05/24/2010 Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 08/19/2009 Date Data Arrived at EDR: 12/29/2009 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 43

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 12/14/2009

Next Scheduled EDR Contact: 03/22/2010 Data Release Frequency: Quarterly

DEL SHWS: Delisted List of Contaminated Sites

Sites that have been delisted or deleted from the List of Contaminated Sites. The available documentation for the site does not support it's listing or the site no longer meets criteria specified in rules.

Date of Government Version: 02/04/2010 Date Data Arrived at EDR: 02/04/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 22

Source: Department of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

CDL: Clandestine Drug Lab Listing

A listing of clandestine drug lab locations.

Date of Government Version: 10/20/2008 Date Data Arrived at EDR: 11/18/2008 Date Made Active in Reports: 11/21/2008

Number of Days to Update: 3

Source: Department of Community Health

Telephone: 517-373-3740 Last EDR Contact: 02/02/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007 Date Data Arrived at EDR: 11/19/2008 Date Made Active in Reports: 03/30/2009

Number of Days to Update: 131

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009 Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 11/03/2009 Date Data Arrived at EDR: 11/05/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 41

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

properties.

Date of Government Version: 12/09/2005 Date Data Arrived at EDR: 12/11/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 31

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 03/17/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Varies

LIENS: Lien List

An Environmental Lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including (but not limited to) liens imposed pursuant to CERCLA 42 USC * 9607(1) and similar state or local laws. In other words: a lien placed upon a property's title due to an environmental condition

Date of Government Version: 01/05/2010 Date Data Arrived at EDR: 01/29/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 28

Source: Department of Environmental Quality

Telephone: 517-373-9837 Last EDR Contact: 01/27/2010

Next Scheduled EDR Contact: 05/10/2010 Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 01/06/2010 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 35

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 04/07/2010

Next Scheduled EDR Contact: 07/19/2010 Data Release Frequency: Annually

PEAS: Pollution Emergency Alerting System

Environmental pollution emergencies reported to the Department of Environmental Quality such as tanker accidents, pipeline breaks, and release of reportable quantities of hazardous substances.

Date of Government Version: 12/08/2009 Date Data Arrived at EDR: 03/12/2010 Date Made Active in Reports: 03/23/2010

Number of Days to Update: 11

Source: Department of Environmental Quality

Telephone: 517-373-8427 Last EDR Contact: 03/15/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Quarterly

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 01/13/2010 Date Data Arrived at EDR: 01/15/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 34

Source: Environmental Protection Agency

Telephone: 312-886-6186 Last EDR Contact: 02/19/2010

Next Scheduled EDR Contact: 04/19/2010

Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 10/13/2009 Date Data Arrived at EDR: 11/10/2009 Date Made Active in Reports: 12/16/2009

Number of Days to Update: 36

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 02/09/2010

Next Scheduled EDR Contact: 05/24/2010 Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS Telephone: 703-692-8801 Last EDR Contact: 01/19/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2008 Date Data Arrived at EDR: 09/30/2009 Date Made Active in Reports: 12/01/2009

Number of Days to Update: 62

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 03/18/2010

Next Scheduled EDR Contact: 06/28/2010

Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 08/03/2009 Date Data Arrived at EDR: 10/27/2009 Date Made Active in Reports: 11/09/2009

Number of Days to Update: 13

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 04/05/2010

Next Scheduled EDR Contact: 07/19/2010 Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/01/2009 Date Data Arrived at EDR: 12/15/2009 Date Made Active in Reports: 01/19/2010

Number of Days to Update: 35

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 04/02/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 01/05/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 05/08/2009

Number of Days to Update: 1

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 01/21/2010

Next Scheduled EDR Contact: 06/14/2010

Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/17/2009 Date Data Arrived at EDR: 12/08/2009 Date Made Active in Reports: 01/19/2010

Number of Days to Update: 42

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 03/10/2010

Next Scheduled EDR Contact: 06/21/2010 Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2008 Date Data Arrived at EDR: 01/13/2010 Date Made Active in Reports: 02/18/2010

Number of Days to Update: 36

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 03/02/2010

Next Scheduled EDR Contact: 06/14/2010 Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002 Date Data Arrived at EDR: 04/14/2006 Date Made Active in Reports: 05/30/2006

Number of Days to Update: 46

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 03/30/2010

Next Scheduled EDR Contact: 07/12/2010 Data Release Frequency: Every 4 Years

FTTS: FIFRA/TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 06/14/2010 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 06/14/2010 Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2008 Date Data Arrived at EDR: 01/06/2010 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/10/2009 Date Data Arrived at EDR: 11/18/2009 Date Made Active in Reports: 01/19/2010

Number of Days to Update: 62

Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 03/29/2010

Next Scheduled EDR Contact: 07/12/2010 Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/01/2009 Date Data Arrived at EDR: 10/21/2009 Date Made Active in Reports: 12/01/2009

Number of Days to Update: 41

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 02/16/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 12/24/2009 Date Data Arrived at EDR: 12/31/2009 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 41

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 03/15/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/12/2010 Date Data Arrived at EDR: 01/13/2010 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 28

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 01/13/2010

Next Scheduled EDR Contact: 04/26/2010 Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/19/2009 Date Data Arrived at EDR: 10/22/2009 Date Made Active in Reports: 12/01/2009

Number of Days to Update: 40

Source: EPA

Telephone: (312) 353-2000 Last EDR Contact: 03/15/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2007 Date Data Arrived at EDR: 02/19/2009 Date Made Active in Reports: 05/22/2009

Number of Days to Update: 92

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 02/25/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Biennially

UIC: Underground Injection Wells Database

A listing of underground injection well locations. The UIC Program is responsible for regulating the construction, operation, permitting, and closure of injection wells that place fluids underground for storage or disposal.

Date of Government Version: 02/02/2010 Date Data Arrived at EDR: 03/03/2010 Date Made Active in Reports: 03/23/2010

Number of Days to Update: 20

Source: Department of Environmental Quality

Telephone: 517-241-1515 Last EDR Contact: 02/01/2010

Next Scheduled EDR Contact: 05/17/2010

Data Release Frequency: Varies

DRYCLEANERS: Drycleaning Establishments
A listing of drycleaning facilities in Michigan.

Date of Government Version: 01/26/2010 Date Data Arrived at EDR: 02/05/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 21

Source: Department of Environmental Quality

Telephone: 517-335-4586 Last EDR Contact: 01/25/2010

Next Scheduled EDR Contact: 05/10/2010 Data Release Frequency: Varies

NPDES: List of Active NPDES Permits

General information regarding NPDES (National Pollutant Discharge Elimination System) permits and NPDES Storm

Water permits.

Date of Government Version: 01/12/2010 Date Data Arrived at EDR: 01/13/2010 Date Made Active in Reports: 01/27/2010

Number of Days to Update: 14

Source: Department of Environmental Quality

Telephone: 517-241-1300 Last EDR Contact: 01/13/2010

Next Scheduled EDR Contact: 04/26/2010

Data Release Frequency: Varies

AIRS: Permit and Emissions Inventory Data Permit and emissions inventory data.

> Date of Government Version: 12/31/2007 Date Data Arrived at EDR: 10/09/2009 Date Made Active in Reports: 11/17/2009

Number of Days to Update: 39

Source: Department of Environmental Quality

Telephone: 517-373-7074 Last EDR Contact: 04/02/2010

Next Scheduled EDR Contact: 07/12/2010 Data Release Frequency: Varies

BEA: BASELINE ENVIRONMENTAL ASSESSMENT DATABASE

A Baseline Environmental Assessment (BEA) allows people to purchase or begin operating at a facility without being held liable for existing contamination. BEAs are used to gather enough information about the property being transferred so that existing contamination can be distinguished from any new releases that might occur after the new owner or operator takes over the property.

Date of Government Version: 03/01/2010 Date Data Arrived at EDR: 03/02/2010 Date Made Active in Reports: 03/23/2010

Number of Days to Update: 21

Source: DEPT. OF ENVIRONMENTAL QUALITY

Telephone: 517-373-9541 Last EDR Contact: 02/23/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Semi-Annually

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 01/19/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 11/16/2009 Date Data Arrived at EDR: 11/16/2009 Date Made Active in Reports: 01/19/2010

Number of Days to Update: 64

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 02/08/2010

Next Scheduled EDR Contact: 05/10/2010

Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 01/19/2010

Next Scheduled EDR Contact: 05/03/2010

Data Release Frequency: N/A

FINANCIAL ASSURANCE: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 01/28/2010 Date Data Arrived at EDR: 02/03/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 23

Source: Department of Environmental Quality

Telephone: 517-335-6610 Last EDR Contact: 01/11/2010

Next Scheduled EDR Contact: 04/19/2010 Data Release Frequency: Varies

FINANCIAL ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 02/03/2010 Date Data Arrived at EDR: 02/04/2010 Date Made Active in Reports: 02/26/2010

Number of Days to Update: 22

Source: Department of Environmental Quality

Telephone: 517-335-4034 Last EDR Contact: 04/05/2010

Next Scheduled EDR Contact: 07/19/2010 Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 11/09/2009 Date Data Arrived at EDR: 12/18/2009 Date Made Active in Reports: 02/10/2010

Number of Days to Update: 54

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 03/16/2010

Next Scheduled EDR Contact: 06/28/2010 Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 01/01/2008 Date Data Arrived at EDR: 02/18/2009 Date Made Active in Reports: 05/29/2009

Number of Days to Update: 100

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 02/24/2010

Next Scheduled EDR Contact: 05/17/2010 Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 01/27/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Sites

Coal fired power plants in Southeast Michigan that have coal ash handling on site.

Date of Government Version: 01/25/2010 Date Data Arrived at EDR: 01/25/2010 Date Made Active in Reports: 01/27/2010

Number of Days to Update: 2

Source: Department of Environmental Quality

Telephone: 586-753-3754 Last EDR Contact: 01/11/2010

Next Scheduled EDR Contact: 04/26/2010

Data Release Frequency: Varies

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: EDR. Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2007 Date Data Arrived at EDR: 08/26/2009 Date Made Active in Reports: 09/11/2009

Number of Days to Update: 16

Source: Department of Environmental Protection

Telephone: 860-424-3375 Last EDR Contact: 03/02/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 01/20/2010 Date Made Active in Reports: 02/05/2010

Number of Days to Update: 16

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 01/20/2010

Next Scheduled EDR Contact: 05/03/2010 Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/04/2010 Date Data Arrived at EDR: 02/11/2010 Date Made Active in Reports: 03/17/2010

Number of Days to Update: 34

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 02/11/2010

Next Scheduled EDR Contact: 05/24/2010 Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2008 Date Data Arrived at EDR: 12/01/2009 Date Made Active in Reports: 12/14/2009

Number of Days to Update: 13

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 02/23/2010

Next Scheduled EDR Contact: 06/07/2010 Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 11/03/2009 Date Data Arrived at EDR: 02/12/2010 Date Made Active in Reports: 02/22/2010

Number of Days to Update: 10

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 03/01/2010

Next Scheduled EDR Contact: 06/14/2010 Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2008 Date Data Arrived at EDR: 07/17/2009 Date Made Active in Reports: 08/10/2009

Number of Days to Update: 24

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 03/22/2010

Next Scheduled EDR Contact: 07/05/2010 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are

comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Centers, Group & Family Homes

Source: Bureau of REgulatory Services

Telephone: 517-373-8300

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2009 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Source: Department of Natural Resources

Telephone: 517-241-2254

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®-PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

WCJC 2270 PLATT ROAD ANN ARBOR, MI 48104

TARGET PROPERTY COORDINATES

Latitude (North): 42.25430 - 42° 15' 15.5" Longitude (West): 83.7029 - 83° 42' 10.5"

Universal Tranverse Mercator: Zone 17 UTM X (Meters): 277031.5 UTM Y (Meters): 4681335.5

Elevation: 824 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map: 42083-C6 ANN ARBOR EAST, MI

Most Recent Revision: 1983

South Map: 42083-B6 YPSILANTI WEST, MI

Most Recent Revision: 1983

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION


Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General ESE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County
WASHTENAW, MI

FEMA Flood
Electronic Data
Not Available

Flood Plain Panel at Target Property: Not Reported

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property

NWI Quad at Target Property

Data Coverage

ANN ARBOR EAST YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles Status: Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

	LOCATION	GENERAL DIRECTION
MAP ID	FROM TP	GROUNDWATER FLOW
3	1/4 - 1/2 Mile NE	SE
6	1/4 - 1/2 Mile NW	Varies
7	1/2 - 1 Mile ENE	N
8	1/2 - 1 Mile NW	N

For additional site information, refer to Physical Setting Source Map Findings.

^{*©1996} Site—specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION

Era: Paleozoic Category: Stratified Sequence

System: Mississippian

Series: Osagean and Kinderhookian Series
Code: M1 (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: ST. CLAIR

Soil Surface Texture: clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: HIGH

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

Soil Layer Information							
	Воц	ındary		Classi	fication		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	9 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.30 Min: 5.60
2	9 inches	25 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 0.20 Min: 0.06	Max: 7.30 Min: 5.60
3	25 inches	70 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 0.20 Min: 0.06	Max: 8.40 Min: 7.40

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silty clay loam

loam loamy sand muck

Surficial Soil Types: silty clay loam

loam

loamy sand muck

Shallow Soil Types: sandy loam

loamy sand

Deeper Soil Types: silty clay

silty clay loam stratified clay loam

muck fine sand

LOCATION

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 1 mile

State Database 1.000

FEDERAL USGS WELL INFORMATION

MAP ID WELL ID LOCATION FROM TP

No Wells Found

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID WELL ID FROM TP


No PWS System Found

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	FROM TP
1	MI20317269	non responsive
4	MI20323136	non responsive
9	MI20317267	non
10	MI20315648	non
11	MI20315647	non
A12	MI20315641	non
A13	MI20322544	non
B14	MI20320195	non
15	MI20315646	non
B16	MI20317271	non
17	MI20317314	non

PHYSICAL SETTING SOURCE MAP - 2738992.1s



SITE NAME: WCJC

ADDRESS: 2270 Platt Road

Ann Arbor MI 48104 LAT/LONG: 42.2543 / 83.7029 CLIENT: TTL Associates CONTACT: Danielle Green INQUIRY#: 2738992.1s

DATE: April 07, 2010 11:37 am

Map ID Direction Distance

Elevation Database EDR ID Number 1 WNW **MI WELLS** MI20317269 1/4 - 1/2 Mile Higher Wellid: 81000006695 Import id: 81737603001 Pittsfield County: Washtenaw Township: Town range: 03S 06E Section: 3 GREATER MICHIGAN CONTRACTING Owner name: Well addr: **COUNTY FARM PARK** Well depth: 148 Well type: Irrigation 0 Wssn: Well num: Driller id: 26 Not Reported 1981-09-26 00:00:00.000 Const date: Case type: Unknown Case dia: 4 Case depth: 114 Screen frm: 144 Screen to: 148 Swl: 73.5 Test depth: 25 Test hours: 4 Test rate: 15 Test methd: Unknown Grouted: Pmp cpcity: 42.2551234476 Latitude: Longitude: -83.7078944174 Methd coll: Interpolation-Map Elevation: Elev methd: Topographoc Map Interpolation Depth flag: Not Reported Elev flag: Not Reported Not Reported Swl flag: Elev dem: 869 Elev dif: Elev miv: 872 Aq code: Not Reported Aq flag: Lithology Problem (Drift under RodRa)t ag: 0 0 Pct aq d: Pct aq r: Pct maq: 0 0 Pct maq d: Pct mag r: 0 Pct cm: 0 Pct cm d: 0 Pct cm r: 0 Pct pcm: 0 Pct pcm d: 0 0 Pct pcm r: 0 Pct na: 0 0 Pct na r: Pct na d: Not Reported -9 Pct flag: Rock top: D r type: Not Reported Spc cpcity: 0 A thicknes: 13 A pct aq: 0 100 A pct maq: 0 A pct pcm: 0 0 A pct cm: A pct na: 0 A thickns2: 75 A pct aq2: A pct maq2: 23 A pct pcm2: 28 49 0 A pct cm2: A pct na2: F F A hit swl: A hit top: A hit rock: F A sc lith1: Not Reported A sc Imod1: Not Reported A sc Imaq1: Not Reported A sc lpct1: A sc lith2: Not Reported Not Reported A sc Imod2: Not Reported A sc Imaq2: A sc lpct2: 0 Pct aq 1: 0 Pct mag 1: 0 Pct cm 1: 70 Pct pcm 1: 30 Pct na 1:

Pct maq 2:	0
Pct pcm 2:	100
Pct aq 3:	0
Pct cm 3:	0
Pct na 3:	0
Pct maq 4:	0
Pct pcm 4:	0
Pct aq 5:	0
Pct cm 5:	100
Pct na 5:	0
Pct maq 6:	0
Pct pcm 6:	0
Pct aq 7:	0
Pct cm 7:	0
Pct na 7:	0
Pct maq 8:	0
Pct pcm 8:	0
Pct aq 9:	0
Pct cm 9:	0
Pct na 9:	0
Pct maq 10:	0
Pct pcm 10:	0
Pct aq 11:	0
Pct cm 11:	0
Pct na 11:	0
Pct maq 12:	0
Pct pcm 12:	0
Pct aq 13:	0
Pct cm 13:	0
Pct na 13:	0
Loc match:	Υ

3 NE 1/4 - 1/2 Mile Lower

Site ID: 810459 Groundwater Flow: SE

Shallowest Water Table Depth: Not Reported Deepest Water Table Depth: Not Reported

Average Water Table Depth: Date: 08/1995

NNE 1/4 - 1/2 Mile Higher

> Not Reported Wellid: 81000015315 Import id: Township: Ann Arbor County: Washtenaw 02S 06E

Section:

Town range:

Well depth: 136

Well type: Household

Wssn:

Well num: Not Reported Driller id: 2014 Const date: 2004-09-14 00:00:00.000 Case type: **PVC Plastic**

Case dia: 5

TC2738992.1s Page A-9

AQUIFLOW

MI WELLS

35

63222

MI20323136

Case depth: 126 Screen frm: 126 Screen to: 136 Swl: 47 Test depth: 136 Test hours: 2 Test rate: 25 Test methd: Air Grouted: Pmp cpcity: 42.25938318 Latitude: -83.70009341 Longitude: Methd coll: Address Matching-House Number Elevation: Elev methd: DEM30M Depth flag: Not Reported Elev flag: Elevation < DEMmin or Elevation > DEMmax Swl flag: Not Reported 823 823 Elev dem: Elev dif: Drift Well Elev miv: 823 Aq code: Not Reported 53 Aq flag: Pct aq: 0 Pct aq d: 53 Pct aq r: Pct mag: 0 Pct mag d: 0 Pct mag r: 0 Pct cm: 47 Pct cm d: 47 Pct cm r: 0 0 Pct pcm: 0 Pct pcm d: 0 0 Pct pcm r: Pct na: 0 Pct na d: 0 Pct na r: Pct flag: Not Reported Rock top: -1 0 D r type: Not Reported Spc cpcity: A thicknes: 14 A pct aq: 100 A pct maq: 0 A pct pcm: 0 0 0 A pct cm: A pct na: A thickns2: 89 A pct ag2: 28 A pct maq2: 0 A pct pcm2: 0 72 0 A pct cm2: A pct na2: A hit swl: F F A hit top: A hit rock: A sc lith1: Sand A sc Imod1: Not Reported A sc Imaq1: AQ Not Reported A sc lpct1: 100 A sc lith2: Not Reported Not Reported A sc Imod2: A sc Imaq2: A sc lpct2: 0 Pct aq 1: 100 Pct mag 1: 0 Pct cm 1: 0 Pct pcm 1: 0 Pct na 1: 0 0 Pct aq 2: 100 Pct maq 2: Pct cm 2: 0 0 Pct pcm 2: 0 90 Pct na 2: Pct aq 3: Pct maq 3: 0 Pct cm 3: 10 Pct pcm 3: 0 Pct na 3: 0 Pct aq 4: 0 Pct maq 4: 0 Pct cm 4: 100 Pct pcm 4: 0 0 Pct na 4: 0 Pct aq 5: Pct maq 5: 0 Pct cm 5: 100 0 0 Pct pcm 5: Pct na 5: 0 12 Pct aq 6: Pct maq 6: 0 Pct cm 6: 88 Pct pcm 6: Pct na 6: 0 Pct aq 7: 0 Pct maq 7: 0 Pct cm 7: 0 Pct pcm 7: 0 Pct na 7: 0 Pct aq 8: 0 Pct maq 8: 0 Pct cm 8: 0 Pct pcm 8: 0 Pct na 8: 0 Pct aq 9: 0 0 Pct maq 9: 0 Pct cm 9: 0 0 Pct na 9: Pct pcm 9:

Pct aq 10: 0 Pct cm 10: 0 Pct na 10: 0 Pct maq 11: 0 Pct pcm 11: 0 Pct aq 12: 0 Pct cm 12: 0 Pct na 12: 0 Pct maq 13: 0 Pct pcm 13: 0 Υ Within sec: Aq code 1: D Hit swl: F Athk2: 89 Horiz Conduct: 14.04502 .00014 Vert Conduct: T2: 1250.0064

0 Pct maq 10: Pct pcm 10: 0 Pct aq 11: 0 0 Pct cm 11: Pct na 11: 0 0 Pct maq 12: Pct pcm 12: 0 Pct aq 13: 0 Pct cm 13: 0 Pct na 13: 0 Loc match: Υ

NW 1/4 - 1/2 Mile Higher

D50plek:

Site ID: 810286
Groundwater Flow: Varies
Shallowest Water Table Depth: Not Reported
Deepest Water Table Depth: Not Reported

191.28809

Average Water Table Depth: 30

Date: 03/28/1994

/ ENE 1/2 - 1 Mile Lower Site ID: 810365
Groundwater Flow: N
Shallowest Water Table Depth: 1.13

Deepest Water Table Depth: 12.83
Average Water Table Depth: Not Reported
Date: 09/20/1993

NW 1/2 - 1 Mile Higher Site ID: Not Reported Groundwater Flow: N

Shallowest Water Table Depth: 2 Deepest Water Table Depth: 10

Average Water Table Depth: Not Reported Date: 07/10/1997

9 East 1/2 - 1 Mile Lower

 Wellid:
 8100006693
 Import id:
 81737602001

 County:
 Washtenaw
 Township:
 Pittsfield

 Town range:
 03S 06E
 Section:
 2

Driller id:

Case type:

non non

non responsi

Well type: Household Wssn: 130

Well num: Not Reported
Const date: 1967-03-02 00:00:00.000

Case dia:

TC2738992.1s Page A-11

AQUIFLOW

AQUIFLOW

AQUIFLOW

MI WELLS

248

Unknown

39405

39419

45881

MI20317267

Case depth: 130 Screen frm: 122 Screen to: 130 Swl: 40 Test depth: 40 Test hours: 8 Test rate: 12 Test methd: Unknown Grouted: Pmp cpcity: 42.2558106192 Latitude: -83.6885998283 Longitude: Methd coll: Interpolation-Map Elevation: Elev methd: Topographoc Map Interpolation Depth flag: Not Reported Elev flag: Not Reported Swl flag: Not Reported 820 Elev dem: Elev dif: 5 Drift Well Elev miv: 825 Aq code: Not Reported Aq flag: Pct aq: 35 0 Pct aq d: 35 Pct aq r: Pct mag: 0 Pct mag d: 0 Pct mag r: 0 Pct cm: 42 Pct cm d: 42 Pct cm r: 0 Pct pcm: 23 Pct pcm d: 23 0 0 Pct pcm r: Pct na: 0 Pct na d: 0 Pct na r: Pct flag: Not Reported Rock top: -1 0 D r type: Not Reported Spc cpcity: A thicknes: 25 A pct aq: 100 A pct maq: 0 A pct pcm: 0 0 0 A pct cm: A pct na: A thickns2: 90 A pct ag2: 28 A pct maq2: 0 A pct pcm2: 11 61 0 A pct cm2: A pct na2: A hit swl: F A hit top: F A hit rock: F A sc lith1: Sand A sc Imod1: Medium A sc Imaq1: AQ Not Reported A sc lpct1: 100 A sc lith2: Not Reported Not Reported A sc Imod2: A sc Imaq2: A sc lpct2: 0 Pct aq 1: 100 Pct mag 1: 0 Pct cm 1: 0 Pct pcm 1: 0 Pct na 1: 0 0 0 Pct aq 2: Pct maq 2: 0 Pct cm 2: Pct pcm 2: 100 0 Pct na 2: Pct aq 3: 0 Pct maq 3: 0 Pct cm 3: 50 Pct pcm 3: 50 Pct na 3: 0 0 Pct aq 4: 0 Pct maq 4: Pct cm 4: 100 Pct pcm 4: 0 0 Pct na 4: 0 Pct aq 5: Pct maq 5: 0 Pct cm 5: 100 0 0 Pct pcm 5: Pct na 5: 0 80 Pct aq 6: Pct maq 6: 0 Pct cm 6: 20 Pct pcm 6: Pct na 6: 0 Pct aq 7: 0 Pct maq 7: 0 Pct cm 7: 0 Pct pcm 7: 0 Pct na 7: 0 Pct aq 8: 0 Pct maq 8: 0 Pct cm 8: 0 Pct pcm 8: 0 Pct na 8: 0 Pct aq 9: 0 0 Pct maq 9: 0 Pct cm 9: 0 0 Pct na 9: Pct pcm 9:

Pct aq 10: 0 Pct maq 10: 0 Pct cm 10: 0 Pct pcm 10: 0 0 Pct na 10: 0 Pct aq 11: 0 0 Pct maq 11: Pct cm 11: Pct pcm 11: 0 Pct na 11: 0 Pct aq 12: 0 0 Pct maq 12: Pct pcm 12: Pct cm 12: 0 0 Pct na 12: 0 Pct aq 13: 0 Pct maq 13: 0 Pct cm 13: 0 0 Pct pcm 13: Pct na 13: 0 Υ Within sec: Loc match: Υ Aq code 1: D F Hit swl: Athk2: 90 Horiz Conduct: 27.7785

10

NE 1/2 - 1 Mile Lower

T2:

D50plek:

Vert Conduct:

 Wellid:
 8100005054
 Import id:
 81727635008

 County:
 Washtenaw
 Township:
 Ann Arbor

 Town range:
 02S 06E
 Section:
 35

non mellon non well depth.

Il donth

.00138

2500.065

373.25338

Well type: Household Wssn: 0

 Well num:
 Not Reported
 Driller id:
 524

 Const date:
 1977-08-11 00:00:00.000
 Case type:
 Unknown

 Case dia:
 4

 Case depth:
 70

 Screen frm:
 70

 Screen to:
 74

 Swl:
 19

 Test depth:
 20

 Test hours:
 2

Test rate: 12 Test methd: Unknown Grouted: 1 Pmp opcity: 0

Latitude: 42.262383721 Longitude: -83.6904548539 Methd coll: Interpolation-Map

Elevation: 815

Elev methd: Topographoc Map Interpolation Depth flag: Not Reported

Elev flag: ELEV_DIF > 20 feet -- Abs(Elevation feet DEM_Elevation) > 20 feet

Swl flag: Not Reported

Elev dem: 28 787 Elev dif: Drift Well Elev miv: 815 Aq code: Aq flag: Not Reported Pct aq: 14 Pct aq d: 14 Pct aq r: 0 Pct maq: 0 Pct maq d: 0 0 86 Pct maq r: Pct cm:

MI WELLS

MI20315648

Pct cm d:	86	Pct cm r:	0
Pct pcm:	0	Pct pcm d:	0
Pct pcm r:	0	Pct na:	0
Pct na d:	0	Pct na r:	0
Pct flag:	Not Reported	Rock top:	-1
_	•	•	
D r type:	Not Reported	Spc cpcity:	0
A thicknes:	6	A pct aq:	100
A pct maq:	0	A pct pcm:	0
A pct cm:	0	A pct na:	0
A thickns2:	55	A pct aq2:	16
A pct mag2:	0	A pct pcm2:	0
A pct cm2:	84	A pct na2:	0
A hit swl:	F	A hit top:	F
A hit rock:	F	A sc lith1:	Gravel
	•		
A sc Imod1:	Not Reported	A sc Imaq1:	AQ
A sc lpct1:	100	A sc lith2:	Not Reported
A sc Imod2:	Not Reported	A sc lmaq2:	Not Reported
A sc lpct2:	0	Pct aq 1:	10
Pct maq 1:	0	Pct cm 1:	90
Pct pcm 1:	0	Pct na 1:	0
Pct aq 2:	10	Pct maq 2:	0
Pct cm 2:	90	Pct pcm 2:	0
Pct na 2:	0	Pct aq 3:	0
Pct maq 3:	0	Pct cm 3:	100
Pct pcm 3:	0	Pct na 3:	0
Pct aq 4:	0	Pct maq 4:	0
Pct cm 4:	0	Pct pcm 4:	0
Pct na 4:	0	Pct aq 5:	0
Pct maq 5:	0	Pct cm 5:	0
Pct pcm 5:	0	Pct na 5:	0
_ '	0		0
Pct aq 6:		Pct maq 6:	
Pct cm 6:	0	Pct pcm 6:	0
Pct na 6:	0	Pct aq 7:	0
Pct maq 7:	0	Pct cm 7:	0
Pct pcm 7:	0	Pct na 7:	0
Pct aq 8:	0	Pct maq 8:	0
Pct cm 8:	0	Pct pcm 8:	0
Pct na 8:	0	Pct aq 9:	0
Pct maq 9:	0	Pct cm 9:	0
Pct pcm 9:	0	Pct na 9:	0
•	0		0
Pct aq 10:		Pct maq 10:	
Pct cm 10:	0	Pct pcm 10:	0
Pct na 10:	0	Pct aq 11:	0
Pct maq 11:	0	Pct cm 11:	0
Pct pcm 11:	0	Pct na 11:	0
Pct aq 12:	0	Pct maq 12:	0
Pct cm 12:	0	Pct pcm 12:	0
Pct na 12:	0	Pct aq 13:	0
Pct maq 13:	0	Pct cm 13:	0
Pct pcm 13:	0	Pct na 13:	0
	Y		Y
Within sec:		Loc match:	ĭ
Aq code 1:	D		
Hit swl:	F		
Athk2:	55		
Horiz Conduct:	16.36372		
Vert Conduct:	.00012		
T2:	900.0046		
D50plek:	86.61128		
= 00k.0			

Map ID Direction Distance

Elevation Database EDR ID Number

NE 1/2 - 1 Mile Lower

Wellid:8100005053Import id:81727635007County:WashtenawTownship:Ann Arbor

Town range: 02S 06E Section:

non non responsive non responsive well depth.

Well depth. 77
Well type: Household Wssn: 0

 Well num:
 Not Reported
 Driller id:
 524

 Const date:
 1976-08-26 00:00:00.000
 Case type:
 Unknown

 Case dia:
 4

 Case depth:
 77

 Screen frm:
 73

 Screen to:
 77

 Swl:
 29

 Test depth:
 41

 Test hours:
 2

Test rate: 12 Test methd: Unknown Grouted: 1 Pmp cpcity: 0

Latitude: 42.2635043783 Longitude: -83.6901912059

Methd coll: Interpolation-Map Elevation: 820

Elev methd: Topographoc Map Interpolation Depth flag: Not Reported

Elev flag: ELEV_DIF > 20 feet -- Abs(Elevation feet DEM_Elevation) > 20 feet

Swl flag: Not Reported

Elev dem: 781 Elev dif: 39 Elev miv: 820 Aq code: Drift Well Aq flag: Not Reported Pct aq: 14 0 Pct aq d: 14 Pct aq r: Pct maq d: 0 Pct maq: 0 Pct mag r: 0 Pct cm: 86

Pct cm d: 86 Pct cm r: 0 Pct pcm: 0 Pct pcm d: 0 0 0 Pct pcm r: Pct na: 0 Pct na d: 0 Pct na r: Not Reported Pct flag: Rock top: -1 D r type: Not Reported Spc cpcity: 0 A thicknes: 5 A pct aq: 100 A pct maq: 0 0 A pct pcm: 0 0 A pct cm: A pct na: A thickns2: 48 A pct aq2: 10 A pct maq2: 0 A pct pcm2: 0 90 0 A pct cm2: A pct na2: F F A hit swl: A hit top:

A hit rock: F A sc lith1: Sand A sc Imaq1: AQ

A sc Ipct1: 100 A sc lith2: Not Reported A sc Imaq2: Not Reported Not Reported

 A sc Ipct2:
 0
 Pct aq 1:
 0

 Pct maq 1:
 0
 Pct cm 1:
 100

 Pct pcm 1:
 0
 Pct na 1:
 0

MI WELLS

35

MI20315647

Pct aq 2:	30
Pct cm 2:	70
Pct na 2:	0
Pct maq 3:	0
Pct pcm 3:	0
Pct aq 4:	0
Pct cm 4:	0
Pct na 4:	0
Pct maq 5:	0
Pct pcm 5:	0
Pct aq 6:	0
Pct cm 6:	0
Pct na 6:	0
Pct maq 7:	0
Pct pcm 7:	0
Pct aq 8:	0
Pct cm 8:	0
Pct na 8:	0
Pct maq 9:	0
Pct pcm 9:	0
Pct aq 10:	0
Pct cm 10:	0
Pct na 10:	0
Pct maq 11:	0
Pct pcm 11:	0
Pct aq 12:	0
Pct cm 12:	0
Pct na 12:	0
Pct maq 13:	0
Pct pcm 13:	0
Within sec:	Y
Aq code 1:	D
Hit swl:	F
Athk2:	48
Horiz Conduct:	5.20842
Vert Conduct:	.00011
T2:	250.0043
D50plek:	22.545

Pct maq 2:	0
Pct pcm 2:	0
Pct aq 3:	0
Pct cm 3:	100
Pct na 3:	0
Pct maq 4:	0
Pct pcm 4:	0
Pct aq 5:	0
Pct cm 5:	0
Pct na 5:	0
Pct maq 6:	0
Pct pcm 6:	0
Pct aq 7:	0
Pct cm 7:	0
Pct na 7:	0
Pct maq 8:	0
Pct pcm 8:	0
Pct aq 9:	0
Pct cm 9:	0
Pct na 9:	0
Pct maq 10:	0
Pct pcm 10:	0
Pct aq 11:	0
Pct cm 11:	0
Pct na 11:	0
Pct maq 12:	0
Pct pcm 12:	0
Pct aq 13:	0
Pct cm 13:	0
Pct na 13:	0
Loc match:	Υ

A12 NNE 1/2 - 1 Mile Lower

Wellid: 8100005047 Import id: County: Washtenaw Township: Town range: 02S 06E Section:

non Well depth.

Well depth. 67
Well type: Household

Wssn: 0

Well num: Not Reported Driller ic Const date: 1968-02-08 00:00:00.000 Case ty

Case dia:

Driller id: 524 Case type: Unknown

MI WELLS

81727635001

Ann Arbor

35

MI20315641

Case depth: 63 Screen frm: 63 Screen to: 67 Swl: 21 Test depth: 32 Test hours: 3 Test rate: 12 Test methd: Unknown Grouted: 0 Pmp cpcity: 42.2665053717 Latitude: -83.6960593123 Longitude: Methd coll: Interpolation-Map Elevation: Elev methd: Topographoc Map Interpolation Depth flag: Not Reported Elev flag: Not Reported Swl flag: Not Reported Elev dem: 813 Elev dif: Drift Well Elev miv: 820 Aq code: Not Reported 78 Aq flag: Pct aq: 0 Pct aq d: 78 Pct aq r: Pct mag: 0 Pct mag d: 0 Pct mag r: 0 Pct cm: 0 Pct cm d: 0 Pct cm r: 0 Pct pcm: 22 Pct pcm d: 22 0 0 Pct pcm r: Pct na: 0 Pct na d: 0 Pct na r: Pct flag: Not Reported Rock top: -1 0 D r type: Not Reported Spc cpcity: A thicknes: 46 100 A pct aq: A pct maq: 0 A pct pcm: 0 0 0 A pct cm: A pct na: A thickns2: 46 A pct ag2: 100 0 A pct maq2: A pct pcm2: 0 0 0 A pct cm2: A pct na2: A hit swl: Т A hit top: F A hit rock: F A sc lith1: Sand A sc Imod1: Coarse A sc Imaq1: AQ Not Reported A sc lpct1: 100 A sc lith2: Not Reported Not Reported A sc Imod2: A sc Imaq2: A sc lpct2: 0 Pct aq 1: 25 Pct mag 1: 0 Pct cm 1: 0 Pct pcm 1: 75 Pct na 1: 0 0 Pct aq 2: 100 Pct maq 2: Pct cm 2: 0 0 Pct pcm 2: 0 Pct na 2: Pct aq 3: 100 Pct maq 3: 0 Pct cm 3: 0 Pct pcm 3: 0 Pct na 3: 0 Pct aq 4: 0 Pct maq 4: 0 Pct cm 4: 0 Pct pcm 4: 0 0 Pct na 4: 0 Pct aq 5: Pct maq 5: 0 Pct cm 5: 0 0 0 Pct pcm 5: Pct na 5: 0 0 Pct aq 6: Pct maq 6: 0 Pct cm 6: 0 Pct pcm 6: Pct na 6: 0 Pct aq 7: 0 Pct maq 7: 0 Pct cm 7: 0 Pct pcm 7: 0 Pct na 7: 0 Pct aq 8: 0 Pct maq 8: 0 Pct cm 8: 0 Pct pcm 8: 0 Pct na 8: 0 Pct aq 9: 0 0 Pct maq 9: 0 Pct cm 9: 0 0 Pct na 9: Pct pcm 9:

Pct aq 10:	0	Pct maq 10:	0
Pct cm 10:	0	Pct pcm 10:	0
Pct na 10:	0	Pct aq 11:	0
Pct maq 11:	0	Pct cm 11:	0
Pct pcm 11:	0	Pct na 11:	0
Pct aq 12:	0	Pct maq 12:	0
Pct cm 12:	0	Pct pcm 12:	0
Pct na 12:	0	Pct aq 13:	0
Pct maq 13:	0	Pct cm 13:	0
Pct pcm 13:	0	Pct na 13:	0
Within sec:	Υ	Loc match:	Υ
Aq code 1:	D		
Hit swl:	T		
Athk2	46		

A13
NNE MI WELLS MI20322544
1/2 - 1 Mile
Lower

Wellid:81000013789Import id:Not ReportedCounty:WashtenawTownship:Ann ArborTown range:02S 06ESection:35

non non responsive non non well depth. 63

200

200

9200

658.43073

Well type: Household

Wssn: 0

Horiz Conduct: Vert Conduct:

T2:

D50plek:

Well num: Not Reported Driller id: 2014

Const date: 2003-08-20 00:00:00.000 Case type: PVC Plastic

 Case dia:
 5

 Case depth:
 53

 Screen frm:
 53

 Screen to:
 63

 Swl:
 30

 Test depth:
 36

 Test hours:
 2

Test rate: 10 Test methd: Unknown Grouted: 1 Pmp cpcity: 12

Latitude: 42.26678543 Longitude: -83.6958325

Methd coll: Address Matching-House Number

Elevation: 807

Elev methd: Topographoc Map Interpolation Depth flag: Not Reported

Elev flag: Not Reported

Swl flag: Not Reported

Elev dem: Elev dif: 817 10 Drift Well Elev miv: 807 Aq code: Aq flag: Not Reported Pct aq: 67 Pct aq d: 67 Pct aq r: 0 0 Pct maq: 0 Pct maq d: Pct cm: Pct maq r: 0 33

Not Reported Not Reported

Pct cm d:	33	Pct cm r:
Pct pcm:	0	Pct pcm d:
Pct pcm r:	0	Pct na:
Pct na d:	0	Pct na r:
Pct flag:	Not Reported	Rock top:
D r type:	Not Reported	Spc cpcity:
A thicknes:	15	A pct ag:
A pct maq:	0	A pct pcm:
	0	
A pct cm:		A pct na:
A thickns2:	33	A pct aq2:
A pct maq2:	0	A pct pcm2:
A pct cm2:	42	A pct na2:
A hit swl:	F	A hit top:
A hit rock:	F	A sc lith1:
A sc Imod1:	Not Reported	A sc lmaq1:
A sc lpct1:	100	A sc lith2:
A sc Imod2:	Not Reported	A sc Imaq2:
A sc lpct2:	0	Pct aq 1:
Pct maq 1:	0	Pct cm 1:
Pct pcm 1:	0	Pct na 1:
Pct aq 2:	70	Pct mag 2:
Pct cm 2:	30	
_		Pct pcm 2:
Pct na 2:	0	Pct aq 3:
Pct maq 3:	0	Pct cm 3:
Pct pcm 3:	0	Pct na 3:
Pct aq 4:	0	Pct maq 4:
Pct cm 4:	0	Pct pcm 4:
Pct na 4:	0	Pct aq 5:
Pct maq 5:	0	Pct cm 5:
Pct pcm 5:	0	Pct na 5:
Pct aq 6:	0	Pct maq 6:
Pct cm 6:	0	Pct pcm 6:
Pct na 6:	0	Pct aq 7:
Pct maq 7:	0	Pct cm 7:
Pct pcm 7:	0	Pct na 7:
Pct aq 8:	0	Pct maq 8:
Pct cm 8:	0	
	0	Pct pcm 8:
Pct na 8:		Pct aq 9:
Pct maq 9:	0	Pct cm 9:
Pct pcm 9:	0	Pct na 9:
Pct aq 10:	0	Pct maq 10:
Pct cm 10:	0	Pct pcm 10:
Pct na 10:	0	Pct aq 11:
Pct maq 11:	0	Pct cm 11:
Pct pcm 11:	0	Pct na 11:
Pct aq 12:	0	Pct maq 12:
Pct cm 12:	0	Pct pcm 12:
Pct na 12:	0	Pct aq 13:
Pct mag 13:	0	Pct cm 13:
Pct pcm 13:	0	Pct na 13:
Within sec:	Y	Loc match:
Aq code 1:	D	
Hit swl:	F	
Athk2:		
	33	
Horiz Conduct:	172.72732	
Vert Conduct:	.00024	
T2:	5700.0014	
D50plek:	299.4875	

Map ID Direction Distance

B14

Elevation Database EDR ID Number

1/2 - 1 Mile Higher MI WELLS MI20320195

Wellid:81000010089Import id:Not ReportedCounty:WashtenawTownship:PittsfieldTown range:03S 06ESection:3

non non Well depth.

Well type: Household Wssn: 0

 Well num:
 Not Reported
 Driller id:
 1607

 Const date:
 2000-08-08 00:00:00.000
 Case type:
 PVC Plastic

 Case dia:
 5

 Case depth:
 234

 Screen frm:
 0

 Screen to:
 0

 Swl:
 35

 Test depth:
 400

 Test hours:
 2

Test rate: 7 Test methd: Test Pump

Grouted: 1 Pmp cpcity: 20

Latitude: 42.24587728 Longitude: -83.71723009

Methd coll: Address Matching-House Number

Elevation: 0

Elev methd: DEM30M Depth flag: Not Reported

Elevation < DEMmin or Elevation > DEMmax

Swl flag: Not Reported

Elev dem: 836 836 Elev dif: Elev miv: 836 Aq code: Rock Well Aq flag: Not Reported Pct aq: 36 77 Pct aq d: 4 Pct aq r: Pct maq d: 10 Pct maq: 0 Pct mag r: 23 Pct cm: 54

Pct cm r: Pct cm d: 96 0 Pct pcm: 0 Pct pcm d: 0 0 0 Pct pcm r: Pct na: Pct na r: 0 Pct na d: 0 Not Reported 225 Pct flag: Rock top: D r type: Not Reported Spc cpcity: 0 A thicknes: A pct aq: 0 A pct maq: 0 0 A pct pcm: 0 0 A pct cm: A pct na: 0 0 A thickns2: A pct aq2: 0 A pct maq2: 0 A pct pcm2: 0 0 A pct cm2: A pct na2: F F

 A hit swl:
 F
 A hit top:
 F

 A hit rock:
 F
 A sc lith1:
 Not Reported

 A sc Imod1:
 Not Reported
 A sc Imaq1:
 Not Reported

 A sc Ipct1:
 0
 A sc lith2:
 Not Reported

 A sc Imod2:
 Not Reported
 A sc Imaq2:
 Not Reported

 A sc Imod2:
 Not Reported
 A sc Imaq2:
 Not

 A sc Ipct2:
 0
 Pct aq 1:
 0

 Pct maq 1:
 0
 Pct cm 1:
 100

 Pct pcm 1:
 0
 Pct na 1:
 0

Pct aq 2: 0 Pct cm 2: 100 Pct na 2: 0 Pct maq 3: 0 Pct pcm 3: 0 Pct aq 4: 0 Pct cm 4: 100 Pct na 4: 0 Pct maq 5: 0 Pct pcm 5: 0 0 Pct aq 6: Pct cm 6: 100 Pct na 6: 0 Pct maq 7: 0 Pct pcm 7: 0 Pct aq 8: 0 Pct cm 8: 100 Pct na 8: 0 Pct maq 9: 0 Pct pcm 9: 0 Pct aq 10: 0 Pct cm 10: 0 Pct na 10: 0 Pct maq 11: 0 Pct pcm 11: 0 Pct aq 12: 0 Pct cm 12: 0 Pct na 12: 0 Pct maq 13: 0 0 Pct pcm 13: Within sec: Υ Aq code 1: R F Hit swl: 0 Athk2: Horiz Conduct: 4.87814 Vert Conduct: .00011 1000.0195 T2: D50plek: 356.68351

Pct maq 2: 0 Pct pcm 2: 0 Pct aq 3: 50 Pct cm 3: 50 Pct na 3: 0 0 Pct maq 4: Pct pcm 4: 0 Pct aq 5: 0 Pct cm 5: 100 Pct na 5: 0 Pct maq 6: 0 Pct pcm 6: 0 Pct aq 7: 0 Pct cm 7: 100 Pct na 7: 0 Pct maq 8: 0 Pct pcm 8: 0 Pct aq 9: 0 Pct cm 9: 0 Pct na 9: 0 Pct mag 10: 0 Pct pcm 10: 0 0 Pct aq 11: Pct cm 11: 0 0 Pct na 11: Pct mag 12: 0 0 Pct pcm 12: Pct aq 13: 0 Pct cm 13: 0 Pct na 13: 0 Loc match: Υ

15
NNE
MI WELLS
MI20315646
1/2 - 1 Mile

Import id:

Township:

Section:

 Wellid:
 8100005052

 County:
 Washtenaw

 Town range:
 02S 06E

non responsive
non non responsive
non responsive

Well depth. 96
Well type: Public
Wssn: 0

Higher

Well num: Not Reported Driller id: 524
Const date: 1969-08-12 00:00:00.000 Case type: Unknown

Case dia:

TC2738992.1s Page A-21

81727635006

Ann Arbor

35

Case depth: 91 Screen frm: 90.5 Screen to: 94.5 Swl: 65 Test depth: 79 Test hours: 2 Test rate: 12 Test methd: Unknown Grouted: Pmp cpcity: 42.2664750477 Latitude: -83.694022183 Longitude: Methd coll: Interpolation-Map Elevation: Elev methd: Topographoc Map Interpolation Depth flag: Not Reported Elev flag: Not Reported Swl flag: Not Reported 840 15 Elev dem: Elev dif: Drift Well Elev miv: 855 Aq code: Not Reported 38 Aq flag: Pct aq: 0 Pct aq d: 38 Pct aq r: Pct mag: 0 Pct mag d: 0 Pct mag r: 0 Pct cm: 63 Pct cm d: 63 Pct cm r: 0 0 Pct pcm: 0 Pct pcm d: 0 0 Pct pcm r: Pct na: 0 Pct na d: 0 Pct na r: Pct flag: Not Reported Rock top: -1 0 D r type: Not Reported Spc cpcity: A thicknes: 100 6 A pct aq: A pct maq: 0 A pct pcm: 0 0 0 A pct cm: A pct na: A thickns2: 30 A pct ag2: 19 A pct maq2: 0 A pct pcm2: 0 81 0 A pct cm2: A pct na2: A hit swl: F A hit top: F A hit rock: F A sc lith1: Sand A sc Imod1: Coarse A sc Imaq1: AQ Not Reported A sc lpct1: 100 A sc lith2: Not Reported Not Reported A sc Imod2: A sc Imaq2: A sc lpct2: 0 Pct aq 1: 100 Pct mag 1: 0 Pct cm 1: 0 Pct pcm 1: 0 Pct na 1: 0 0 50 Pct aq 2: Pct maq 2: Pct cm 2: 50 0 Pct pcm 2: 0 Pct na 2: 0 Pct aq 3: Pct maq 3: 0 Pct cm 3: 100 Pct pcm 3: 0 Pct na 3: 0 Pct aq 4: 0 Pct maq 4: 0 Pct cm 4: 100 Pct pcm 4: 0 0 Pct na 4: 0 Pct aq 5: Pct maq 5: 0 Pct cm 5: 0 0 0 Pct pcm 5: Pct na 5: 0 0 Pct aq 6: Pct maq 6: 0 Pct cm 6: 0 Pct pcm 6: Pct na 6: 0 Pct aq 7: 0 Pct maq 7: 0 Pct cm 7: 0 Pct pcm 7: 0 Pct na 7: 0 Pct aq 8: 0 Pct maq 8: 0 Pct cm 8: 0 Pct pcm 8: 0 Pct na 8: 0 Pct aq 9: 0 0 Pct maq 9: 0 Pct cm 9: 0 0 Pct na 9: Pct pcm 9:

Pct aq 10: 0 Pct maq 10: 0 Pct cm 10: 0 Pct pcm 10: 0 0 Pct na 10: 0 Pct aq 11: 0 0 Pct maq 11: Pct cm 11: Pct pcm 11: Pct na 11: 0 0 Pct aq 12: 0 0 Pct maq 12: Pct pcm 12: Pct cm 12: 0 0 Pct na 12: 0 Pct aq 13: 0 Pct maq 13: 0 Pct cm 13: 0 0 Pct pcm 13: Pct na 13: 0 Υ Within sec: Loc match: Υ Aq code 1: D F Hit swl: Athk2: 30 Horiz Conduct: 36.66675

1/2 - 1 Mile Higher

Wellid: 81000006697 Import id: 81737603302 County: Washtenaw Township: Pittsfield Town range: 03S 06E Section: 3

Well depth

.00012 1100.00245

57.12617

Well type:

Vert Conduct:

T2: D50plek:

Type I public 6840 Wssn:

Well num: WALDEN WOODS SUB WELL #2Driller id: Const date: Not Reported Case type: Unknown

Case dia: Case depth: 0 Screen frm: 0 Screen to: 0 999.99 Swl: Test depth: 0

0

Test rate: 75 Unknown Test methd: Grouted: Pmp cpcity:

Latitude: 42.246037 Longitude: -83.718556

Methd coll: GPS Code Meas. Std. Positioning Svc. SA Off

Elevation:

Test hours:

Well Depth = 0 Elev methd: Topographoc Map Interpolation Depth flag:

Elev flag: Not Reported SWL > Well Depth Swl flag:

Elev dem: 840 Elev dif:

Elev miv: 841 Aq code: Unknown Lithology

Aq flag: Not Reported Pct aq: 0 Pct aq d: 0 Pct aq r: 0 Pct maq: 0 Pct maq d: 0 0 0 Pct maq r: Pct cm:

MI WELLS

MI20317271

	_		_
Pct cm d:	0	Pct cm r:	0
Pct pcm:	0	Pct pcm d:	0
Pct pcm r:	0	Pct na:	0
Pct na d:	0	Pct na r:	0
Pct flag:	Not Reported	Rock top:	-3
D r type:	Not Reported	Spc cpcity:	0
A thicknes:	0	A pct aq:	0
A pct maq:	0	A pct pcm:	0
A pct cm:	0	A pct na:	0
A thickns2:	0	A pct aq2:	0
A pct maq2:	0	A pct pcm2:	0
A pct cm2:	0	A pct na2:	0
A hit swl:	F	A hit top:	F
A hit rock:	F	A sc lith1:	Not Reported
A sc Imod1:	Not Reported	A sc Imag1:	
	•	•	Not Reported
A sc lpct1:	0 Not Deported	A sc lith2:	Not Reported
A sc Imod2:	Not Reported	A sc Imaq2:	Not Reported
A sc lpct2:	0	Pct aq 1:	0
Pct maq 1:	0	Pct cm 1:	0
Pct pcm 1:	0	Pct na 1:	0
Pct aq 2:	0	Pct maq 2:	0
Pct cm 2:	0	Pct pcm 2:	0
Pct na 2:	0	Pct aq 3:	0
Pct maq 3:	0	Pct cm 3:	0
Pct pcm 3:	0	Pct na 3:	0
Pct aq 4:	0	Pct maq 4:	0
Pct cm 4:	0	Pct pcm 4:	0
Pct na 4:	0	Pct aq 5:	0
Pct maq 5:	0	Pct cm 5:	0
Pct pcm 5:	0	Pct na 5:	0
Pct aq 6:	0	Pct maq 6:	0
Pct cm 6:	0	Pct pcm 6:	0
Pct na 6:	0	Pct aq 7:	0
Pct maq 7:	0	Pct cm 7:	0
Pct pcm 7:	0	Pct na 7:	0
Pct aq 8:	0	Pct maq 8:	0
Pct cm 8:	0	Pct pcm 8:	0
Pct na 8:	0	Pct aq 9:	0
Pct maq 9:	0	Pct cm 9:	0
Pct pcm 9:	0	Pct na 9:	0
Pct aq 10:	0	Pct mag 10:	0
Pct cm 10:	0	Pct pcm 10:	0
Pct na 10:	0	Pct aq 11:	0
Pct mag 11:	0	Pct cm 11:	0
Pct pcm 11:	0	Pct na 11:	0
Pct aq 12:	0	Pct mag 12:	0
Pct cm 12:	0	Pct pcm 12:	0
Pct na 12:	0	-	0
		Pct aq 13:	
Pct maq 13:	0	Pct cm 13: Pct na 13:	0
Pct pcm 13:	0 Y		Y
Within sec:		Loc match:	ĭ
Aq code 1:	Not Reported		
Hit swl:	Not Reported		
Athk2:	0		
Horiz Conduct:	0		
Vert Conduct:	0		
T2:	0		
D50plek:	0		

Map ID Direction Distance

Elevation Database EDR ID Number 17 **MI WELLS** MI20317314

1/2 - 1 Mile Higher

> Wellid: 81000006740 Import id: 81737610302 Pittsfield County: Washtenaw Township: 03S 06E Town range: 10 Section:

Well depth 0 Well type: Type I public 6840 Wssn:

Well num: WALDEN WOODS SUB WELL #1Driller id:

Const date: Not Reported Case type: Unknown

Case dia: 6 Case depth: 0 Screen frm: 0 Screen to: 0 Swl: 999.99 Test depth: 0 0 Test hours:

Test rate: 40 Test methd: Unknown

Grouted: Pmp cpcity:

42.246058 Latitude: Longitude: -83.718642

Methd coll: GPS Code Meas. Std. Positioning Svc. SA Off

Elevation:

Elev methd: Topographoc Map Interpolation Depth flag: Well Depth = 0

Elev flag: Not Reported SWL > Well Depth Swl flag:

Elev dem: 840 Elev dif:

Elev miv: 841 Aq code: Unknown Lithology Aq flag: Not Reported Pct aq: 0

Pct aq d: 0 Pct aq r: Pct maq d: Pct maq: 0 Pct mag r: 0 Pct cm: Pct cm d: 0 Pct cm r: Pct pcm: 0 Pct pcm d: Pct pcm r: 0 Pct na: 0 Pct na d: Pct na r: Not Reported Pct flag: Rock top: D r type: Not Reported Spc cpcity: A thicknes: A pct aq: A pct maq: 0 A pct pcm: 0 A pct cm: A pct na: 0 A thickns2: A pct aq2: A pct maq2: 0 A pct pcm2: 0 A pct cm2: A pct na2: F

A hit swl: A hit top: A hit rock: A sc lith1: Not Reported A sc Imod1: Not Reported A sc Imaq1: Not Reported

A sc lpct1: A sc lith2: Not Reported Not Reported A sc Imod2: A sc Imaq2:

Not Reported A sc lpct2: 0 Pct aq 1: 0 Pct mag 1: 0 Pct cm 1: 0 Pct pcm 1: 0 Pct na 1: 0

0

0

0

0

0 0

0

-3

0

0

0

0

0

0

0

F

Pct aq 2:	0
Pct cm 2:	0
Pct na 2:	0
Pct maq 3:	0
Pct pcm 3:	0
Pct aq 4:	0
Pct cm 4:	0
Pct na 4:	0
Pct maq 5:	0
Pct pcm 5:	0
Pct aq 6:	0
Pct cm 6:	0
Pct na 6:	0
Pct maq 7:	0
Pct pcm 7:	0
Pct aq 8:	0
Pct cm 8:	0
Pct na 8:	0
Pct maq 9:	0
Pct pcm 9:	0
Pct aq 10:	0
Pct cm 10:	0
Pct na 10:	0
Pct maq 11:	0
Pct pcm 11:	0
Pct aq 12:	0
Pct cm 12:	0
Pct na 12:	0
Pct maq 13:	0
Pct pcm 13:	0
Within sec:	Υ

Pct maq 2: Pct pcm 2: Pct aq 3: Pct cm 3: Pct na 3: Pct maq 4: Pct pcm 4: Pct aq 5: Pct cm 5: Pct na 5: Pct maq 6: Pct pcm 6: Pct aq 7: Pct cm 7: Pct na 7: Pct maq 8: Pct pcm 8: Pct aq 9: Pct cm 9: Pct na 9: Pct maq 10: Pct pcm 10: Pct aq 11: Pct cm 11: Pct na 11: Pct maq 12: Pct pcm 12: Pct aq 13: Pct cm 13: Pct na 13: Loc match:

0

0

0

0

0

0

0

0

0

0

0

0

0

0

0

0

0

0

0 0

0

0

0

0

0

0 Y

Aq code 1: Not Reported Hit swl: Not Reported Athk2: 0

AthK2: 0
Horiz Conduct: 0
Vert Conduct: 0
T2: 0
D50plek: 0

AREA RADON INFORMATION

State Database: MI Radon

Radon Test Results

Test Type	Zip	Floor	Stop Date	Can 1 Res pCi/L	Can 1 Error	Can 2 Res pCi/L	Can 2 Error
	_						
Random	48104			NR			
Random	48104			NR			
Random	48104	1	5/22/87	0.7	103.1	%	
Random	48104	0	12/6/87	1.5	12.2%		
Random	48104	0	5/8/87	1.6	15.5%		
Random	48104	0	4/3/87	1.8	12.7%		
Random	48104	1	1/21/88	3.4	7.8%		
Random	48104	0	12/28/87	3.6	6.2%		
Random	48104	0	12/31/87	5.2	5.6%		
Random	48104	1	12/10/87	5.3	5.6%		
Random	48104	0	11/27/87	6.1	4.2%		
Random	48104	0	11/27/87	7.4	4.4%		
Random	48104	0	1/22/88	12.4	3.5%	11.	7 3.7%
Random	48104	0	2/8/88	12.7	3.0%		
Random	48104	0	12/26/87	27.3	2.1%		
Geographic	48104	0	3/24/88	0.8	21.9%		

State Database: MI Radon

Radon Test Results

Zip	Less than sign	Pci/L
_		
48104		2.10
48104	<	0.30
48104		11.60
48104		3.10
48104		1.90
48104		6.00
48104		22.80
48104		1.50
48104		1.40
48104		1.40
48104		1.60
48104		4.40
48104		4.30
48104		3.20
48104		3.00
48104		5.30
48104		6.10
48104		3.50
48104		

		1.10
48104		1.20
48104		5.80
48104		3.60
48104		4.20
48104		3.30
48104		3.60
48104		1.60
48104		1.10
48104		10.40
48104		9.00
48104		4.80
48104		2.80
48104		2.20
48104		2.30
48104		3.10
48104		1.40
48104		14.10
48104		10.50
48104		2.20
48104		9.60
48104		0.80
48104	<	0.30
48104	•	6.00
48104		8.10
48104		6.60
48104		3.30
48104		2.90
48104		3.60
48104		3.20
48104		2.30
48104		20.70
48104		18.40
48104		14.10
48104		7.50
48104		7.20
48104		3.20
48104		4.20
48104		9.40
48104		2.70
48104		4.60
48104		6.20
48104		4.00
48104		7.00
48104		8.10
48104		8.30
48104		6.70
48104		4.80
48104		20.60
48104		2.80
48104		12.20
48104		1.90
48104		16.90
48104	<	0.30
48104	•	2.50
48104		9.10
48104		- · -
2. - .		

		4.50
48104		1.40
48104		10.60
48104		40.30
48104		44.90
48104		4.10
48104		0.40
48104		0.50
48104		0.80
48104		0.80
48104	<	0.30
48104	<	0.30
48104		5.70
48104		4.40
48104	_	0.30
48104 48104	<	2.90
48104 48104		0.60
48104		5.10
48104		1.70
48104		3.00
48104		4.70
48104		0.90
48104		5.60
48104		2.20
48104		7.20
48104	<	0.30
48104		6.50
48104		12.80
48104	<	0.30
48104		8.40
48104		0.80
48104		1.50
48104		6.00
48104		6.40
48104		5.60
48104		1.30
48104		0.70
48104		3.00
48104		1.00
48104		1.40
48104		4.10
48104		7.10
48104		1.10
48104		5.20
48104		7.80
48104		1.20
48104		7.80
48104		3.90
48104		6.10
48104		4.10
48104		1.70
48104		0.70
48104		1.50
48104		0.50
48104		3.20
48104		1.50
48104		

	6.70
48104	8.90
48104	3.70
48104	4.90
48104	1.90
48104	1.40
48104	14.70
48104	4.60
48104	
	10.10
48104	2.00
48104	2.40
48104	3.60
48104	2.10
48104	5.00
48104	5.50
48104	3.40
48104	0.60
48104	6.20
48104	12.60
48104	5.40
48104	3.50
48104	2.00
48104	16.50
48104	1.50
48104	0.90
48104	2.10
48104	2.50
48104	1.70
48104	
	0.50
48104	4.50
48104	3.60
48104	1.90
48104	1.40
48104	2.20
48104	3.70
48104	12.60
48104	7.00
48104	2.20
48104	1.30
48104	5.40
48104	3.80
48104	2.80
48104	2.60
48104	2.30
48104	8.40
48104	0.60
48104	6.90
48104	5.80
48104	7.30
48104	6.10
48104	3.20
48104	1.20
48104	1.60
48104	0.80
48104	1.10
48104	7.80
48104	

		2.80
48104		4.10
48104		4.40
48104		1.90
48104		10.70
48104		27.70
48104		2.70
48104		1.20
48104		1.30
48104		0.90
48104		31.30
48104		10.60
48104		2.00
48104		4.30
48104		2.20
48104		2.00
48104		5.00
48104		14.40
48104		5.90
48104		5.80
48104		9.90
48104		4.80
48104		4.10
48104		8.30
48104		5.80
48104		12.50
48104 48104		1.70
48104 48104		10.80
48104 48104		9.10
48104 48104		13.10
48104		10.90
48104		5.80
48104		10.30
48104		2.10
48104		2.30
48104		1.90
48104		4.50
48104	<	0.30
48104		6.30
48104		3.70
48104		4.70
48104		0.70
48104		1.90
48104		3.30
48104		11.50
48104		2.70
48104		2.90
48104		5.60
48104		4.00
48104		4.30
48104		1.60
48104	<	0.30
48104		10.60
48104		2.50
48104		2.00
48104	<	0.30
48104		J

AREA RADON INFORMATION

1.80 48104 < 0.30 48104 6.90

Federal EPA Radon Zone for WASHTENAW County: 1

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 48104

Number of sites tested: 10

Area Average Activity % <4 pCi/L % 4-20 pCi/L % >20 pCi/L Living Area - 1st Floor 3.133 pCi/L 67% 33% 0% Not Reported Not Reported Living Area - 2nd Floor Not Reported Not Reported Basement 8.500 pCi/L 30% 60% 10%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2009 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Source: Department of Natural Resources

Telephone: 517-241-2254

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Data

Source: Department of Environmental Quality

Telephone: 517-335-9218

OTHER STATE DATABASE INFORMATION

Michigan Oil and Gas Wells

Source: Michigan Department of Natural Resources

Locations of oil and gas wells are compiled from permit records on file at the Geological Survey Division (GSD), Michigan Department of Natural Resources.

RADON

State Database: MI Radon

Source: Department of Environmental Quality

Telephone: 517-335-9551 Radon Test Results

Michigan Radon Test Results

Source: Department of Environmental Quality

Telephone: 517-335-8037

These results are from test kits distributed by the local health departments and used by

Michigan residents. There is no way of knowing whether the devices were used properly, whether there are duplicates (or repeat verification) test (i.e., more than one sample per home), etc.

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency

(USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at

private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX G TTL TEAM RESUMES



Danielle J. Green



Environmental Scientist

Danielle has seven years of experience performing Phase I and Phase II Environmental Site Assessments of commercial, residential, industrial and institutional properties throughout the United States.

Education

B.S., Environmental Studies, Michigan State University, 2000 Post Baccalaureate Certificate of Paralegal Studies, University of Toledo, 2002

Specialized Skills & Training

OSHA 29 CFR 1910.120 HAZWOPER #MS03060040HR08 Danielle joined TTL in 2008 and has over 7 years of experience.

Project Experience

Regional & National Environmental Consulting Firms Project Manager/Environmental Scientist

Performed and managed ESAs on various industrial, commercial, institutional and residential properties. Assessments included limited and comprehensive surveys for asbestos, lead-based paint, lead-in-drinkingwater and radon gas emissions. Also completed subsurface investigations to determine the presence of contamination in soil and/or groundwater, and prepared written reports in formats prescribed by various fiduciary institutions, including the U.S. Department of Housing and Urban Development, Fannie Mae, and the Michigan State Housing Development Authority.

Various Clients - Throughout the United States **Environmental Scientist**

Performed comprehensive ESAs for sites located in numerous states in accordance with American Society for Testing and Materials (ASTM) and state regulatory standards. Project activities involved site reconnaissance, historical information research, regulatory review, and report preparation.

Various Clients - Throughout the United States **Environmental Scientist**

Developed and completed community wellhead protection programs, public outreach environmental education materials, wetlands assessments, baseline environmental assessments (BEA's), and community emergency response and contingency plans.





Steven J. Gach, P.E.

Senior Engineer

Steven joined TTL in 1996 and has over 19 years of experience.

Professional Registration

P.E., Michigan, 1994

Professional Certification

MI Certified Underground Storage Tank Professional

Education

B.S., Environmental Sciences Engineering University of Michigan, 1983 M.S., Environmental Engineering University of Michigan, 1986

Specialized Training & Skills 40-hour HAZWOPER

Organizations & Memberships

Michigan Association of Environmental Professionals National Society of Professional Engineers American Society of Civil Engineers Engineering Society of Detroit

Current Project Experience

Current - 2004

Site Investigation and Remediation

Monroe Bank & Trust, Temperance, Michigan

Project Manager for the investigation and remediation of gasoline and chlorinated compound impacts identified in soil and groundwater during construction activities. TTL investigated the nature and extent of the releases, on-site and offsite, including a total of 47 Geoprobe soil borings, and eight rotary drilled soil borings completed as monitoring wells. Two of the borings were advanced to the top of the underlying bedrock aquifer and converted to double-cased monitoring wells. TTL's hydrogeologic assessment included slug tests and soil permeability testing. Fraction of organic carbon and bulk density were tested for development of site-specific cleanup criteria and contaminant transport modeling. The results of the site investigation activities were used to prepare a Remedial Investigation Report and an Interim Response Plan (IRP). The IRP, approved by the MDEQ. included the excavation and disposal of the most significantly impacted soils, which were highly contaminated and appeared to be acting as a continuing source for groundwater contamination. Approximately 800 tons of soil were excavated from the gasoline USTs area and 300 tons of soil were excavated from the chlorinated compound impacted area. Soil impacted by chlorinated compounds

"I am solution, integrity, and quality oriented and deeply care about results from all perspectives."

-- Steven J. Gach, P.E.

Phone 734 455 8600, Ext. 1236 Fax 734 455 8608 email sgach@ttlassoc.com



Steven J. Gach, P.E.

Senior Engineer Page 2

was required to be disposed of as hazardous waste. Through on-site segregation techniques, approximately \$100,000 in soil disposal costs was saved. Two additional USTs were discovered in the gasoline USTs area during excavation, that were registered and removed. The results of the interim response actions and supplementary investigatory activities were used to prepare an Interim Response Report with recommendations for continued groundwater monitoring and additional groundwater fate and transport modeling, expected to lead to the completion of a monitored natural attenuation Remedial Action Plan (RAP) within approximately two years.

2007

Phase II ESA, Baseline Environmental Assessment, Due Care Plan City of Taylor/Downriver Area Brownfields Consortium, Taylor, MI A project that began as a Phase I ESA and developed into a Phase II ESA included a Sampling and Analysis Plan (SAP) that was reviewed and approved by the U.S. EPA prior to implementation. The site, a former truck service center and machining facility, had seven underground storage tanks (USTs) that were discovered, registered with the MDEQ, and emptied. Soil and groundwater contaminants were detected during the Phase II ESA at concentrations greater than Part 201 residential cleanup criteria; therefore, the site was identified as a "facility" under Part 201 and eligible for a Baseline Environmental Assessment (BEA). TTL prepared a BEA on behalf of the City of Taylor, providing liability protection for the new owner, and submitted it to the MDEQ. TTL also prepared a Section 7a Compliance Analysis (or Due Care Plan) to assist the owner to ensure that due care would be exercised with respect to the existing contamination. TTL also developed and provided the City of Taylor demolition specifications for the removal of asbestos-containing materials and the USTs.

2006

Integrated Contingency Plan (ICP)

Precision Castparts, Inc., Waterford, Michigan
Prepared an ICP, that included the elements of a Spill Control and
Countermeasure (SPCC) Plan and a Pollution Incident Prevention Plan (PIPP)
for the Waterford facility. Originally, TTL was requested to update the existing
SPCC Plan and to prepare a PIPP per request of the Michigan Department of
Environmental Quality (MDEQ). However, to streamline the client's use of
the planning, TTL recommended consolidating the plans into a single plan, the
ICP. The client seemed very pleased with the final plan. SPCC Plans require
certification by a professional engineer. The project included an assessment of
the needs of the facility, based on the facility characteristics including but not
limited to potential spill and storm drainage conditions, as well as client-specific
considerations and the vicinity infrastructure, and preparation of a plan to meet
the regulatory requirements.

Robin J. Clark

Senior Scientist



"I tailor my investigation and remediation programs to sitespecific conditions to meet the client needs and ensure technical performance within the specified schedule and budget."

- Rob Clark

Professional Certifications

OH Environmental Protection Agency Certified Professional - Voluntary Action Program MI Certified Underground Storage Tank Professional

NREP Registered Environmental **Property Assessor**

Education

B.S., Aquatic Environments Allegheny College, 1985

Specialized Training & Skills

OSHA 40-Hour HAZWOPER, 1986, Annual Refreshers Groundwater Modeling Underground Storage Tanks Risk-based Corrective Action Baseline Environmental

Assessments Hydrogeologist **Environmental Site Assessments**

- Phase I & II Due Diligence

> Phone (419) 324-2222, ext. 1235

> > Fax (734) 455-8608

Cell (810) 623-0830

Email rclark@ttlassoc.com Rob joined TTL in 1997 and has over 23 years of experience.

Project Experience

NEPA Environmental Assessment & Phase I Environmental Site Assessment

Proposed VA Fisher House and Polytrauma Housing, San Antonio, Texas

TTL Project Manager for the completion of a NEPA EA and Phase I ESA of the 9.6-acre proposed VA Fisher Housing and Polytrauma Housing project in San Antonio, Texas. TTL completed the Phase I ESA in accordance with ASTM 1527-05 and the US EPA All Appropriate Inquiry requirements and identified no recognized environmental conditions (RECs) in connection with the site. TTL completed the EA and Finding of No Significant Impact (FONSI) in accordance with NEPA, 38 CFR Part 26 and the VA Environmental Compliance Manual.

Phase I and Phase II ESAs and Environmental Document Review

Proposed VA Clinic, Jacksonville, Florida

TTL Project Manager for the completion of a Phase I ESA and Phase II ESA for a proposed VA Clinic located in Jacksonville, Florida. Phase I ESA research identified several historic business on site and in the site vicinity of potential environmental concern, including gasoline stations, automobile repair operations, dry cleaners, and a bulk oil storage facility. The Phase II ESA was designed to assess for possible site impacts associated with these historic operations. In addition, the site is part of the US EPA Jacksonville Ash Superfund site due to the historic placement of ash from a nearby incinerator on the property. TTL's task for this project includes the review of US EPA's reports, including the Remedial Investigation, Feasibility Study and Record of Decision, to assess the contamination specifically associated with the site and its impact on the proposed development.

NEPA Environmental Assessment

Proposed VA Outpatient Clinic, Bangor, Maine

TTL Manager for the completion of a NEPAEA of the 6.3-acre proposed VA Community-Based Outpatient Clinic project in Bangor, Maine. TTL completed the EA and Finding of No Significant Impact (FONSI) in accordance with NEPA, 38 CFR Part 26 and the VA Environmental Compliance Manual. The EA identified that the proposed action would results in potentially significant adverse impacts related to noise, traffic and State-listed threatened species at the site. Working with the VA, the State of Maine, and the City of Bangor, we developed site-specific mitigation measures to reduce these potential impacts to lessthan-significant levels.

Site Development Services

CVS Pharmacy, Eastern United States

Program Manager for multidisciplined team of environmental, geotechnical, civil engineering, remediation and construction professionals to assist CVS with acquisition, development and divestment of more than 500 sites in a 12-state area. Program managed Phase I and Phase II due diligence projects to ensure the special assessment needs of the client that functions as both buyer and seller of properties, were met. Participated in negotiations between buyers, seller, environmental and real estate attorneys, and regulatory agencies to promote cost-effective, fast-paced redevelopment of impacted properties, while achieving "no further action" letters from regulatory agencies.

Brownfield Site Assessments

Downriver Area Brownfield Consortium, Southeast Michigan

TTL Program Manager for a U.S. EPA funded \$200,000 Brownfield Site Assessment Grant was awarded to The Downriver Area Brownfield Consortium, a group of 12 Southeast Michigan communities. Worked with the communities to identify and assess Brownfield sites for redevelopment. Prepared and/or reviewed a grant-specific Quality Assurance Project Plan that was reviewed and approved by U.S. EPA, Phase I ESAs, site specific sampling and analysis plans approved by the U.S. EPA, Phase II ESAs, Baseline Environmental Assessments and Due Care Plans. Met with communities to identify potential Brownfield sites, participated in monthly DABC meetings to review the status of active and pending projects, and prepared quarterly progress reports for submittal to the U.S. EPA.